

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2400332
INV Date : 21-08-2024

Reference CD/FCI24070153/Rma3
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLZ 2203P
Insured Veh. SH 6991H
Claim No. D24005906MFCT
Policy No. D-24101861MFCT
Accident Date 04/07/2024
Inspection Date 11/07/2024

Description	Amount
Survey Inspection	250.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	250.00
GST (9%)	22.50
Grand Total	272.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

FWL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CD/FCI24070153/Rma3

Date: 22/08/2024

Code: FCI2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SH 6991H	Veh. Inspected	SLZ 2203P
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005906MFCT	Excess	\$0.00
Assign From	-	Assign Date	09/07/2024

2. Vehicle Details

Make & Model	VOLKSWAGEN GOLF TSI TL	C.C	999
Engine No.	CHZ644795	Year of Reg.	26/04/2018
Chassis No.	WVWZZZAUZJW155125	Colour	GREY
Odometer	42513 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55 R16	PIRELLI	6
L/H Front Tyre	205/55 R16	PIRELLI	6
R/H Rear Tyre	205/55 R16	PIRELLI	6
L/H Rear Tyre	205/55 R16	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/07/2024	Inspection Date
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLZ 2203P

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	COVER FOR BUMPER PRIMED (SN)	DEFORMED	\$1,570.79	\$1,570.79
1	SUPPORT PART BUMPER INNER BRACKET LH (SN)	NOT NECESSARY	\$91.90	\$0.00
1	GUIDE PIECE BUMPER SIDE BRACKET LH (SN)	NOT NECESSARY	\$56.74	\$0.00
1	GUIDE PIECE BUMPER SIDE BRACKET RH (SN)	NOT NECESSARY	\$56.74	\$0.00
1	GUIDE BUMPER CTR BRACKET (SN)	NOT NECESSARY	\$136.99	\$0.00
1	COVER PART FOR BUMPER SAT LHS BUMPER CTR GRILLE (CTR) (SN)	NOT NECESSARY	\$72.99	\$0.00
1	COOLING AIR GRILL SATIN B LHS BUMPER CTR GRILLE (UPPER) (SN)	NOT NECESSARY	\$114.62	\$0.00
1	COOLING AIR GRILL SATIN B LHS BUMPER CTR GRILLE (LOWER) (SN)	NOT NECESSARY	\$114.62	\$0.00
1	TWIN HALOGEN HEADLAMPS LH (SN)	SCRATCHED	\$996.21	\$996.21
1	FLAT CONTACT HOUSING H/LAMP WIRE HOUSING (SN)	NOT NECESSARY	\$24.67	\$0.00
			\$3,236.27	\$2,567.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR		\$2,520.00	\$840.00
	SPRAY PAINT		\$2,400.00	\$800.00
	B&P CHECK SHORT CIRCUIT HARNESS REPAIR		\$280.00	\$280.00
	B&P DIAGNOSIS AND PROGRAMMING		\$480.00	\$480.00
			\$5,680.00	\$2,400.00
GRAND TOTAL			\$8,916.27	\$4,967.00
RECOMMENDED COST OF REPAIRS				\$4,967.00
Report Ref No: CD/FCI24070153/Rma3				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P



PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P



PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933


TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 10)


PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P




PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P



PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P



PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 8 of 10)

PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P



PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

INSPECTION PHOTOS (Page 10 of 10)

PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P



PHOTOGRAPHS FOR VEHICLE NO. : SLZ 2203P

