

ASS. REC. BY:

REF:

F621

CS/FCI 240 60047/Knp3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8200k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 1.5 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLT 83R Yr Regn: 05, 23Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Tesla Model Y C.C. _____Colour: M.P. White A/C: Insured / Std / NI / NASp. Reading: 36893 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LRWYH CF 52PC 892733Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 255/35R21R: 275/35R21BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 5 mmL/Bal. 7 mm L/Bal. 5 mmD.O.A. 29/5/24 D.O.I. 12/6/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/7 @ 7071.29 Cash (Red. \$ 2341.37, 24%)

Date/Time, File Pass to?

☐ : Prell. ReportDays Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$ _____)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	529H

Vehicle Details

Vehicle No.:	SLJ83R
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jun 2024
Vehicle Make:	TESLA
Vehicle Model:	MODEL Y RWD
Primary Colour:	White
Manufacturing Year:	2023
Engine No.:	-
Chassis No.:	LRWYHCFS2PC892733
Maximum Power Output:	220.0 kW (295 bhp)
Open Market Value:	\$61,318.00
Original Registration Date:	09 May 2023
First Registration Date:	09 May 2023
Transfer Count:	0
Actual ARF Paid:	\$44,295.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 May 2033
PARF Rebate Amount:	\$33,221.00

Intended COE Rebate Details

COE Expiry Date:	08 May 2033
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$120,889.00
COE Rebate Amount:	\$107,792.00
Total Rebate Amount:	\$141,013.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 08 Jun 2024

OK

Date: 10-6-2024
Vehicle No: SLJ83R
Model: Tesla Model Y
Chassis: LRWYHCFS2PC892733
Reg.Year: 9.5.2023

Not Withheld
Primary B4paim
5 day
87071.29

Third Party Insurer: FCIL
Third Party Veh No: SHC1483Y
Date of Accident: 29/5/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR LH DOOR PANEL	1		<i>Re</i> \$1,869.16
2	REAR LH DOOR SEAL	1		<i>Re</i> \$107.47
3	REAR LH FENDER OUTER GARNISH	1		<i>Re/LH</i> \$65.42
4	REAR LH WHEEL RIM	1		<i>Re</i> \$1,130.84
5	REAR LH KNUCKLE ARM	1		<i>Re</i> \$672.89
6	REAR LH KNUCKLE HUB + BEARING	1		<i>Re</i> \$149.53
7	REAR LH UPPER AFTER LINK	1		<i>PL</i> \$18.69
8	REAR LH LOWER AFTER LINK	1		<i>PL</i> \$224.29
9	REAR LH UPPER FORE LINK	1		<i>PL</i> \$18.69
10	REAR LH TOE LINK	1		<i>PL</i> \$17.75
11	REAR LH LOWER FORE LINK	1		<i>PL</i> \$224.29
12	SIDE SKIRT RH	1		<i>PL</i> \$364.48
13	REAR RH WHEEL RIM	1		<i>Re</i> \$1,130.84
14	FRONT RH WHEEL RIM	1		<i>Re</i> \$1,130.84
15	REAR LH FENDER PANEL	1		REPAIR
16	FRONT BUMPER	1		REPAIR
SUB TOTAL				\$7,125.18
LESS 10%				-\$712.52
PARTS TOTAL				\$6,412.66

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR INNER TRIM BOARD CLIPS	1		<i>nn</i> \$50.00
2	REAR FENDER GARNISH CLIPS	1		<i>nn</i> \$50.00
3	SIDE SKIRT CLIPS	1		<i>nn</i> \$50.00
S/N TOTAL				\$150.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

\$800.00 *3001*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR LH DOOR, REAR LH FENDER, FRONT BUMPER, FRONT & REAR RH WHEEL RIM, ETC

\$1,300.00 *4401*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

\$150.00 *601*

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10-6-2024
Vehicle No: SLJ83R
Model: Tesla Model Y
Chassis: LRWYHCF52PC892733
Reg.Year: 9.5.2023

Third Party Insurer: FCIL
Third Party Veh No: SHC1483Y
Date of Accident: 29/5/2024
Estimator: Loong
Surveyor:

TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	\$120.00	8d
TO REMOVE AND REFIT REAR UNDERCARRIAGE PARTS TO ENABLE REPAIR	\$300.00	8d
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$100.00	3d
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$80.00	2d

LABOUR TOTAL	\$2,850.00
--------------	------------

TOTAL	\$9,412.66
-------	------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10-6-2024
Vehicle No: SLJ83R
Model: Tesla Model Y
Chassis: LRWYHCFS2PC892733
Reg.Year: 9.5.2023

Third Party Insurer: FCIL
Third Party Veh No: SHC1483Y
Date of Accident: 29/5/2024
Estimator: Loong
Surveyor:

SUPPLEMENTARY ESTIMATE

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	RE-COATING AND POLISHING FOR ACCIDENT PORTION	1		\$430.00
			S/N TOTAL	\$430.00

380/-

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554800
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011





UEN 202011263C

SPEEDWASH.SG PRIVATE LIMITED

YEO CHIAH YONG

87 Dawson Road #46-27
Singapore 141087

TESLA

SLJ83R

DATE

22 JULY 2024

DESCRIPTION	QTY	PRICE	TOTAL
Adam's Polished 10H Graphene Ceramic Coating Package (Apply Only On Both Left Door Panels (\$250)	1	\$250.00	\$250.00
3 Stage Polishing (\$150)	1	\$150	\$150 100%
Mobile Service (\$30)	1	\$30	\$30
		TOTAL	\$430.00
		DISCOUNT	-
		AMOUNT	\$430.00

PAYMENT INFORMATION

Paynow To :
speedwas.sg private limited
UEN 202011263C

5001 Beach Road #07-
01/15 Golden Mile
Complex Singapore
199588

+65 97222082
speedwashsingapore@gmail.com



UEN-202011263C

SPEEDWASH.SG PRIVATE LIMITED

YEO CHIAH YONG

87 Dawson Road #46-27
Singapore 141087

TESLA

SLJ83R

DATE

19 MAY 2023

DESCRIPTION	QTY	PRICE	TOTAL
Adam's Polished 10H Graphene Ceramic Coating Package (\$700)	1	\$700.00	\$700.00
3 Stage Polishing (\$360)	1	\$360	\$360
Mobile Service (\$30)	1	\$30	\$30
Pest Fumigation (\$50)	0	-	-
Steam Cleaning (\$60)	0	-	-
Leather Conditioning (\$30)	0	-	-
TOTAL			\$1,090.00
DISCOUNT			-
AMOUNT			\$1,090.00

PAYMENT INFORMATION

Paynow To :
speedwas.sg private limited
UEN 202011263C

5001 Beach Road #07-
01/15 Golden Mile
Complex Singapore
199588

+65 97222082
speedwashesingapore@gmail.com

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SLJ 83 R

Technician:

Mileage:

Time Printed 22.6.24 10:15 AM

TESLA MODEL Y

Front : Left

Actual	BEFORE	Specified Range
-0°18'		-1°35' -0°05'
5°17'		5°11' 7°11'
0°04'		-0°05' 0°10'
17°24'		
17°05'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°29'		-1°35' -0°05'
5°14'		5°10' 7°10'
0°03'		-0°05' 0°10'
11°47'		
11°19'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°10'		-0°30' 0°30'
0°04'		-0°59' 1°01'
5°36'		
0°07'		-0°10' 0°20'

Rear : Left

Actual	BEFORE	Specified Range
-1°10'		-1°15' 0°15'
0°06'		0°03' 0°18'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°57'		-1°15' 0°15'
0°05'		0°03' 0°18'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°13'		-1°20' 1°20'
0°11'		0°05' 0°35'
0°01'		-0°10' 0°10'

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SLJ 83 R

Technician:

Mileage:

Time Printed 21.6.24 11:38 AM

TESLA MODEL Y

Front : Left

Actual	BEFORE	Specified Range
0°00'		-1°35' -0°05'
5°17'		5°11' 7°11'
-0°33'		-0°05' 0°10'
12°30'		
12°29'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°32'		-1°35' -0°05'
5°06'		5°10' 7°10'
0°27'		-0°05' 0°10'
11°07'		
10°35'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°31'		-0°30' 0°30'
0°11'		-0°59' 1°01'
1°23'		
-0°06'		-0°10' 0°20'

Rear : Left

Actual	BEFORE	Specified Range
2°35'		-1°15' 0°15'
2°08'		0°03' 0°18'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°35'		-1°15' 0°15'
0°19'		0°03' 0°18'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
3°10'		-1°20' 1°20'
2°27'		0°05' 0°35'
0°54'		-0°10' 0°10'