

Date: 10-6-2024
Vehicle No: SLJ83R
Model: Tesla Model Y
Chassis: LRWYHCFS2PC892733
Reg.Year: 9.5.2023

Not Notified
Recovery B4 painting
5 days
87071.29

Third Party Insurer: FCIL
Third Party Veh No: SHC1483Y
Date of Accident: 29/5/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR LH DOOR PANEL	1		<i>By</i> \$1,869.16
2	REAR LH DOOR SEAL	1		<i>By</i> \$107.47
3	REAR LH FENDER OUTER GARNISH	1		<i>By</i> \$65.42
4	REAR LH WHEEL RIM	1		<i>By</i> \$1,130.84
5	REAR LH KNUCKLE ARM	1		<i>By</i> \$672.89
6	REAR LH KNUCKLE HUB + BEARING	1		<i>By</i> \$149.53
7	REAR LH UPPER AFTER LINK	1		<i>By</i> \$18.69
8	REAR LH LOWER AFTER LINK	1		<i>By</i> \$224.29
9	REAR LH UPPER FORE LINK	1		<i>By</i> \$18.69
10	REAR LH TOE LINK	1		<i>By</i> \$17.75
11	REAR LH LOWER FORE LINK	1		<i>By</i> \$224.29
12	SIDE SKIRT RH	1		<i>By</i> \$364.48
13	REAR RH WHEEL RIM	1		<i>By</i> \$1,130.84
14	FRONT RH WHEEL RIM	1		<i>By</i> \$1,130.84
15	REAR LH FENDER PANEL	1		REPAIR
16	FRONT BUMPER	1		REPAIR
SUB TOTAL				\$7,125.18
LESS 10%				-\$712.52
PARTS TOTAL				\$6,412.66

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR INNER TRIM BOARD CLIPS	1		<i>By</i> \$50.00
2	REAR FENDER GARNISH CLIPS	1		<i>By</i> \$50.00
3	SIDE SKIRT CLIPS	1		<i>By</i> \$50.00
S/N TOTAL				\$150.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

\$800.00 *300*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR LH DOOR, REAR LH FENDER, FRONT BUMPER, FRONT & REAR RH WHEEL RIM, ETC

\$1,300.00 *440*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

\$150.00 *60*

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011



Date: 10-6-2024
Vehicle No: SLJ83R
Model: Tesla Model Y
Chassis: LRWYHCFS2PC892733
Reg.Year: 9.5.2023

Third Party Insurer: FCIL
Third Party Veh No: SHC1483Y
Date of Accident: 29/5/2024
Estimator: Loong
Surveyor:

TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT

\$120.00 *8d*

TO REMOVE AND REFIT REAR UNDERCARRIAGE PARTS TO ENABLE REPAIR

\$300.00 *8d*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$100.00 *3d*

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$80.00 *2d*

LABOUR TOTAL \$2,850.00

TOTAL \$9,412.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 10-6-2024
Vehicle No: SLJ83R
Model: Tesla Model Y
Chassis: LRWYHCFS2PC892733
Reg. Year: 9.5.2023

Third Party Insurer: FCIL
Third Party Veh No: SHC1483Y
Date of Accident: 29/5/2024
Estimator: Loong
Surveyor:

SUPPLEMENTARY ESTIMATE

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	RE-COATING AND POLISHING FOR ACCIDENT PORTION	1		\$430.00
			S/N TOTAL	\$430.00

380/

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9019 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1822 | Fax: (+65) 6481 1011



NAME

ADDRESS

Home Tel.:

VIN:

Registration: SLJ 83 R

Technician:

Mileage:

Time Printed 21.6.24 11:38 AM

TESLA MODEL Y

Front : Left

Actual	BEFORE	Specified Range
0°00'		-1°35' -0°05'
5°17'		5°11' 7°11'
-0°33'		-0°05' 0°10'
12°30'		
12°29'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°32'		-1°35' -0°05'
5°06'		5°10' 7°10'
0°27'		-0°05' 0°10'
11°07'		
10°35'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°31'		-0°30' 0°30'
0°11'		-0°59' 1°01'
1°23'		
-0°06'		-0°10' 0°20'

Rear : Left

Actual	BEFORE	Specified Range
2°35'		-1°15' 0°15'
2°08'		0°03' 0°18'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°35'		-1°15' 0°15'
0°19'		0°03' 0°18'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
3°10'		-1°20' 1°20'
2°27'		0°05' 0°35'
0°54'		-0°10' 0°10'



UEN 202011263C

SPEEDWASH.SG PRIVATE LIMITED

YEO CHIAH YONG

87 Dawson Road #46-27
Singapore 141087

TESLA

SLJ83R

DATE

22 JULY 2024

DESCRIPTION	QTY	PRICE	TOTAL
Adam's Polished 10H Graphene Ceramic Coating Package (Apply Only On Both Left Door Panels (\$250)	1	\$250.00	\$250.00
3 Stage Polishing (\$150)	1	\$150	\$150 100%
Mobile Service (\$30)	1	\$30	\$30
		TOTAL	\$430.00
		DISCOUNT	-
		AMOUNT	\$430.00

PAYMENT INFORMATION

Paynow To :
speedwas.sg private limited
UEN 202011263C

5001 Beach Road #07-
01/15 Golden Mile
Complex Singapore
199588

+65 97222082
speedwashsingapore@gmail.com



UEN 202011263C

SPEEDWASH.SG PRIVATE LIMITED

YEO CHIAH YONG

87 Dawson Road #46-27
Singapore 141087

TESLA

SLJ83R

DATE

19 MAY 2023

DESCRIPTION	QTY	PRICE	TOTAL
Adam's Polished 10H Graphene Ceramic Coating Package (\$700)	1	\$700.00	\$700.00
3 Stage Polishing (\$360)	1	\$360	\$360
Mobile Service (\$30)	1	\$30	\$30
Pest Fumigation (\$50)	0	-	-
Steam Cleaning (\$60)	0	-	-
Leather Conditioning (\$30)	0	-	-
TOTAL			\$1,090.00
DISCOUNT			-
AMOUNT			\$1,090.00

PAYMENT INFORMATION

Paynow To :
speedwas.sg private limited
UEN 202011263C

5001 Beach Road #07-
01/15 Golden Mile
Complex Singapore
199588

+65 97222082
speedwashsingapore@gmail.com