

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070156/UUA3Q2**Date:** 27/03/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070179327
Claimant Vehicle No :	FBQ2517A	Insured Vehicle No :	SMX3671M
Date of Loss:	26/01/2024	Nature of Claim:	TP
		Claim No:	6668334025SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ2517A	Engine No:	G3K9E0027406
Make & Model:	YAMAHA MTN155, 155cc	Chassis No:	MH3RG5620K0003818
Reg. Date:	23/08/2019 (Man. Year: 2019)	Odometer:	88141 km
Colour:	Black		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-17	Rear Tyre Size:	140/70-17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,069.00	2,293.20	775.80	25.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	300.00	550.00	64.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,919.00	2,593.20	1,325.80	33.83
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	3,919.00	2,050.00	1,869.00	47.69
+ GST 9.00/9.00% (S\$)	352.71	184.50	168.21	47.69
Nett Amount (S\$)	4,271.71	2,234.50	2,037.21	47.69
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		2,296.68		

INSPECTION

Date of Assignment:	09/07/2024	Ban Hock Hin Co. Pte Ltd (HQ)
Date Inspected:	09/07/2024 Inspected At:	BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial City
Estimated Period of Repair:	3.0 days	Singapore 533758

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALANCER HANDLE BAR	Cut	63.00 F	*63.00 FL
2	1		*BAR HANDLE	Bent	47.00 F	*47.00 FL
3	1		*BODY ASSY HEADLIGHT	Damaged	60.00 F	*60.00 FL
4	1		*BOLT FOOTREST	Cracked	17.00 F	*17.00 FL
5	1		*BOX REAR (SHAD) SH42 (CUT)	Not Consistent With The Impact	373.00 F	*- FL
6	1		*COVER HEADLIGHT	Cut	75.00 F	*75.00 FL
7	1		*COVER OUTER 1	Cut	28.00 F	*28.00 FL
8	1		*COVER SHIFT PEDAL	Damaged	47.00 F	*47.00 FL
9	1		*COVER SIDE 1	Cut	78.00 F	*78.00 FL
10	1		*COVER SIDE 3	Cut	78.00 F	*78.00 FL
11	1		*EMBLEM (YAMAHA) LOGO	Necessary	16.00 F	*16.00 FL
12	1		*EMBLEM YAMAHA	Necessary	3.00 F	*3.00 FL
13	1		*FENDER FRONT	Cut	85.00 F	*85.00 FL
14	1		*FOOTREST FRONT LEFT	Cracked	16.00 F	*16.00 FL
15	1		*FRONT FORK ASSY (LH)	Damaged	1,055.00 F	*1,055.00 FL
16	1		*GRAPHIC 1	Necessary	25.00 F	*25.00 FL
17	1		*GRAPHIC 3	Necessary	6.00 F	*6.00 FL
18	1		*LAMP SIGNAL FRONT LH	Cracked	28.00 F	*28.00 FL
19	1		*LEVER CLUTCH	Cut	28.00 F	*28.00 FL
20	1		*LIGHT PILOT HEADLAMP LEFT (SMALL LIGHT)	Cut	78.00 F	*78.00 FL
21	1		*MIRROR SET (RIZOMA) (CUT)	Not Consistent With The Impact	125.00 F	*- FL
22	1		*MT15 LOGO EMBLEM PLATE ALLOY (LED LIGHT)	Necessary	101.00 F	*101.00 FL
23	1		*PANEL LH	Cut	50.00 F	*50.00 FL
24	1		*SCOOP AIR LH	Cut	30.00 F	*30.00 FL
25	1		*SIDE STAND BIG FOOT (GOLD COLOUR)	Not Necessary	23.00 F	*- FL
26	1		*SLIDER ENGINE	Missing	125.00 F	*125.00 FL
27	1		*STAY HEADLIGHT	Bent	50.00 F	*50.00 FL
28	1		*SET STEERING CONE	Necessary	63.00 F	*63.00 FL
29	1		*UNDER BRACKET COMP	Damaged	296.00 F	*296.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,069.00	2,548.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	254.80
Total Parts (\$)	3,069.00	2,293.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	850.00	300.00
Gross Labour Cost (\$\$)			850.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >