



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

QUOTATION

NO. : 47026

DATE : 10/07/2024
CLAIM NO. : 12536
POLICY NO. : 5124154388-02
FROM : RAYMOND

VEHICLE NO. : FBQ2517A
MAKE/MODEL : YAM / MTN155

*not Authorized
in
motor
9/7/24
1/5 # 2050
3 days.
take photo. Heavily.*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE BAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	63.00
2	BAR HANDLE P/N: 74723 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$47.00	47.00
3	BODY ASSY, HEADLIGHT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$60.00	60.00
4	BOLT FOOTREST P/N: 80452 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
5	BOX REAR (SHAD) SH42 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$373.00	373.00
6	COVER HEADLIGHT P/N: 80453 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$75.00	75.00
7	COVER OUTER 1 P/N: 80462 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
8	COVER SHIFT PEDAL - (REPORTED BY MECHANIC)	REPLACE	1.00	\$47.00	47.00
9	COVER SIDE 1 P/N: 80454 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$78.00	78.00

*47026 *



DATA PROTECTION
ASSURED

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	COVER, SIDE 3 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$78.00	78.00
11	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
12	EMBLEM, YAMAHA - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	3.00
13	FENDER FRONT P/N: 80473 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	85.00
14	FOOTREST FRONT LEFT P/N: 80461 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
15	FRONT FORK ASSY (L.H) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,055.00	1,055.00
16	GRAPHIC 1 P/N: 80459 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	25.00
17	GRAPHIC 3 P/N: 80457 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	6.00
18	LABOUR P/N: 06766	Supply/Install	10.00	\$85.00	850.00
19	LAMP SIGNAL FRONT LH P/N: 79532 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
20	LEVER CLUTCH P/N: 72412 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
21	LIGHT PILOT HEADLAMP LEFT (SMALL LIGHT) P/N: 80465 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$78.00	78.00
22	MIRROR SET(RIZOMA) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$125.00	125.00
23	MT15 LOGO EMBLEM PLATE ALLOY (LED LIGHT) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$101.00	101.00
24	PANEL LH P/N: 80469 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$50.00	50.00
25	SCOOP AIR LH P/N: 80464 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	30.00

*47026 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
26	SIDE STAND BIG FOOT (GOLD COLOUR) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	23.00
27	SLIDER ENGINE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$125.00	125.00
28	STAY HEADLIGHT P/N: 80467 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$50.00	50.00
29	STEERING CONE SET P/N: 73287 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	63.00
30	UNDER BRACKET COMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$296.00	296.00

SUB TOTAL

\$3,919.00

GST @ 9 %

\$352.71

GRAND TOTAL (SGD)

\$4,271.71

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*47026 *

bizSAFE₃

22588
 102
 228320
 300
 2583.2
 202
 2074