



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24070157/Rqp3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	13/08/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 1768J	Veh. Inspected	SLK 3515L
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/026(LK)	Excess	\$0.00
Assign From	LAI PENGCHONG	Assign Date	08/07/2024

### 2. Vehicle Details

Make & Model	TOYOTA PRIUS HYBRID 1.8 CVT	C.C	1798
Engine No.	2ZRR982761	Year of Reg.	13/01/2017
Chassis No.	JTDKB3FU003541353	Colour	GREY
Odometer	513508 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	ARIVO	6
L/H Front Tyre	195/65R15	ARIVO	6
R/H Rear Tyre	195/65R15	ARIVO	6
L/H Rear Tyre	195/65R15	ARIVO	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	28/06/2024	Inspection Date	09/07/2024
Survey held at	LION CITY RENTALS PTE LTD - 4 JALAN BESUT SINGAPORE 619557		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days