

Name & Address:

Motor Claims Department
FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

Email/Fax No:

Contact No:

Vehicle No:

SND8986R

Brand & Model:

MINI One 5 Door RHD

Chassis/VIN No:

WMW22DK0802R77198

WIP#:

Date:

4-Jul-24

Franchise:

MINI

Contact Person (Eurokars):

JOSEPH

Contact No (Eurokars):

6331 0680

Type of Claim:

THIRD PARTY

YEAR MODEL:

21/12/2021

PARTS / MATERIAL CHARGES				MARK = Survey Marking [Key "A" if item is approved]		
NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER <i>scd</i>	M51.11.5.A3C.853	1		-	\$ 471.64
2	KIT ADD-ONS <i>scd</i>	M51.11.5.B39.761	1		-	\$ 67.34
3	BUMPER TRIM CENTER <i>repair</i>	M51.11.5.A3C.856	1		-	\$ 163.09
4	BUMPER TRIM COVER LH <i>scd</i>	M51.11.5.A3C.863	1		-	\$ 158.60
5	BUMPER TRIM COVER RH <i>X</i>	M51.11.5.A3C.864	1		-	\$ 114.27
6	AIR DUCT LH <i>X</i>	M51.11.9.450.597	1		-	\$ 58.89
7	BLIND RIVET <i>scd</i>	M07.14.7.191.115	10		-	\$ 14.30
8	CENTER GRILLE STRIPE TRIM <i>X</i>	M51.74.7.224.070	1		-	\$ 124.67
9	GRILLE SURROUND OUTER TOP <i>scd</i>	M51.11.9.450.550	1		-	\$ 162.57
10	GRILLE SURROUND OUTER BOTTOM <i>scd</i>	M51.11.9.450.551	1		-	\$ 128.05
11	GRILLE FRAME <i>scd</i>	M51.11.9.450.552	1		-	\$ 300.31
12	BONNET <i>bt</i>	M41.00.8.499.868	1		-	\$ 1,529.13
13	BONNET HINGE LH <i>7.</i>	M41.00.7.370.301	1		-	\$ 116.22
14	BONNET HINGE RH <i>X</i>	M41.00.7.370.302	1		-	\$ 116.22
15	LOCK F HOOD, LH <i>X</i>	M51.23.7.300.569	1		-	\$ 93.54
16	LOCK F HOOD, RH <i>X</i>	M51.23.7.300.570	1		-	\$ 93.54
17	SEAL BUMPER LH <i>X</i>	M41.00.7.297.245	1		-	\$ 19.96
18	GASKET, HEADLIGHT <i>X</i>	M51.76.7.391.409	1		-	\$ 60.97
19	LABEL, COOLANT <i>scd</i>	M71.23.6.992.810	1		-	\$ 34.91
20	TRIM RING, LH <i>mis</i>	M51.13.7.449.209	1		-	\$ 155.35
21	TRIM RING, RH <i>scd</i>	M51.13.7.449.210	1		-	\$ 155.35
22	CLIP RETAINE <i>scd</i>	M51.46.7.453.747	6		-	\$ 42.54
23	CLIP FOR TRIM RING <i>scd</i>	M51.13.2.752.145	14		-	\$ 56.42
24	MINI EMBLEM <i>scd</i>	M51.14.2.465.241	1		-	\$ 101.21
25	FENDER LH <i>repair</i>	M41.00.7.374.521	1		-	\$ 576.68
26	MOUNT FOR HEADLIGHT <i>X</i>	M51.64.7.301.599	1		-	\$ 92.82
27	BRACKET, DEFEND TOP <i>X</i>	M41.00.7.374.527	1		-	\$ 27.89
28	FENDER COVER TRIM <i>scd</i>	M51.11.9.450.647	1		-	\$ 210.34
29	CLIP NATUR <i>scd</i>	B51.43.7.001.491	4		-	\$ 4.44
30	HEADLIGHT, LH <i>cm</i>	M63.11.5.A21.CA3	1		-	\$ 2,834.07

31					\$ -
----	--	--	--	--	------

Sub-Total (Parts Price) \$ - \$ 8,085.33

LABOUR / SERVICES CHARGES			
NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE FRONT BUMPER, BONNET, FRT FENDER LH AND ALL RELATED DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	2760	\$ 3,650.00
2	TO RESPRAY FRONT BUMPER, BONNET & FRT FENDER LH.	2880	\$ 3,840.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 300 350.00
6	SUNDRIES.	nett	\$ 20 50.00

Survey Date & Time:	Repair Days:	Excess:
11/07/24	5 days	

Surveyor Remarks:

RASM
Repr by paint

Sub-Total (Labour Price) \$ - \$ 8,420.00

	REVISED	PRICE
Parts Price	\$ -	\$ 8,085.33
Labour Price	\$ -	\$ 8,420.00
Total (Initial Estimate)	\$ -	\$ 16,505.33
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 16,505.33
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 16,505.33
GST 9%	\$ -	\$ 1,485.48
GRAND TOTAL	\$ -	\$ 17,990.81

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: