

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

TO	: MSIG	DATE	12/7/2024
VEHICLE NO	: SKW3289M (2015)		Veron.
VEHICLE MODEL	: MAZDA 3		
CHASSIS NO	: JM6BM42A8G0318993		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Behind</i>	1	\$ 1,074.80	\$ 1,074.80
2	REAR BUMPER SIDE HOLDER <i>Ren</i>	2	\$ 38.00	\$ 76.00
3	REAR BUMPER REFLECTOR <i>Ren</i>	2	\$ 54.50	\$ 109.00
4	REAR BUMPER TOW COVER <i>Ren</i>	1	\$ 33.60	\$ 33.60
5	REAR BUMPER REINFORCEMENT <i>Ren</i>	1	\$ 537.30	\$ 537.30
6	REAR BUMPER SENSOR <i>1 piece</i>	2	\$ 185.20	\$ 370.40
7	REAR END PANEL <i>Ren</i>	1	\$ 559.60	\$ 559.60
8	REAR END PANEL TOP GARNISH <i>Ren</i>	1	\$ 185.00	\$ 185.00
9	REAR END PANEL ANTENNA SENSOR <i>Ren</i>	1	\$ 143.60	\$ 143.60

TOTAL PRICE: \$ 3,089.30
LESS 20% \$ 617.86
SUB TOTAL PRICE: \$ 2,471.44

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>Ren</i>	1 SET	\$ 50.00	\$ 50.00
2	REAR END PANEL TOP GARNISH CLIPS <i>31</i>	1 SET	\$ 20.00	\$ 20.00
3	REAR END PANEL SEALANT	1	\$ 60.00	\$ 60.00

TOTAL : \$ 130.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 600.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 600.00	500	
3	WIRING CHECK	\$ 50.00	X	
4	TUFF COAT	\$ 150.00	30	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO REMOVE AND REFIT UPHOLSTERY	\$ 150.00	X	

TOTAL: \$ 1,650.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 2,601.44

TOTAL LABOUR COST: \$ 1,650.00

TOTAL REPAIR COST: \$ 4,251.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

980

total: 2018

4/s: 1.6k

03 Days

1.6k