7/15/24, 5:59 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24070163/ENP3E2

Date: 15/07/2024

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MAA00601

Claimant Vehicle

CHASESP

CNASSESP

CNASSESP

CNASSESP

No: SHA3553B Insured Vehicle No: SNN5062Z

Date of Loss: 08/07/2024 Nature of Claim: TP Claim No: M2403827

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA3553B

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU405223

Reg. Date: 27/08/2020 (Man. Year: 2019) Chassis No: KMHC851CVLU188876

Colour: Blue Odometer: 352618 km

Engine Capacity: 1580 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm
West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,199.80	2,112.00	1,087.80	34.00
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,500.00	970.00	530.00	35.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,711.80	3,094.00	1,617.80	34.34
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	4,711.80	2,500.00	2,211.80	46.94
+ GST 9.00/9.00% (S\$)	424.06	225.00	199.06	46.94
Nett Amount (S\$)	5,135.86	2,725.00	2,410.86	46.94

INSPECTION

Date of Assignment: 09/07/2024 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 10/07/2024 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/15/24, 5:59 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jul 2024)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA3553B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Broken	481.10 FL	*481.10 FL
2	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*FRT BUMPER SIDE BRACKET LH	Not Necessary	35.00 FL	*- FL
4	1		*FRT FENDER LH	Repair	588.80 FL	*- FL
5	1		*FRT FENDER EMBLEM LH	Necessary	26.60 FL	*26.60 FL
6	1		*HEADLAMP ASSY LH	Cut	2,110.30 FL	*2,110.30 FL
7	1		*FRT FOG LAMP LH	Not Necessary	642.50 FL	*-FL
8	1		*FRT FOG LAMP GRILLE LH	Not Necessary	93.45 FL	*- FL
F=Fra	anchise p	part. L=ListIter	nDisc.			
				Sub Total (S\$)	3,999.75	2,640.00
			- List Item Discoun	t on L Items 20.00/20.00% (S\$)	799.95	528.00
				Total Parts (S\$)	3,199.80	2,112.00
				_		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items 1 1 OD/TP Case (Insurer)		12.00	12.00
	Sub Total (S\$)	12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	800.00	380.00
2	SPRAYPAINT CHARGES	New	600.00	560.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	0.00
		Gross Labour Cost (S\$)	1,500.00	970.00
	Rep	ort was unsubmitted during this print-out.		

< END OF ESTIMATES >