

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

TO	SOMPO	DATE	9/7/2024
VEHICLE NO	: SMG6420R (2016)	Veron.	
VEHICLE MODEL	: TOYOTA VIOS		
CHASSIS NO	: MHFBT9F3206070039		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Reis</i>	1	\$ 570.90	\$ 570.90
2	REAR BUMPER SIDE HOLDER <i>Cracked</i>	1	\$ 97.60	\$ 97.60
3	TAILLAMP <i>Cracked</i>	1	\$ 387.90	\$ 387.90
4	TAILLAMP PANEL <i>Reis</i>	1	\$ 320.40	\$ 320.40
5	TAILLAMP LOWER BRACKET <i>Reis</i>	1	\$ 35.10	\$ 35.10
6	REAR WINDSCREEN MOULDING <i>Reis</i>	1	\$ 185.20	\$ 185.20
7	REAR FENDER <i>Dislodged</i>	1	\$ 972.40	\$ 972.40
8	REAR FENDER INNER TRIM <i>Cracked</i>	1	\$ 356.40	\$ 356.40

1999.50

TOTAL PRICE: \$ 2,925.90

1499.62

LESS 25% \$ 731.47

SUB TOTAL PRICE: \$ 2,194.43

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>Red m</i>	1 SET	\$ 30.00	\$ 30.00
2	REAR FENDER SEALANT <i>m</i>	1	\$ 60.00	\$ 60.00
3	REAR FENDER INNER TRIM CLIPS <i>m</i>	1 SET	\$ 30.00	\$ 30.00
4	REAR WINDSCREEN SEALANT <i>m</i>	1	\$ 60.00	\$ 60.00

150

TOTAL : \$ 180.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 800.00	500	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	60	
5	TO REMOVE UPHOLSTRY	\$ 150.00	50	
6	TO REMOVE REVERSE SENSOR	\$ 100.00	X	
7	TO REMOVE VIDEO RECORDER	\$ 100.00	50	
8	TO REMOVE REAR WINDSCREEN	\$ 180.00	120	
9	TO REMOVE FUEL TANK	\$ 150.00	60	

TOTAL: \$ 2,680.00

1470

ESTIMATE REPORT

TOTAL PARTS COST: \$ 2,374.43

TOTAL LABOUR COST: \$ 2,680.00

TOTAL REPAIR COST:

\$

5,054.43

total: 3119.62

h/s: 2.5K

04 days

1/22/14/15
2.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: