

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Toh, Yuslinda

Date: 29 Aug 2024

Preliminary Advice

Vehicle No	: SNF3268C	Accident Date	: 29/06/2024
Make	: AUDI A5	Policy No.	: 7220055041
Assignment Date	: 09/07/2024	Excess	: S\$1,600.00
Date of Inspection	: 12/07/2024	Est. Duration of Repair	: 5
Inspection At	: 281 ALEXANDRA ROAD		
	REPAIRER: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,369.00 (inclusive supp \$192.00)
Revised Amount	:S\$	15,287.92
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,287.92
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	185,000.00
COE / PARF Rebate	:S\$	107,900.00
Salvage Value	:S\$	
Margin for Repair	:S\$	77,100.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Kindly approve on supplementary.