

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Toh, Yuslinda

Date: 16 Jul 2024

Preliminary Advice

Vehicle No	: SNF3268C	Accident Date	: 29/06/2024
Make	: AUDI A5	Policy No.	: 7220055041
Assignment Date	: 09/07/2024	Excess	: S\$1,600.00
Date of Inspection	: 12/07/2024	Est. Duration of Repair	: 5
Inspection At	: 281 ALEXANDRA ROAD		
	REPAIRER: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,177.00
Revised Amount	:S\$	16,927.00
Check Items (Estimated)	:S\$	3,967.00
Total	:S\$	20,894.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	185,000.00
COE / PARF Rebate	:S\$	107,900.00
Salvage Value	:S\$	
Margin for Repair	:S\$	77,100.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.