
ASS. REC. BY: Taypun - 1 REF: C5/A16/24670/66/Tup3

<u>ASS</u>	IGNMENT
From: Date:	Veh No: SNF 3268C Yr Regn: 2022, 05
Estimated Cost:	Турв: (A.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
QD/TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Traller or
To Inspect Vehicle No:	Make Audi AS
at Workshop m/s	Colour White A/C: Insured/Std/NI/NA
of	Sp.Reading 3613 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WAUZZE S5. MAO62382
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: 1/19	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record) \$600	Brake: Inscar / Jammed / Leaked / Burnt or
Make of Veh:	Modl: NII /S/Rim / STD A/Rim pr
	Tyre Size: F: 245 498
(Policy Condition)	R: w'~
Remark: The veh had commenced its repair at the time of inspection. N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value:	TOYO/YOKO or Hankook
IDAC Accident Rport: Consistent? : Yes or No	Front Rear
GIA / PR Seen: Consistent? : Yes or No	R/Bal. / mm R/Bal. / mm
Est Repairs: 5 days Res.: Yes or No	D.O.A. D.O.I. () 13/24
Lum Sum: % 3 Val.: Yes or No	Survey held at Memily Alexandra
CA REP. / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop- or
Vehicle: IN / OUT	Fv7 0 5
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Confirm final fig \$15,287.92 before	excess \$600.00 & GST and 5 repair days.
(red, \$20081.08, 56%)	
Date/Time, File Pass to? : Prell. Report	ays Of Repair: 5
Final Report R	esurvey No. of Trip: Survey Fee:
Dale/Ilme, File Return to?	Transportation:
Add Fee:	
Per format :	: Interview (\$) Photos
Lump Sun/LEE: 15	Tech, Invs (\$) ones
· · · · · · · · · · · · · · · · · · ·	: Meel:eucl (it

TOTAL

* PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA, KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS

 WORKSHOP
 : UBI ROAD 1

 CONTACT NO
 : 6366 2323

 FAX NO
 : 6841 1183

REFERENCE : PA/OD/0542/2024/KS

DATE : 11-Jul-24 WIP : 22613

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/7/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR STEPHEN MCNULTY

ADDRESS : 55 COVE DR

#0509

SINGAPORE 219384

TELEPHONE : HP +65 81211688

TYPE OF CLAIM : OWN DAMAGE CLAIM

POLICY NO : 7220055041-01

VEHICLE NO : SNF 3268 C

MODEL CODE : A5 SPORTBACK 2.0 TFSI

MODEL YEAR : 20/5/2022 ENGINE NO : DEM 034525

CHASSIS NO : WAUZZZF55MA062382

MILEAGE : KM

DATE IN : -

ESTIMATED BY : JOHNNY BOO / ALLAN WU

ACCIDENT DATE : 29-Jun-24

PLACE OF ACCIDENT : THE CASCADEN RESIDENCE





55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 3268 C

S/N	NATURE OF JOBS		_	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N	\$	480.00	~
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	S/N	\$	350.00	~
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$	2,800.00	1000
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.		\$	2,600.00	1100
5	TO RENEW RHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT.	S/N	\$	280.00	×
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$	292.00	/
	TOTAL LABOUR CHARGES	:	\$	6,802.00	- -





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 3268 C.

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	 S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,802.00 de	
2	FRONT BUMPER SECURING STRIP	1	\$ 45.00 Ne(~	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 245.00 🗶	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 329.00 7	
5	FRONT BUMPER SPOILER	1	\$ 675.00 2	
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 56.00 ?	
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 329.00 ?	
8	FRONT BUMPER AIR GUIDE GRILLE	1	\$ 169.00 art	
9	FRONT BUMPER TRIM - RH	1	\$ 60.00M1	7/
10	FRONT BUMPER TRIM - CENTER	1	\$ 143.00 🗶	
11	RADIATOR GRILLE	1	\$ 2,098.00 🗙	
12	FRONT PARKING AID SENSOR	1	\$ 286.00	
13	FRONT PARKING AID SENSOR SEAL RING	4	\$ 11.00	
14	FRONT LOCK CARRIER TOP BRACKET	1	\$ 183.00 (
15	FRONT REINFORCEMENT BEAM	1	\$ 1,033.00 🗶	
16	FRONT LOCK CARRIER TOP BRACKET SUPPORT LH / RH	2	\$ 74.00	
17	OUT TEMP SENSOR BRACKET	1	\$ 30.00 ?	
18	FRONT BUMPER GUIDE SECTION - RH	1	\$ 46.00 7	1
19	LED HEADLIGHT - RH	1	\$ 9,204.00 6~	1/
20	LED HEADLIGHT SPACER - RH	3	\$ 150.00 🗸	01/
	SUB TOTAL SPARE PARTS	:	\$ 17,968.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 3268 C.

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT REMARKS
21	LIFT CYLINDER - RH	1	\$ 239.00 ?
22	LIFT CYLINDER BRACKET - RH	1	\$ 19.00 ?
23	LIFT CYLINDER HOSE	1	\$ 118.00 ?
24	FRONT FENDER - RH	1	\$ 1,264.00 4
25	FRONT FENDER ATTACHMENT PARTS - RH	1	\$ 61.00 🗙
26	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 92,00 7
27	FRONT FENDER BRACKET - RH	1	\$ 73.00 }
28	FRONT FENDER BRACKET - RH	1	\$ 56.00 ?
29	FRONT FENDER BRACE - RH	1	\$ 177.00 *
30	FRONT FENDER BRACKET - RH	1	\$ 72.00 .
31	FRONT HEADLIGHT TOP COVER	1	\$ 55.00 🗴
32	FRONT FENDER LEDGE COVER - RH LONG	4	\$ 20.00 🗴
33	FRONT FENDER LEDGE COVER - RH SHORT	1	\$ 45.00 💢
34	FRONT WHEEL HOUSING LINER - RH	1	\$ 332.00 (
35	FRONT WHEEL SPOILER - RH	1	\$ 92.00
36	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 190.00?
37	BONNET	1	\$ 3,538.00 📈
38	BONNET ATTACHMENT PARTS	1	\$ 138.00 🗶
39	BONNET HINGE - LH / RH	2	\$ 1,020.00×
40	BONNET IMPACT PROTECTION	1	\$ 36.00 X
	SUB TOTAL SPARE PARTS	:	\$ 7,637.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 3268 C.

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	 S/NETT	REMARKS
			72.00 X	
41	BONNET IMPACT PROTECTION - LH / RH	1	\$	
42	FRONT ALUMINIUM RIM - RH	1	\$ 2,123.00 ⊀	
43	FRONT ALUMINIUM RIM RUBBER VALVE- RH	1	\$ 15.00 🗸	
44	FRONT NO PLATE	S/N	\$ 60.00 🗸	
45	SUNDRIES		\$ 500.00)
	TOTAL SPARE PARTS	:	\$ 28,375.00	
	TOTAL LABOUR CHARGES	į	\$ 6,802.00	
	GRAND TOTAL	. □ 1 • □ 1	\$ 35,177.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Tugihn 17495749
Not unprovise: Exitor 12/1/24 (240
P/P resum person paint
Sdays taught c/khanto.un

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF

THE AFFECTED VEHICLE. SHOULD WE REQUIRE

FURTHER LABOUR CHARGES AND SPARE PARTS IN THE

PROGRESS OF REPAIR, WE SHALL INFORM YOU

ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify

- the Repairer of the following:
- . To resurvey before/after spray painting . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO BODY REPAIR MANAGER

ALLAN WU CLAIMS CONSULTANT