

ASSIGNMENT

Front: _____ Date: _____
 Estin: ~~Estin~~ _____
 OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MV
 To In ~~Vehicle~~ No: _____
 at WO ~~in~~ / m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vek: _____
 (Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKP8746P Yr Regn: 2014, oct
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Volkswagen Touran 1598
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 196288 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WVGZZZITZF W008625
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/50R17
 R: 215/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Habilead

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 09/07/24
 Survey held at MCR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>W Chin.</u>
	COE Expiry: <u>30/04/2024</u>
	Estimate given during: Yes (✓)
	1st Survey: No ()
	MV: <u>110K</u>
	PV: <u>85.6K</u>
	Nett: <u>24.4K</u>

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

Survey Fee:

Transportation:

Photos

Others

Report Format:

Engine/Chassis / Body / etc

MCR Motors Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SKP 8746P**
 Made : Volkswagen
 Model : Touran 1.6 TDI
 Chassis No : WVGZZZ1TZFW008625

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper <i>Defend</i>	1	\$ 1,133.86	\$ 1,133.86
2	Front Bumper Side Retainer RH <i>Defend</i>	1	\$ 45.08	\$ 45.08
3	Front Bumper Side Bracket RH <i>New</i>	1	\$ 25.40	\$ 25.40
4	Front Bumper Side Retainer LH <i>New</i>	1	\$ 45.08	\$ 45.08
5	Front Bumper Side Bracket LH <i>New</i>	1	\$ 25.40	\$ 25.40
6	Front Bumper Sponge <i>New</i>	1	\$ 78.03	\$ 78.03
7	Front Bumper Reinforcement <i>New</i>	1	\$ 515.77	\$ 515.77
8	Front Bumper Side Garnish RH <i>New</i>	1	\$ 106.38	\$ 106.38
9	Front Bumper Centre Garnish <i>New</i>	1	\$ 185.78	\$ 185.78
10	Front Headlamp Assembly RH <i>ht</i>	1	\$ 763.80	\$ 763.80
11	Front Headlamp Assembly LH <i>New</i>	1	\$ 763.80	\$ 763.80
12	Front Headlamp Top Panel RH <i>New</i>	1	\$ 55.47	\$ 55.47
13	Front Headlamp Lower Bracket RH <i>New</i>	1	\$ 34.70	\$ 34.70
14	Front Headlamp Lower Bracket LH <i>New</i>	1	\$ 34.70	\$ 34.70
15	Front Chrome Outer Garnish <i>2</i>	1	\$ 554.60	\$ 554.60
16	Front Grille Chrome Emblem <i>ht</i>	1	\$ 64.34	\$ 64.34
17	Front Chrome Grille <i>New</i>	1	\$ 401.80	\$ 401.80
18	Front Support Panel <i>New</i>	1	\$ 826.01	\$ 826.01
19	Aircon Condenser	1	\$ 783.40	\$ 783.40
20	Front Fender RH <i>Defend</i>	1	\$ 556.54	\$ 556.54
21	Front Fender Inner Shield RH <i>form</i>	1	\$ 109.30	\$ 109.30
22	Front Wheel Rim RH <i>ht</i>	1	\$ 1,252.00	\$ 1,252.00
23	Front Lower Arm RH <i>But</i>	1	\$ 420.18	\$ 420.18
24	Front Wheel Bearing RH <i>Defend</i>	1	\$ 113.00	\$ 113.00
25	Front Shock Absorber RH <i>But</i>	1	\$ 342.45	\$ 342.45
26	Front Knuckle Arm RH <i>Defend</i>	1	\$ 613.80	\$ 613.80

Parts Sub Total : \$ 9,850.67

10% Discount \$ 985.07

PARTS TOTAL : \$ 8,865.60

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate <i>New</i>	1	\$ 50.00	\$ 50.00
2	Front Bumper Clips - Set <i>New</i>	1	\$ 50.00	\$ 50.00
3	Front Grille Assembly Clips - Set <i>New</i>	1	\$ 50.00	\$ 50.00
4	Front Fender Inner Shield Clips RH - Set <i>New</i>	1	\$ 50.00	\$ 50.00
5	Front Fender Sealant RH <i>New</i>	1	\$ 150.00	\$ 150.00

6	Radiator Coolant <i>Refill</i>	1	\$ 120.00	\$ 120.00	+
7	Front Tyre RH <i>Refill</i>	1	\$ 350.00	\$ 350.00	+
SPECIAL NETT TOTAL :				\$ 820.00	

Nos.	LABOUR	TOTAL S\$	
1	To Panel Beat, Remove & Refix Parts	\$ 1,600.00	400
2	To Spray Paint Affected Areas	\$ 1,600.00	400
3	Wiring & Bulb Check	\$ 100.00	30
4	To Remove & Refix Aircon Condenser and Top Up Gas	\$ 150.00	+
5	To Remove & Refix Radiator and Pressure Test	\$ 150.00	+
6	To Remove & Refix Front Undercarriage	\$ 350.00	?
7	To Conduct Four Wheel Alignment	\$ 150.00	80
8	To Remove & Refix Front Tyre and Conduct Wheel Balancing	\$ 120.00	+
9	To apply anti rust on affected parts	\$ 200.00	30
10	To Conduct Water Leak Test	\$ 100.00	+
11	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 480.00	+
LABOUR TOTAL :		\$ 5,000.00	

PARTS TOTAL : \$ 8,865.60
 SPECIAL NETT TOTAL : \$ 820.00
 LABOUR TOTAL : \$ 5,000.00
GRAND TOTAL : \$ 14,685.60

Adrian Lj
2/s 09/07/24.
07 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MCR Motors Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : SKP 8746P
Made : Volkswagen
Model : Touran 1.6 TDI
Chassis No : WVGZZZ1TZFW008625

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Steering Rack <i>Bent</i>	1	\$ 5,333.21	\$ 5,333.21 ✓
Parts Sub Total :				\$ 5,333.21
10% Discount				\$ 533.32
PARTS TOTAL :				\$ 4,799.89

PARTS TOTAL : \$ 4,799.89

GRAND TOTAL : \$ 4,799.89

Adrian Lj
10/07/24. H.S.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	044M
Vehicle Details	
Vehicle No.:	SKP8746P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Jul 2024
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.6 TDI AT 1T332Z
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	CAYAE2406
Chassis No.:	WVGZZZ1TZFW008625
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$25,090.00
Original Registration Date:	17 Oct 2014
First Registration Date:	17 Oct 2014
Transfer Count:	3
Actual ARF Paid:	\$17,126.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Oct 2024
PARF Rebate Amount:	\$8,563.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2034
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
PQP Paid:	\$78,482.00
COE Rebate Amount:	\$76,999.00
Total Rebate Amount:	\$85,562.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 08 Jul 2024

OK