

MCR Motors Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SKP 8746P**
 Made : Volkswagen
 Model : Touran 1.6 TDI
 Chassis No : WVGZZZ1TZFW008625

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper <i>Rehd</i>	1	\$ 1,133.86	\$ 1,133.86
2	Front Bumper Side Retainer RH <i>Rnd</i>	1	\$ 45.08	\$ 45.08
3	Front Bumper Side Bracket RH <i>new</i>	1	\$ 25.40	\$ 25.40
4	Front Bumper Side Retainer LH <i>new</i>	1	\$ 45.08	\$ 45.08
5	Front Bumper Side Bracket LH <i>new</i>	1	\$ 25.40	\$ 25.40
6	Front Bumper Sponge <i>new</i>	1	\$ 78.03	\$ 78.03
7	Front Bumper Reinforcement <i>new</i>	1	\$ 515.77	\$ 515.77
8	Front Bumper Side Garnish RH <i>new</i>	1	\$ 106.38	\$ 106.38
9	Front Bumper Centre Garnish <i>new</i>	1	\$ 185.78	\$ 185.78
10	Front Headlamp Assembly RH <i>at</i>	1	\$ 763.80	\$ 763.80
11	Front Headlamp Assembly LH <i>new</i>	1	\$ 763.80	\$ 763.80
12	Front Headlamp Top Panel RH <i>new</i>	1	\$ 55.47	\$ 55.47
13	Front Headlamp Lower Bracket RH <i>new</i>	1	\$ 34.70	\$ 34.70
14	Front Headlamp Lower Bracket LH <i>new</i>	1	\$ 34.70	\$ 34.70
15	Front Chrome Outer Garnish <i>2</i>	1	\$ 554.60	\$ 554.60
16	Front Grille Chrome Emblem <i>1</i>	1	\$ 64.34	\$ 64.34
17	Front Chrome Grille <i>1</i>	1	\$ 401.80	\$ 401.80
18	Front Support Panel <i>1</i>	1	\$ 826.01	\$ 826.01
19	Aircon Condenser	1	\$ 783.40	\$ 783.40
20	Front Fender RH <i>Dented</i>	1	\$ 556.54	\$ 556.54
21	Front Fender Inner Shield RH <i>torn</i>	1	\$ 109.30	\$ 109.30
22	Front Wheel Rim RH <i>at</i>	1	\$ 1,252.00	\$ 1,252.00
23	Front Lower Arm RH <i>Bent</i>	1	\$ 420.18	\$ 420.18
24	Front Wheel Bearing RH <i>Rnd</i>	1	\$ 113.00	\$ 113.00
25	Front Shock Absorber RH <i>Bent</i>	1	\$ 342.45	\$ 342.45
26	Front Knuckle Arm RH <i>Rnd</i>	1	\$ 613.80	\$ 613.80

Parts Sub Total : \$ 9,850.67

10% Discount \$ 985.07

PARTS TOTAL : \$ 8,865.60

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate <i>new</i>	1	\$ 50.00	\$ 50.00
2	Front Bumper Clips - Set <i>new</i>	1	\$ 50.00	\$ 50.00
3	Front Grille Assembly Clips - Set <i>new</i>	1	\$ 50.00	\$ 50.00
4	Front Fender Inner Shield Clips RH - Set <i>new</i>	1	\$ 50.00	\$ 50.00
5	Front Fender Sealant RH <i>new</i>	1	\$ 150.00	\$ 150.00

6	Radiator Coolant <i>Refill</i>	1	\$ 120.00	\$ 120.00	+
7	Front Tyre RH <i>Refill</i>	1	\$ 350.00	\$ 350.00	+
SPECIAL NETT TOTAL :				\$ 820.00	

Nos.	LABOUR	TOTAL S\$	
1	To Panel Beat, Remove & Refix Parts	\$ 1,600.00	400
2	To Spray Paint Affected Areas	\$ 1,600.00	400
3	Wiring & Bulb Check	\$ 100.00	30
4	To Remove & Refix Aircon Condenser and Top Up Gas	\$ 150.00	x
5	To Remove & Refix Radiator and Pressure Test	\$ 150.00	+
6	To Remove & Refix Front Undercarriage	\$ 350.00	?
7	To Conduct Four Wheel Alignment	\$ 150.00	80
8	To Remove & Refix Front Tyre and Conduct Wheel Balancing	\$ 120.00	+
9	To apply anti rust on affected parts	\$ 200.00	30
10	To Conduct Water Leak Test	\$ 100.00	+
11	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 480.00	x
LABOUR TOTAL :		\$ 5,000.00	

PARTS TOTAL : \$ 8,865.60
 SPECIAL NETT TOTAL : \$ 820.00
 LABOUR TOTAL : \$ 5,000.00
GRAND TOTAL : \$ 14,685.60

Adnan Lj
2/s 09/07/24.
07 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MCR Motors Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SKP 8746P**
Made : **Volkswagen**
Model : **Touran 1.6 TDI**
Chassis No : **WVGZZ1TZFW008625**

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Steering Rack <i>Best</i>	1	\$ 5,333.21	\$ 5,333.21
Parts Sub Total :				\$ 5,333.21
10% Discount				\$ 533.32
PARTS TOTAL :				\$ 4,799.89

PARTS TOTAL : \$ 4,799.89

GRAND TOTAL : \$ 4,799.89

Adrian Lj
10/07/24. H.S.