



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 47012

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MS FIRST CAPITAL INSURANCE LTD

DATE : 04/07/2024
CLAIM NO. : 12532
POLICY NO. : MC/00496611/06

FROM : STEPHANIE

VEHICLE NO. : FBL8420G
MAKE/MODEL : YAM / SUPER TENERE

*Not Allowed
has
notes
9/7/24
limited repair
1/5 &
3 days
Whisper. When
(Page 1 of 3)*

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT FORK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	186.00 <i>Bo</i>
2	BOX REAR (COOCASE) 60L P/N: 56161 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$775.00	<i>See</i> 775.00 <i>X</i>
3	COVER 2 P/N: 54373 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$279.00	<i>cut</i> 279.00 <i>✓</i>
4	COVER FOOTREST RH P/N: 50788 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00 <i>?</i>
5	COVER HANDLE RH P/N: 44788 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.00	<i>cut</i> 36.00 <i>✓</i>
6	CRASH BAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,488.00	<i>cut</i> 1,488.00 <i>✓</i>
7	EMBLEM P/N: 45253 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$53.00	<i>new</i> 53.00 <i>✓</i>
8	EMBLEM "SUPER TENERE" SIDE COVER P/N: 59838 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$17.00	<i>new</i> 34.00 <i>✓</i>
9	FOOTREST P/N: 46860 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$59.00	<i>cut</i> 59.00 <i>✓</i>



S/N	Description	Action	Qty	Unit Price	Amount
10	FORK PROTECTORS (R&G) SUPER TENERE 2014 P/N: 48478 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	186.00
11	FRONT FORK GUARDS PROTECTION - (REPORTED BY MECHANIC)	REPLACE	1.00	\$232.00	232.00
12	GRIP TANK (SS) YAM SUPER TENERE (2010-CURRENT) P/N: 63726 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$279.00	279.00
13	LABOUR P/N: 06766 - (REPORTED BY MECHANIC)	REPLACE	8.00	\$85.00	680.00
14	LED LIGHT (J4B) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$698.00	698.00
15	MIRROR R P/N: 46825 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$107.00	107.00
16	PANEL 2 P/N: 45261 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$239.00	239.00
17	PEDAL BRAKE P/N: 46832 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$197.00	197.00
18	PEDAL BRAKE PLATE P/N: 73675 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$78.00	78.00
19	REAR FOOTREST ASSY 2 P/N: 46827 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$270.00	270.00
20	SPRAY PAINT FUEL TANK - (REPORTED BY MECHANIC)	Spray	1.00	\$341.00	341.00
21	STICKER (YAMAHA STRIPES) L/R - (REPORTED BY MECHANIC)	REPLACE	1.00	\$39.00	39.00
22	STICKER COVER SIDE L/R P/N: 59839 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	25.00
23	STICKER COVER SIDE RH P/N: 59833 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	25.00

SUB TOTAL

\$6,322.00

GST @ 9 %

\$568.98

GRAND TOTAL (SGD)

\$6,890.98

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	50% deposit required before ordering of parts.				

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



STEPHANIE

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

bizSAFE₃