



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBL 8420G

| REPLACEMENT OF PARTS |  |                      |                        |                   |
|----------------------|--|----------------------|------------------------|-------------------|
| Qty                  | Description of Parts                           | Condition            | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1                    | BOX REAR (COOCASE) 60L                         | SERVICEABLE          | \$775.00               | \$0.00            |
| 1                    | COVER 2  | CUT                  | \$279.00               | \$279.00          |
| 1                    | COVER FOOTREST RH                              | * CHECK              | \$16.00                | \$0.00            |
| 1                    | COVER HANDLE RH                                | CUT                  | \$36.00                | \$36.00           |
| 1                    | CRASH BAR                                      | CUT                  | \$1,488.00             | \$1,488.00        |
| 1                    | EMBLEM   | NECESSARY            | \$53.00                | \$53.00           |
| 2                    | EMBLEM "SUPER TENERE" SIDE COVER @\$17.00      | NECESSARY            | \$34.00                | \$34.00           |
| 1                    | FOOTREST                                       | CUT                  | \$59.00                | \$59.00           |
| 1                    | FORK PROTECTORS (R&G) SUPER TENERE 2014        | MISSING              | \$186.00               | \$186.00          |
| 1                    | FRONT FORK GUARDS PROTECTION                   | SERVICEABLE          | \$232.00               | \$0.00            |
| 1                    | GRIP TANK (SS) YAM SUPER TENERE (2010-CURRENT) | NOT NECESSARY        | \$279.00               | \$0.00            |
| 1                    | LED LIGHT (J4B)                                | BROKEN               | \$698.00               | \$698.00          |
| 1                    | MIRROR R                                       | CUT                  | \$107.00               | \$107.00          |
| 1                    | PANEL 2  | CUT                  | \$239.00               | \$239.00          |
| 1                    | PEDAL BRAKE                                    | TO REPAIR SEE LABOUR | \$197.00               | \$0.00            |
| 1                    | PEDAL BRAKE PLATE                              | SERVICEABLE          | \$78.00                | \$0.00            |
| 1                    | REAR FOOTREST ASSY 2                           | SERVICEABLE          | \$270.00               | \$0.00            |
| 1                    | STICKER (YAMAHA STRIPES) RH                    | NECESSARY            | \$39.00                | \$39.00           |
| 1                    | STICKER COVER SIDE RH                          | NECESSARY            | \$25.00                | \$25.00           |
| 1                    | STICKER COVER SIDE RH                          | NECESSARY            | \$25.00                | \$25.00           |
|                      | <b>LESS 0.00 / 10.00% DISCOUNT</b>             |                      | \$0.00                 | (\$326.80)        |
|                      |  |                      | \$5,115.00             | \$2,941.20        |

| Labour             |  |           |                        |                   |
|--------------------|--|-----------|------------------------|-------------------|
|                    | Description of Parts                           | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
|                    | ALIGNMENT FORK                                 |           | \$186.00               | \$80.00           |
|                    | LABOUR. INCLUSIVE OF THE REPAIR OF PEDAL BRAKE |           | \$680.00               | \$350.00          |
|                    | SPRAY PAINT FUEL TANK                          |           | \$341.00               | \$220.00          |
|                    |  |           | \$1,207.00             | \$650.00          |
| <b>GRAND TOTAL</b> |  |           | <b>\$6,322.00</b>      | <b>\$3,591.20</b> |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

|  |   |  |                   |
|--|---|--|-------------------|
|  | <b>RECOMMENDED COST OF REPAIRS<br/>(REPAIR COST NOT CONCLUDE)<br/>(EXCLUDE CHECK ITEMS S\$14.40 NETT)</b> |  | <b>\$3,591.20</b> |
|--|---|--|-------------------|

**Report Ref No: CS/FCI24070170/Uvp3**

**MARKET VALUE: \$3,200.00 (EST)-LTA REIMBURSEMENT VALUE: \$184.00=NETT VALUE: \$3,016.00**

## CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.