



BAN HOCK HIN
Co., Pte Ltd

Fatni

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

NO. : 47014

DATE : 08/07/2024
CLAIM NO. : 12528
POLICY NO. : 5131876148-01
FROM : RAYMOND

VEHICLE NO. : FBP8897T
MAKE/MODEL : YAM / R15

*not authorized
him
moray
9/7/24
L/SS
take place after 6 days*

(Page 1 of 8)

S/N	Description	Action	Qty	Unit Price		Amount
1	ALIGNMENT BODY P/N: 29561 - (REPORTED BY MECHANIC)	Repair	1.00	\$711.00	?	711.00
2	AXLE RIM FRONT P/N: 72393 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	C47	23.00
3	BALANCER HANDLE (AFTERMARKET) HEAVY P/N: 75305 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	C47	63.00
4	BAR HANDLE LH P/N: 72405 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$82.00	?	82.00
5	BAR HANDLE RH P/N: 75573 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$82.00	?	82.00
6	BEARING P/N: 50211 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$13.00	RM	26.00
7	BEARING STEERING CONE LOWER P/N: 56456 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	RM	14.00
8	BEARING STEERING CONE UPPER P/N: 56209 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	RM	23.00
9	BOLT FOOTREST P/N: 47685 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	C47	10.00

*47014 *



DATA PROTECTION
ASSURED

bizSAFE₃



S/N	Description	Action	Qty	Unit Price		Amount
10	BRACKET UNDER FORK P/N: 64113 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$324.00	One	324.00
11	BRACKET, POUCH P/N: 81833 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	Dye	38.00
12	CABLE CLUTCH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	?	21.00
13	COMPLETER AFTERMARKET STICKERS - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	ner ?	341.00
14	COOLANT (MOBIL) ANTIFREEZE P/N: 60213 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	ner	21.00
15	COVER 7 P/N: 72400 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	One	34.00
16	COVER HANDLE LEVER CLUTCH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	One	6.00
17	COVER INNER FRONT RH P/N: 73959 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$47.00	One	47.00
18	COVER RADIATOR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	?	17.00
19	COVER SIDE LOWER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$90.00	One	90.00
20	COVER SIDE LOWER RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$97.00	One	97.00
21	COVER TAIL RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$54.00	One	54.00
22	COVER TANK CENTER P/N: 75821 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$74.00	One ?	74.00
23	COVER TANK SIDE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$57.00	?	57.00
24	COVER TANK SIDE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$57.00	?	57.00

*47014 *

DATA PROTECTION
ASSUREDbizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	COWLING FRONT LOWER P/N: 72422 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	<i>CM</i> 55.00
26	COWLING FRONT UPPER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	<i>CM</i> 51.00
27	COWLING SIDE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$81.00	<i>CM</i> 81.00
28	COWLING SIDE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$81.00	<i>CM</i> 81.00
29	CROWN HANDLE P/N: 72411 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$91.00	<i>7.00</i> 91.00
30	DAMPER COWLING 1 P/N: 75574 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$3.00	<i>ner</i> 6.00
31	DAMPER COWLING 2 P/N: 75571 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$3.00	<i>ner</i> 6.00
32	EMBLEM (YAMAHA) LOGO P/N: 56610 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$21.00	<i>ner</i> 42.00
33	EMBLEM YAMAHA - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	<i>ner</i> 10.00
34	FOOTREST FRONT RH P/N: 50412 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	<i>CM</i> 23.00
35	FORK FRONT ASSY LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$850.00	<i>sup/ner</i> 850.00
36	FORK FRONT ASSY RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$850.00	<i>sup/ner</i> 850.00
37	GASKET WATER PUMP P/N: 58136 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	<i>?</i> 8.00
38	GRILL AIR OULET LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	<i>7.00</i> 8.00
39	GROMMET POLE REAR P/N: 43692 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	<i>?</i> 7.00

*47014 *

DATA PROTECTION
ASSUREDbizSAFE₃

S/N	Description	Action	Qty	Unit Price		Amount
40	GROMMET RADIATOR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	?	3.00
41	HEADLIGHT ASSY P/N: 72416 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$530.00	one	530.00
42	HOSE RADIATOR 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	?	13.00
43	LABEL WARNING P/N: 72389 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	?	3.00
44	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	Supply/Install	24.00	\$85.00	700	2,040.00
45	LEVER BRAKE P/N: 50424 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	504	23.00
46	LEVER CLUTCH P/N: 72412 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	1m	28.00
47	LICENCE LIGHT ASSY P/N: 64188 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	?	28.00
48	METER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$240.00	?	240.00
49	MID GROMMET P/N: 21154 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	?	6.00
50	MIRROR RECTANGLE (SET) P/N: 54669 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$78.00	one	78.00
51	MUDGUARD FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$60.00	one	60.00
52	NUT P/N: 20925 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$12.00	new	48.00
53	NUT SPRING P/N: 53709 - (REPORTED BY MECHANIC)	REPLACE	5.00	\$4.00	new	20.00
54	NUT STEERING CONE P/N: 65885 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$13.00	new	26.00

*47014 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price		Amount
55	PAD CAP TANK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	1.1	71.00 X
56	PANEL CONSOLE LH P/N: 81850 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	1.1	14.00
57	PANEL CONSOLE RH P/N: 81830 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	1.1	16.00
58	PANEL INNER FRONT LOWER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	1.1	51.00
59	PANEL INNER LH P/N: 72403 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	1.1	11.00
60	PANEL INNER RH P/N: 81831 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	1.1	11.00
61	PANEL SIDE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	1.1	22.00
62	PANEL SIDE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	1.1	22.00
63	PEDAL BRAKE P/N: 72397 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	1.1	28.00
64	PIPE TANK COOLANT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	?	19.00
65	PLATE P/N: 81846 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	?	5.00
66	PLATE P/N: 81838 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	?	5.00
67	PLATE NUMBER FRONT (STRAIGHT) P/N: 26249 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	2.2	22.00
68	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	3.0	30.00
69	PROTECTOR MUFFLER P/N: 64189 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$46.00	1.1	46.00

*47014 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
70	RACE BALL 1 P/N: 26829 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	? 14.00
71	RACE BALL UPPER 2 P/N: 26830 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	? 14.00
72	RADIATOR ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$282.00	Sur 282.00 X
73	RETAINER BALL BEARING P/N: 55218 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	? 13.00
74	RIM SPORT FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$353.00	wogab 353.00
75	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE	10.00	\$3.00	ner 30.00
76	SEAL P/N: 72417 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	ner 5.00
77	SEAL 2 P/N: 72426 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	ner 5.00
78	SEAL 2 P/N: 72426 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	ner 5.00
79	SEAL DUST STERRING CONE P/N: 41201 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	ner 10.00
80	SEAL WHEEL FRONT P/N: 67590 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	ner 10.00
81	SHAFT ROCKER 2 P/N: 70369 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	ner 11.00
82	SIGNAL FRONT LH ASSY P/N: 72388 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	rye 31.00
83	SIGNAL FRONT RH ASSY P/N: 72413 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	rye 31.00
84	STAY HEADLAMP P/N: 75842 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$94.00	Sur 94.00

*47014 *

DATA PROTECTION
ASSUREDbizSAFE₃

S/N	Description	Action	Qty	Unit Price		Amount
85	STAY WATERPUMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	?	13.00
86	STICKER COVER TAIL LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	ner	5.00
87	STICKER COWLING FRONT UPPER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	ner	3.00
88	STICKER COWLING FRONT UPPER RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	ner	3.00
89	STICKER COWLING SIDE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	ner	3.00
90	STICKER COWLING SIDE LH 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	ner	13.00
91	STICKER COWLING SIDE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	ner	3.00
92	STICKER COWLING SIDE RH 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	ner	13.00
93	SWITCH HANDLE LH P/N: 81834 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$61.00	?	61.00
94	TANK COOLANT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	?	17.00
95	TRANSPORT CHARGES P/N: 07169 - - ONE WAY TOWING		1.00	\$63.00	35-	63.00
96	VALVE RIM P/N: 27762 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	?	14.00
97	WASHER CROWN HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	ner	6.00
98	WASHER PLATE P/N: 28656 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	ner	5.00
99	WASHER STEERING CONE P/N: 64848 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	ner	5.00

*47014 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
100	WINDSHIELD FRONT P/N: 75820 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$81.00	81.00
SUB TOTAL					\$9,216.00
GST @ 9 %					\$829.44
GRAND TOTAL (SGD)					<u>\$10,045.44</u>

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*47014 *



bizSAFE₃

