



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0541/2024/KS  
**DATE** : 10-Jul-24  
**WIP** : 22608

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/7/2024**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : MS GAN SIYI  
**ADDRESS** : 88 WEST COARD ROAD  
#04-38  
SINGAPORE 126819  
**TELEPHONE** : HP +65 83395234  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7210156090-01  
**VEHICLE NO** : **SMS 8946 P**  
**MODEL CODE** : Q2 1.0 TFSI S TRONIC  
**MODEL YEAR** : 19/3/2020  
**ENGINE NO** : CHZ C33098  
**CHASSIS NO** : WAUZZZGA8KA083090  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 8-Jul-24  
**PLACE OF ACCIDENT** : PIE (DIRECTION TOWARDS TUAS)



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 8946 P**

<b>S/N</b>	<b>NATURE OF JOBS</b>	<b>ESTIMATED CHARGES</b>	<b>SURVEYOR'S RECOMMENDATIONS</b>
1	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	S/N \$ 280.00	
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$ 800.00	
3	TO PLACE VEHICLE ON CAR-O-LINER	S/N \$ 2,400.00	
4	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT,HORNS, OUTSIDE TEMPERATURE SENOSR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
5	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	
6	TO REMOVE AND RENEW AIRCON CONDENSOR, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM AND REGAS AND PRESSURISE COOLING SYSTEM.	S/N \$ 1,400.00	
7	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00	
8	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CNTORL UNIT, PILLAR TRIMS, ROOF LININGS AND BOTH CURTAIN AIRBAGS.	S/N \$ 3,600.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 10,200.00</b>	

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 8946 P**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
9	TO REMOVE AND RENEW INTAKE CONNECTION AND AIR FILTER HOUSING. TO REMOVE AND AIR FILTER HOUSING. TO REMOVE AND RENEW CHARGE AIR COOLER.	S/N \$ 780.00	
10	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY.	S/N \$ 3,200.00	
11	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY TO FACILITATE CAR O-LINER REPAIR.	S/N \$ 2,800.00	
12	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO ALIGN BOTH FRONT CHASSIS FRAME TO SPECIFICATION. TO REPAIR BOTH FRONT DOORS AND BOTH A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN POSITION. TO CUT OUT AND WELD RHS FRONT FENDER SUPPORT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 12,800.00	
13	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BOTH FRONT DOORS, BONNET BOTH A-PILLAR, ENGINE COMPARTMENT AND RHS FRONT FENDER SUPPORT.	\$ 8,000.00	
14	TO RENEW FRONT WINDSCREEN AND CARRY OUT WATER SEEPAGE TEST.	S/N \$ 680.00	
15	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	S/N \$ 400.00	
16	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$ 584.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 29,244.00</b>	

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1		1	\$	2,321.00
2	FRONT BUMPER FIXING PARTS	1	\$	387.00
3	FRONT BUMPER GRILLE	1	\$	247.00
4	FRONT BUMPER AIR GUIDE GRILLE- LH / RH	2	\$	424.00
5	FRONT BUMPER AIR GUIDE GRILLE END CAP - LH / RH	2	\$	148.00
6	FRONT BUMPER SPOILER	1	\$	374.00
7	FRONT BUMPER CLOSING ELEMENT	1	\$	195.00
8	FRONT WHEEL SPOILER - LH / RH	2	\$	86.00
9	FRONT BUMPER ADAPTOR - LH / RH	2	\$	108.00
10	RADIATOR GRILLE	1	\$	1,734.00
11	RADIATOR GRILLE STRIKER PLATE	1	\$	153.00
12	FRONT BUMPER TOP COVER	1	\$	126.00
13	"CAUTION" STICKER	1	\$	25.00
14	"A/C" STICKER	1	\$	10.00
15	FRONT REINFORCEMENT BEAM	1	\$	882.00
16	FRONT FOAM FILLER PIECE	1	\$	98.00
17	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$	90.00
18	FRONT FENDER - LH / RH	2	\$	2,730.00
19	FRONT FENDER ATTACHMENT PARTS	1	\$	47.00
20	FRONT FENDER BRACKET - LH / RH TOP REAR	2	\$	40.00
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$</b>	<b>10,225.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:       REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                   SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
21	FRONT FENDER BRACKET - LH / RH TOP CENTER	2	\$ 124.00	
22	FRONT FENDER BRACKET - LH / RH TOP FRONT	2	\$ 68.00	
23	FRONT FENDER RIVET - LH / RH	12	\$ 52.00	
24	FRONT FENDER BRACE - LH / RH	2	\$ 134.00	
25	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 84.00	
26	FRONT FENDER INSULATION - LH / RH	2	\$ 258.00	
27	FRONT FENDER WHEEL HOUSE SEAL - LH / RH	2	\$ 94.00	
28	HEADLIGHT BRACKET - LH / RH	2	\$ 112.00	
29	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 472.00	
30	FRONT WHEEL HOUSING LINER ATTACHMENT PART	1	\$ 67.00	
31	FRONT WHEEL COVER - LH / RH	2	\$ 802.00	
32	LED HEADLIGHT - LH / RH	2	\$ 11,784.00	
33	LED HEADLIGHT POWER MODULE - LH / RH	1	\$ 1,808.00	
34	LED HEADLIGHT CONTROL UNIT - LH / RH	2	\$ 1,327.00	
35	LED WITH HEAT SINK - LH / RH	2	\$ 1,848.00	
36	LED HEADLIGHT SPACER - LH / RH	2	\$ 113.00	
37	LED HEADLIGHT MOUNTING - LH / RH	2	\$ 294.00	
38	LIFT CYLINDER - LH / RH	2	\$ 340.00	
39	LIFT CYLINDER HOSE	1	\$ 233.00	
40	LIFT CYLINDER HOSE COUPLING ELEMENT	2	\$ 28.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 20,042.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:       REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                   SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	LIFT CYLINDER HOSE T-JOINT	1	\$ 36.00	
42	BONNET	1	\$ 2,980.00	
43	BONNET ATTACHMENT PARTS	1	\$ 184.00	
44	BONNET HINGE - LH / RH	2	\$ 200.00	
45	BONNET GAS FILLIED STRUT	1	TBC	
46	BONNET STRIKER - LH / RH	2	\$ 260.00	
47	BONNET SOUND ABSORBER	1	\$ 275.00	
48	BONNET IMPACT PROTECTION - CENTER	1	\$ 38.00	
49	BONNET IMPACT PROTECTION - LH / RH	2	\$ 76.00	
50	PLENUM CHAMBER COVER - LH / RH	2	\$ 106.00	
51	PLENUM CHAMBER COVER - CENTER	2	\$ 260.00	
52	BONNET LOCK WITH MIRCO SWITCH	2	\$ 491.00	
53	BONNET BOWDEN CABLE - CENTER	1	\$ 72.00	
54	BONNET LOCK CABLE	1	\$ 92.00	
55	BONNET BOWDEN CABLE COVER	1	\$ 12.00	
56	BONNET BOWDEN CABLE	1	\$ 71.00	
57	BONNET BOWDEN CABLE	1	\$ 71.00	
58	BONNET RELEASE LEVER	1	\$ 16.00	
59	RADIATOR AIR GUIDE - LH / RH	2	\$ 118.00	
60	RADIATOR AIR GUIDE SEAL - RH	1	\$ 9.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 5,367.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.**

				<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>S/NETT</b>	<b>REMARKS</b>
61	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$	59.00	
62	HORN - LH	1	\$	343.00	
63	HORN - RH	1	\$	185.00	
64	HORN BRACKET - LH / RH	2	\$	80.00	
65	LOCK CARRIER	1	\$	1,236.00	
66	OUTSIDE TEMPERATURE SENSOR	1	\$	66.00	
67	A/C CONDENSOR	1	\$	876.00	
68	A/C CONDENSOR SEAL RING - NEC	1	\$	31.00	
69	REFRIFERENT LINE - A/C CONDENSOR -> CUTOFF	1	\$	846.00	
70	REFRIFERENT LINE - A/C COMPRESSOR -> CONDENSOR	1	\$	679.00	
71	REFRIGERENT LINE SEAL RING	1	\$	16.00	
72	RADIATOR	1	\$	1,177.00	
73	ADDITIONAL RADIATOR	1	\$	987.00	
74	RADIATOR BRACKET - UPPER LH / RH	2	\$	94.00	
75	RADIATOR BUSH - LOWER	2	\$	48.00	
76	RADIATOR SEALING STRIP - LH / RH	2	\$	44.00	
77	RADIATOR TOP HOSE	1	\$	177.00	
78	RADIATOR LOWER HOSE	1	\$	155.00	
79	RADIATOR RESERVOIR TANK	1	\$	70.00	
80	RADIATOR RESERVOIR TANK CAP	1	\$	44.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$</b>	<b>7,213.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:       REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                   SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
81	RADIATOR COOLANT	6	\$ 332.00	
82	RADIATOR FAN	1	\$ 1,681.00	
83	AIR FILTER	1	\$ 370.00	
84	AIR FILTER AIR GUIDE	1	\$ 72.00	
85	AIR FILTER AIR GUIDE COVER	1	\$ 49.00	
86	AIR FILTER AIR GUIDE	1	\$ 24.00	
87	AIR FILTER HOSE BAND CLAMP	1	\$ 24.00	
88	INTAKE MANIFOLD	1	\$ 809.00	
89	CHARGE AIR COOLAR	1	\$ 890.00	
90	CHARGE AIR COOLAR SEAL	1	\$ 26.00	
91	CONNECTING TUBE WITH AKF VALVE	1	\$ 392.00	
92	CONNECTING PLATE	1	\$ 93.00	
93	ENGINE MOUNTING	1	\$ 308.00	
94	GEARBOX MOUNTING	1	\$ 327.00	
95	RUBBER BUSH - UPPER / LOWER	1	\$ 127.00	
96	CONSOLE	1	\$ 215.00	
97	WINDSCREEN	1	\$ 1,227.00	
98	WINDSCREEN RAIN SENSOR GEL FOIL	1	\$ 140.00	
99	WINDSCREEN RETAINING SPRING	1	\$ 26.00	
100	WINDSCREEN PRIMER	1	\$ 27.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 7,159.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
101	AIRBAG UNIT - RH	1	\$ 4,399.00	
102	SPORTS STEERING WHEEL	1	\$ 2,533.00	
103	AIRBAG UNIT - LH	1	\$ 5,444.00	
104	HEAD AIRBAG UNIT - LH / RH	2	\$ 3,612.00	
105	HEAD AIRBAG UNIT GUIDE - LH / RH	2	\$ 62.00	
106	AIRBAG CONTROL UNIT	1	\$ 1,804.00	
107	CRASH SENSOR FOR AIRBAG	2	\$ 971.00	
108	DASHBOARD WITH AIR DUCT	1	\$ 5,285.00	
109	ROOF LINER	1	\$ 2,505.00	
110	SUNVISOR WITH MIRROR - LH	1	\$ 515.00	
111	RETAINER FOR SUN VISOR	2	\$ 50.00	
112	SUNVISOR - RH	1	\$ 515.00	
113	GRAB HANDLE - FRONT LH / RH	2	\$ 367.00	
114	A-PILLAR TRIM - LH / RH	2	\$ 398.00	
115	B-PILLAR TRIM - LH / RH UPPER	2	\$ 456.00	
116	C-PILLAR TRIM - LH / RH	2	\$ 230.00	
117	FRONT SEAT BELT - LH / RH	2	\$ 2,468.00	
118	WASH WATER RESERVOIR	1	\$ 222.00	
119	WATER LEVEL SWITCH	1	\$ 56.00	
120	WATER LEVEL SWITCH SEAL RING	1	\$ 28.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 31,920.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
121	WINDSCREEN WASHER PUMP	1	\$	147.00
122	WINDSCREEN WASHER PUMP SEAL	1	\$	10.00
123	WASH WATER RESERVOIR STRAINER	1	\$	26.00
124	WASH WATER RESERVOIR CAP	1	\$	26.00
125	FRONT DOOR COVER - LH / RH	2	\$	608.00
126	SEATBELT ADJUSTER - LH / RH	2	\$	414.00
127	BASE ENGINE	1	\$	23,733.00
128	NEEDLE BEARING	1	\$	30.00
129	7 SPEED DUAL CLUTCH GEARBOX	1	\$	20,563.00
130	TRANSMISSION FLUID	6		TBC
131	ENGINE COOLANT	6	\$	491.00
132	FRONT WINDSCREEN SEALANT	S/N	\$	200.00
133	METAL FILLER POWDER	S/N	\$	280.00
134	STONE CHIP	S/N	\$	180.00
135	CAVITY WAX	S/N	\$	140.00
136	FRONT NO PLATE	S/N	\$	60.00
<b>TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$</b>	<b>128,834.00</b>
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$</b>	<b>29,244.00</b>
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$</b>	<b>158,078.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT