

(08/11/13) Wef
ASS. REC. BY:

REF: CS(A1424070174/RVP3

5940

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SM8 8946P

at Workshop m/s

PREMIUM

of

BENOL SKROR

Insured:

AK

Policy No.

Claims No.

Sum Insured:

Excess:


TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

102k

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT 65K

Veh No:

SM8 8946P

Yr Regn:

2020 / MAR

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ANDI Q2110TFSI S.TRAK cc 999

Colour

GREEN

AC:

Insured / Std / NI / NA

Sp.Reading

41844

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAN2224A8KA083096

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

68/01/24

D.O.I.

11/01/24

Survey held at

BENOL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$

): S + RS \$



: Interview (\$

): Photos



: Tech. Invs (\$

): Others



: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0541/2024/KS
DATE : 10-Jul-24
WIP : 22608

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/7/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS GAN SIYI
ADDRESS : 88 WEST COARD ROAD
#04-38
SINGAPORE 126819
TELEPHONE : HP +65 83395234
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210156090-01
VEHICLE NO : **SMS 8946 P**
MODEL CODE : Q2 1.0 TFSI S TRONIC
MODEL YEAR : 19/3/2020
ENGINE NO : CHZ C33098
CHASSIS NO : WAUZZZGA8KA083090
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Jul-24
PLACE OF ACCIDENT : PIE (DIRECTION TOWARDS TUAS)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 8946 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	S/N \$ 280.00	X
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$ 800.00	?
3	TO PLACE VEHICLE ON CAR-O-LINER	S/N \$ 2,400.00	?
4	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT,HORNS, OUTSIDE TEMPERATURE SENOSR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	/
5	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	500
6	TO REMOVE AND RENEW AIRCON CONDENSOR, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM AND REGAS AND PRESSURISE COOLING SYSTEM.	S/N \$ 1,400.00	/
7	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00	280
8	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CNTORL UNIT, PILLAR TRIMS, ROOF LININGS AND BOTH CURTAIN AIRBAGS.	S/N \$ 3,600.00	/
TOTAL LABOUR CHARGES		: \$ 10,200.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 8946 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
9	TO REMOVE AND RENEW INTAKE CONNECTION AND AIR FILTER HOUSING. TO REMOVE AND AIR FILTER HOUSING. TO REMOVE AND RENEW CHARGE AIR COOLER.	S/N \$ 780.00	/
10	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY.	S/N \$ 3,200.00	/ photo
11	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY TO FACILITATE CAR O-LINER REPAIR.	S/N \$ 2,800.00	?
12	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO ALIGN BOTH FRONT CHASSIS FRAME TO SPECIFICATION. TO REPAIR BOTH FRONT DOORS AND BOTH A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN POSITION. TO CUT OUT AND WELD RHS FRONT FENDER SUPPORT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 12,800.00	3500
13	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BOTH FRONT DOORS, BONNET BOTH A-PILLAR, ENGINE COMPARTMENT AND RHS FRONT FENDER SUPPORT.	\$ 8,000.00	3300
14	TO RENEW FRONT WINDSCREEN AND CARRY OUT WATER SEEPAGE TEST.	S/N \$ 680.00	/
15	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	S/N \$ 400.00	invoice /
16	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$ 584.00	/
TOTAL LABOUR CHARGES		: \$ 29,244.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	Front Bumper, front ✓	1	\$ 2,321.00	
2	FRONT BUMPER FIXING PARTS ✓	1	\$ 387.00	
3	FRONT BUMPER GRILLE ✓	1	\$ 247.00	
4	FRONT BUMPER AIR GUIDE GRILLE- LH / RH ✓	2	\$ 424.00	
5	FRONT BUMPER AIR GUIDE GRILLE END CAP - LH / RH ✓	2	\$ 148.00	
6	FRONT BUMPER SPOILER ✓	1	\$ 374.00	
7	FRONT BUMPER CLOSING ELEMENT ?	1	\$ 195.00	
8	FRONT WHEEL SPOILER - LH / RH ?	2	\$ 86.00	
9	FRONT BUMPER ADAPTOR - LH / RH ✓ / 1 pc	2	\$ 108.00	
10	RADIATOR GRILLE ✓	1	\$ 1,734.00	
11	RADIATOR GRILLE STRIKER PLATE ✓	1	\$ 153.00	
12	FRONT BUMPER TOP COVER ✓	1	\$ 126.00	
13	"CAUTION" STICKER ✓	1	\$ 25.00	
14	"A/C" STICKER ✓	1	\$ 10.00	
15	FRONT REINFORCEMENT BEAM ✓	1	\$ 882.00	
16	FRONT FOAM FILLER PIECE ✓	1	\$ 98.00	
17	FRONT BUMPER GUIDE SECTION - LH / RH ✓	2	\$ 90.00	
18	FRONT FENDER - LH / RH ✓	2	\$ 2,730.00	
19	FRONT FENDER ATTACHMENT PARTS ✓	1	\$ 47.00	
20	FRONT FENDER BRACKET - LH / RH TOP REAR	2	\$ 40.00	

SUB TOTAL SPARE PARTS
: \$ 10,225.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT FENDER BRACKET - LH / RH TOP CENTER <i>bt</i>	2	\$	124.00	
22	FRONT FENDER BRACKET - LH / RH TOP FRONT <i>bt</i>	2	\$	68.00	
23	FRONT FENDER RIVET - LH / RH <i>me</i>	12	\$	52.00	
24	FRONT FENDER BRACE - LH / RH <i>bt / 1 pc</i>	2	\$	134.00	
25	FRONT FENDER CLOSING ELEMENT - LH / RH <i>cut</i>	2	\$	84.00	
26	FRONT FENDER INSULATION - LH / RH <i>me</i>	2	\$	258.00	
27	FRONT FENDER WHEEL HOUSE SEAL - LH / RH <i>X</i>	2	\$	94.00	
28	HEADLIGHT BRACKET - LH / RH <i>com</i>	2	\$	112.00	
29	FRONT WHEEL HOUSING LINER - LH / RH <i>com</i>	2	\$	472.00	
30	FRONT WHEEL HOUSING LINER ATTACHMENT PART <i>X</i>	1	\$	67.00	
31	FRONT WHEEL COVER - LH / RH <i>me - mis</i>	2	\$	802.00	
32	LED HEADLIGHT - LH / RH <i>how ? com</i>	2	\$	11,784.00	
33	LED HEADLIGHT POWER MODULE - LH / RH <i>? com</i>	1	\$	1,808.00	
34	LED HEADLIGHT CONTROL UNIT - LH / RH <i>? com</i>	2	\$	1,327.00	
35	LED WITH HEAT SINK - LH / RH <i>X shawl</i>	2	\$	1,848.00	
36	LED HEADLIGHT SPACER - LH / RH <i>me</i>	2	\$	113.00	
37	LED HEADLIGHT MOUNTING - LH / RH <i>? com</i>	2	\$	294.00	
38	LIFT CYLINDER - LH / RH <i>com</i>	2	\$	340.00	
39	LIFT CYLINDER HOSE <i>cut</i>	1	\$	233.00	
40	LIFT CYLINDER HOSE COUPLING ELEMENT <i>me</i>	2	\$	28.00	
SUB TOTAL SPARE PARTS		:	\$	20,042.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LIFT CYLINDER HOSE T-JOINT ?	1	\$ 36.00	
42	BONNET <i>me</i>	1	\$ 2,980.00	
43	BONNET ATTACHMENT PARTS X	1	\$ 184.00	
44	BONNET HINGE - LH / RH <i>lt</i>	2	\$ 200.00	
45	BONNET GAS FILLIED STRUT <i>lt</i>	1	TBC	
46	BONNET STRIKER - LH / RH <i>lt</i>	2	\$ 260.00	
47	BONNET SOUND ABSORBER <i>de</i>	1	\$ 275.00	
48	BONNET IMPACT PROTECTION - CENTER <i>m</i>	1	\$ 38.00	
49	BONNET IMPACT PROTECTION - LH / RH <i>ne</i>	2	\$ 76.00	
50	PLENUM CHAMBER COVER - LH / RH <i>con</i>	2	\$ 106.00	
51	PLENUM CHAMBER COVER - CENTER X	2	\$ 260.00	
52	BONNET LOCK WITH MIRCO SWITCH <i>gan</i>	2	\$ 491.00	
53	BONNET BOWDEN CABLE - CENTER <i>cut</i>	1	\$ 72.00	
54	BONNET LOCK CABLE <i>cut</i>	1	\$ 92.00	
55	BONNET BOWDEN CABLE COVER <i>mis</i>	1	\$ 12.00	
56	BONNET BOWDEN CABLE <i>cut</i>	1	\$ 71.00	
57	BONNET BOWDEN CABLE <i>cut</i>	1	\$ 71.00	
58	BONNET RELEASE LEVER X	1	\$ 16.00	
59	RADIATOR AIR GUIDE - LH / RH <i>de</i>	2	\$ 118.00	
60	RADIATOR AIR GUIDE SEAL - RH <i>mis</i>	1	\$ 9.00	
SUB TOTAL SPARE PARTS		:	\$ 5,367.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.
DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR AIR GUIDE - UPPER CENTRE <i>cm</i>	1	\$ 59.00	
62	HORN - LH <i>X</i>	1	\$ 343.00	
63	HORN - RH <i>X</i>	1	\$ 185.00	
64	HORN BRACKET - LH / RH <i>bt</i>	2	\$ 80.00	
65	LOCK CARRIER <i>cm</i>	1	\$ 1,236.00	
66	OUTSIDE TEMPERATURE SENSOR <i>ne</i>	1	\$ 66.00	
67	A/C CONDENSOR <i>bt</i>	1	\$ 876.00	
68	A/C CONDENSOR SEAL RING - NEC <i>✓</i>	1	\$ 31.00	
69	REFRIFERENT LINE - A/C CONDENSOR -> CUTOFF <i>bt</i>	1	\$ 846.00	
70	REFRIFERENT LINE - A/C COMPRESSOR -> CONDENSOR <i>bt</i>	1	\$ 679.00	
71	REFRIGERENT LINE SEAL RING <i>ne</i>	1	\$ 16.00	
72	RADIATOR <i>bt</i>	1	\$ 1,177.00	
73	ADDITIONAL RADIATOR <i>bt</i>	1	\$ 987.00	
74	RADIATOR BRACKET - UPPER LH / RH <i>ne</i>	2	\$ 94.00	
75	RADIATOR BUSH - LOWER <i>new</i>	2	\$ 48.00	
76	RADIATOR SEALING STRIP - LH / RH <i>mls</i>	2	\$ 44.00	
77	RADIATOR TOP HOSE <i>twis</i>	1	\$ 177.00	
78	RADIATOR LOWER HOSE <i>?</i>	1	\$ 155.00	
79	RADIATOR RESERVOIR TANK <i>cm</i>	1	\$ 70.00	
80	RADIATOR RESERVOIR TANK CAP <i>X</i>	1	\$ 44.00	
SUB TOTAL SPARE PARTS		:	\$ 7,213.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
81	RADIATORN COOLANT <i>re /</i>	6	\$	332.00	
82	RADIATOR FAN <i>ca / plus</i>	1	\$	1,681.00	
83	AIR FITER <i>ca /</i>	1	\$	370.00	
84	AIR FILTER AIR GUIDE <i>ca /</i>	1	\$	72.00	
85	AIR FILTER AIR GUIDE COVER <i>ca /</i>	1	\$	49.00	
86	AIR FILTER AIR GUIDE <i>ca /</i>	1	\$	24.00	
87	AIR FILTER HOSE BAND CLAMP <i>re /</i>	1	\$	24.00	
88	INTAKE MANIFOLD <i>ca /</i>	1	\$	809.00	
89	CHARGE AIR COOLAR <i>bt /</i>	1	\$	890.00	
90	CHARGE AIR COOLAR SEAL <i>re /</i>	1	\$	26.00	
91	CONNECTING TUBE WITH AKF VALVE ?	1	\$	392.00	
92	CONNECTING PLATE <i>bt /</i>	1	\$	93.00	
93	ENGINE MOUNTING ?	1	\$	308.00	
94	GEARBOX MOUNTING ?	1	\$	327.00	
95	RUBBER BUSH - UPPER / LOWER ?	1	\$	127.00	
96	CONSOLE ?	1	\$	215.00	
97	WINDSCREEN <i>ca /</i>	1	\$	1,227.00	
98	WINDSCREEN RAIN SENSOR GEL FOIL <i>re /</i>	1	\$	140.00	
99	WINDSCREEN RETAINING SPRING <i>re /</i>	1	\$	26.00	
100	WINDSCREEN PRIMER <i>re /</i>	1	\$	27.00	
SUB TOTAL SPARE PARTS		:	\$	7,159.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	AIRBAG UNIT - RH <i>ACT ✓</i>	1	\$ 4,399.00	
102	SPORTS STEERING WHEEL <i>cm ✓</i>	1	\$ 2,533.00	
103	AIRBAG UNIT - LH <i>ACT ✓</i>	1	\$ 5,444.00	
104	HEAD AIRBAG UNIT - LH / RH <i>ACT ✓</i>	2	\$ 3,612.00	
105	HEAD AIRBAG UNIT GUIDE - LH / RH <i>X</i>	2	\$ 62.00	
106	AIRBAG CONTROL UNIT <i>ACT ✓</i>	1	\$ 1,804.00	
107	CRASH SENSOR FOR AIRBAG <i>ACT ✓</i>	2	\$ 971.00	
108	DASHBOARD WITH AIR DUCT <i>cm ✓</i>	1	\$ 5,285.00	
109	ROOF LINER <i>ACT ✓</i>	1	\$ 2,505.00	
110	SUNVISOR WITH MIRROR - LH <i>X</i>	1	\$ 515.00	
111	RETAINER FOR SUN VISOR <i>X</i>	2	\$ 50.00	
112	SUNVISOR - RH <i>X</i>	1	\$ 515.00	
113	GRAB HANDLE - FRONT LH / RH <i>?</i>	2	\$ 367.00	
114	A-PILLAR TRIM - LH / RH <i>?</i>	2	\$ 398.00	
115	B-PILLAR TRIM - LH / RH UPPER <i>?</i>	2	\$ 456.00	
116	C-PILLAR TRIM - LH / RH <i>?</i>	2	\$ 230.00	
117	FRONT SEAT BELT - LH / RH <i>ACT ✓</i>	2	\$ 2,468.00	
118	WASH WATER RESERVOIR <i>de ✓</i>	1	\$ 222.00	
119	WATER LEVEL SWITCH <i>X</i>	1	\$ 56.00	
120	WATER LEVEL SWITCH SEAL RING <i>new ✓</i>	1	\$ 28.00	
SUB TOTAL SPARE PARTS		:	\$ 31,920.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8946 P.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
121	WINDSCREEN WASHER PUMP X	1	\$	147.00
122	WINDSCREEN WASHER PUMP SEAL X	1	\$	10.00
123	WASH WATER RESERVOIR STRAINER X	1	\$	26.00
124	WASH WATER RESERVOIR CAP X	1	\$	26.00
125	FRONT DOOR COVER - LH / RH X	2	\$	608.00
126	SEATBELT ADJUSTER - LH / RH ?	2	\$	414.00
127	BASE ENGINE ?	1	\$	23,733.00
128	NEEDLE BEARING ?	1	\$	30.00
129	7 SPEED DUAL CLUTCH GEARBOX ?	1	\$	20,563.00
130	TRANSMISSION FLUID ?	6		TBC
131	ENGINE COOLANT ?	6	\$	491.00
132	FRONT WINDSCREEN SEALANT m /	S/N	\$	200.00
133	METAL FILLER POWDER m /	S/N	\$	280.00
134	STONE CHIP m /	S/N	\$	180.00
135	CAVITY WAX m /	S/N	\$	140.00
136	FRONT NO PLATE b /	S/N	\$	60.00
TOTAL SPARE PARTS		:	\$	128,834.00
TOTAL LABOUR CHARGES		:	\$	29,244.00
GRAND TOTAL		:	\$	158,078.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasna - Hp 50010068
: 11/07/24
: 22 days
: EXCESS: THA
: Repair
: Repry by paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	594D
Vehicle Details	
Vehicle No.:	SMS8946P
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jul 2024
Vehicle Make:	AUDI
Vehicle Model:	Q2 1.0 TFSI S TRONIC
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	CHZC33098
Chassis No.:	WAUZZZGA8KA083090
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,669.00
Original Registration Date:	19 Mar 2020
First Registration Date:	19 Mar 2020
Transfer Count:	0
Actual ARF Paid:	\$25,137.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Mar 2030
PARF Rebate Amount:	\$18,852.00
Intended COE Rebate Details	
COE Expiry Date:	18 Mar 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,210.00
COE Rebate Amount:	\$17,736.00
Total Rebate Amount:	\$36,588.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 12 Jul 2024

OK



Audi Q2 1.0A TFSI S-tronic

\$102,800

Instalment \$1,223/mth

PREMIUM AD

Shortlist

Get Warranty

Loan Calculator

Overview Financial Photo Research

Depreciation	\$15,840 / year
Reg. Date	23-Mar-2020 (5yrs 8mths 10days COE left)
Manufactured	2019
Mileage	<u>77,434 km</u> (18k / year)
Transmission	Auto
Engine Cap	999 cc
Road Tax	\$392 / year
Power	85.0 kW (113 bhp) View specs of the Audi Q2 (2017)
Curb Weight	<u>1,315 kg</u>
COE	\$31,210
OMV	\$23,674
ARF	\$25,144
Dereg Value	\$36,635 as of today