

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07113

Vehicle Insured : SMX1405D
Accident Date : 05-Jul-2024

Date : 08-Jul-2024

Our Ref : 024134 (AUTO & GEN) / CHAN

PAGE : 1

TAN CHAI HWA
57 HILLVIEW AVENUE
#06-04
Singapore 669568

Not Withheld
Repairing B4 painting
4 days

\$ 8568.97

ESTIMATED COST OF REPAIR FOR BMW 216i SLB4461Z

1 pc	Front bumper fascia	<i>nd/cm</i>	1,187.80	✓
1 pc	Front bumper logo	<i>na</i>	115.50	✓
1 pc	Front o/s bumper side grille	<i>cm</i>	140.72	✓
1 pc	O/s bumper side grille garnish	<i>B</i>	85.72	✓
1 pc	O/s side grille parking sensor	<i>sn</i>	285.50	X
1 pc	O/s side grille top garnish	<i>sn</i>	81.55	X
1 pc	O/s bumper parking sensor-out	<i>sn</i>	265.55	X
1 pc	Front o/s bumper side retainer	<i>DIY</i>	187.00	✓
1 pc	O/s front grille	<i>sn</i>	359.60	X
1 pc	O/s headlamp	<i>Bn</i>	2,650.20	✓
1 pc	O/s headlamp panel	<i>Bu</i>	161.85	✓
1 pc	O/s headlamp ballast	<i>sn</i>	1,157.15	X
1 pc	O/s headlamp control module	<i>sn</i>	365.10	X
1 pc	Bonnet	<i>Bn</i>	1,496.80	✓
1 pc	Front o/s fender	<i>R</i>	708.90	X
1 pc	Front o/s fender inner shield	<i>sn</i>	165.10	X
			9,414.04	
		Less 5% :	470.70	

1 pc Front bumper rivet (set)

8,943.34
na 30.00 sn ✓

To rewire damaged parts and refocus headlamp beam.

180.00 2d

To putty and spray replaced parts

800.00 66d

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

1210
7358.98

(025.58

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMX1405D

Page : 2

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500/
700.00

Total : S\$10,653.34

Singapore Dollars Ten Thousand Six Hundred and
Fifty Three and Cents Thirty Four Only

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMX1405D (AUTO & GEN)

Date : 23-07-2024

Accident Date : 05-07-2024

Our Ref : 024134 / CHAN

TAN CHAI HWA

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR BMW 216I SLB4461Z

1 PC	FRONT BUMPER SPONGE	CM	\$195.25	✓
1 PC	FRONT BUMPER REINFORCEMENT	B	\$940.20	✓
1 PC	FRONT W/S GLASS WASHER TANK	nd	\$290.15	✓
1 PC	FRONT O/S BUMPER INNER PARTS	CM	\$295.10	✓
			<u>\$1,720.70</u>	
LESS 5%			\$86.04	
			<u>\$1,634.66</u>	

Singapore Dollars One Thousand Six Hundred Thirty Four And Cents Sixty Six Only

P 5724.31
S.P 1634.66
30.00
82 1180.00
L
8568.97
→

