

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

Not Authorised
12/6/24
Whight. All in
1/5 # 9900
Fly

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street

IOB Building #04-05

Singapore 049711

Tel: 63476100

Fax: 62244174 , 62257743

Attn: Motor Claim Department \ INDIA
INTERNATIONAL

Your Ref No: TP 0624-8071

Claim Type: Third Party

Accident Date: 08 June 2024

TP Veh Reg No: SMN6830D

Estimate No: EST1511378

Date: 08 Jun 2024

Veh Reg No: SMP5527B

Make/Model: AUDI A4 SEDAN 2.0 TFSI
S TRONIC (NAV)

Chassis No: WAUZZZF4XKA055268

Engine No: CVK079066

Reg. Date: 30 Sep 2019

Estimate Repair Cost to Vehicle No: SMP5527B

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 REAR BUMPER-	1,910.00	1 PC	1,910.00	✓
2 REAR BUMPER SIDE RETAINERS - LH/RH- <i>11</i>	50.85	2 PC	101.70	✓
3 REAR BUMPER CLIPS-	83.25	1 SET	83.25	✓
4 REAR BUMPER REINFORCEMENT- <i>men</i>	650.65	1 PC	650.65	✓
5 REAR BUMPER OUTER GARNISH <i>to in</i>	280.30	1 PC	280.30	✓
6 REAR BUMPER LOWER (BLACK) <i>de</i>	196.50	1 PC	196.50	✓
7 REAR EXHAUST CHROME - LH <i>cut / 24</i>	398.25	1 PC	398.25	✓
8 REAR BUMPER REFLECTOR - LH <i>SCR</i>	29.25	1 PC	29.25	✓
9 REAR BUMPER SENSOR-	208.85	2 PC	417.70	✓
10 REAR BUMPER SENSOR WIRE <i>SU</i>	569.15	1 PC	569.15	✓
11 REAR BOOT- <i>SS</i>	3,919.65	1 PC	3,919.65	✓
12 REAR BOOT HINGE - LH/RH <i>11</i>	190.75	2 PC	381.50	✓
13 REAR BOOT RUBBER- <i>11</i>	144.45	1 PC	144.45	✓
14 REAR BOOT A4 WORDINGS <i>men</i>	93.65	1 PC	93.65	✓
15 REAR BOOT AUDI LOGO <i>SU</i>	105.85	1 PC	105.85	✓
16 REAR BOOT LAMP- LH <i>SU</i>	689.05	1 PC	689.05	✓
17 REAR TAILLAMP - LH- <i>BNO</i>	910.95	1 PC	910.95	✓
18 TAILLAMP LOWER RETAINER - LH <i>11</i>	18.40	1 PC	18.40	✓
19 FRONT SEATBELT - LH/RH <i>11</i>	829.60	2 PC	1,659.20	✓
20 FRONT SEATBELT BUCKLE - LH/RH <i>SU</i>	287.45	2 PC	574.90	✓
21 FRONT SEATBELT ADJUSTER - LH/RH <i>SU</i>	181.20	2 PC	362.40	✓
22 BATTERY OVERLOAD PROTECTION PYROFUSE <i>11</i>	121.70	1 PC	121.70	✓
23 AIRBAG CONTROL UNIT <i>SU</i>	1,996.30	1 PC	1,996.30	✓
24 REAR END PANEL- <i>SS / 11</i>	995.60	1 PC	995.60	✓

(103)

16,610.35
Less 5% -830.46
15,779.89

Special Net

25 REAR NUMBER PLATE WITH CASING- <i>SU</i>	35.00	1 PC	35.00	✓
				35.00

Labour

26 TO KNOCK OUT DENTS, ON REAR LH FENDER, REMOVE, REPLACE ACCIDENT PARTS-	1,000.00	1 JOB	1,000.00	800
27 TO RESPRAY PAINT ON ACCIDENT PORTIONS-	1,100.00	1 JOB	1,100.00	800
28 TO CHECK WIRING-	50.00	1 JOB	50.00	24
29 TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR	180.00	1 PC	180.00	60
30 TO TUFF-KOTE	90.00	1 PC	90.00	40
31 TO REMOVE, REPLACE REAR BUMPER SENSOR	80.00	1 PC	80.00	✓
32 TO RESET CHECKLIGHT, REPROGRAM & CALIBRATE AIRBAG CONTROL UNIT	500.00	1 PC	500.00	300

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

33	TO REMOVE, REPLACE FRONT SEATBELT, AIRBAG CONTROL UNIT & RELATED PARTS	500.00	1 PC	500.00	200	3,500.00
----	---	--------	------	--------	-----	----------

Total	19,314.89
Add GST @ 9%	1,738.34
Total Amount Payable SGD	21,053.23

SINGAPORE DOLLAR TWENTY ONE THOUSAND FIFTY THREE AND CENTS TWENTY THREE ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 11261-70
10%
10135.53
2300
- 12436.53
202
9948

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE