


SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 03685592
Estimator Telephone Number : 68682823
Accident Reporting Number : 68682872

Date Generated : 09/07/2024

User ID : choonhwee03

Section A - Accident Details	
Registration Number	SG5874A
Case Reference Number	BU5/07/24/5015
Registration Date	11/16/2017
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	Chow Nyuk Fatt
Type of Accident	Head to Rear
Accident Date and Time	7/8/2024 11:00 PM
Accident Reported Date and Time	7/8/2024 4:32 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5874A - REAR PORTION SLZ4581J (TP) - INSURED WITH CHINA TAIPING
Prepared Date and Time	7/9/2024 1:58 PM
Chassis Number	WMAA95ZZ9G7003558
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,650.00	\$0.00
Total Spray Cost	\$942.00	\$0.00
Total Spare Part Cost	\$8,865.47	\$0.00
Total Other Cost	\$500.00	\$0.00
TOTAL COST	\$12,957.47	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	09/07/2024 3:09 PM	
Signature		
Remarks		

Steve (LKK)
10/7/24, 3:27 PM

P/R

4 djs

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park EA, Singapore 757105
FAX Number: 63965502
Estimator Telephone Number: 69962823
Accident Reporting Number: 69962872

Date Generated : 09/07/2024

User ID : choonhwee93

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,650.00 53773	1590
Total Labour	\$2,650.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$942.00	864
Total Spray Painting & Panel Beating	\$942.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
CHASSIS ALIGNMENT	\$500.00	?
Total Other Costs	\$500.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013481	Body	124-2-2-009-011	FRP REAR BUMPER	1.00	\$1,875.00	10.00	\$1,687.50	Replace / RR	
6013482	Body	124-2-2-009-012	O/S FRP REAR LAMP	1.00	\$975.00	10.00	\$877.50	Replace / BR	
		G20.04.01.12	BUMPER STEEL	1.00	\$625.00	10.00	\$562.50	Replace / DD	
	Body	LRFC-808022-RED	REFLECTOR-BUMPER	1.00	\$36.00	10.00	\$32.40	Replace / BR	
6010298			STOP LAMP LED	1.00	\$1,141.70	10.00	\$1,027.53	Replace ?	
6010299			SIGNAL LAMP LED REAR	1.00	\$1,274.10	10.00	\$1,146.69	Replace ?	
6012635	VE		REAR LAMP BULB (A95 MAN)	1.00	\$245.00	10.00	\$220.50	Replace / RR	
6012636	VE		REVERSE LAMP BULB (A95 MAN)	1.00	\$235.00	10.00	\$211.50	Replace / RR	
		36-15201-5208	TAIL PIPE	1.00	\$5,582.35	10.00	\$5,024.12	Replace / DD	
6013423	Body	155-2-2-009007	FRP REAR ENGINE DOOR COMPLETED	1.00	\$3,750.00	100.00	\$0.00	Repair X R	
		124-2-2-001-034	RADIATOR GRILL	1.00	\$1,700.00	100.00	\$0.00	Repair X R	
			SMRT STICKERS	1.00	\$75.00	0.00	\$75.00	Replace / RR	
			60 KM/H STICKER	1.00	\$5.00	0.00	\$5.00	Replace / RR	
		OSTK-0158-00	STICKER REFLECTOR RIGHT	1.00	\$137.50	10.00	\$123.75	Replace X	
		81-96210-0602	RUBBER TO METAL PAD	1.00	\$87.85	0.00	\$87.85	Replace / TR	
Total					\$17,744.50		\$11,081.84		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									