



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/08/2024

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5874A
Case Reference Number	BUS/07/24/5015
Registration Date	16/11/2017
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	Chow Nyuk Fatt
Type of Accident	Head to Rear
Accident Date and Time	6/7/2024 11:00 PM
Accident Reported Date and Time	8/7/2024 4:32 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24121807
Special Instruction to ARC,if any	SG5874A - REAR PORTION SLZ4581J (TP) - INSURED WITH CHINA TAIPING
Prepared Date and Time	9/7/2024 1:58 PM
Chassis Number	WMAA95ZZ9G7003556
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,650.00	\$1,590.00
Total Spray Cost	\$942.00	\$864.00
Total Spare Part Cost	\$12,086.03	\$10,247.66
Total Other Cost	\$1,000.00	\$700.00
TOTAL COST	\$16,678.03	\$13,401.66
Lump Sum Total	\$0.00	\$13,400.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Jeong Choon Hwee	STEVE CHEN (LKK)
ARC / Surveyor Sign Off Date	09/07/2024 3:09 PM	11/07/2024 11:13 AM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/08/2024

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$2,650.00				\$1,590.00 ✓		
Total Labour			\$2,650.00				\$1,590.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO PUTTY & RESPRAY			\$942.00				\$864.00 ✓		
Total Spray Painting & Panel Beating			\$942.00				\$864.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TOWING CHARGE			\$500.00				\$500.00 / Nec		
CHASSIS ALIGNMENT			\$500.00				\$200.00 ✓		
Total Other Costs			\$1,000.00				\$700.00		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013481	Body	124-2-2-009-011	FRP REAR BUMPER	1.00	\$1,875.00	10.00	\$1,687.50	Replace	Replace
6013482	Body	124-2-2-009-012	O/S FRP REAR LAMP	1.00	\$975.00	10.00	\$877.50	Replace	Replace
		G20.04.01.12	BUMPER STEEL	1.00	\$625.00	10.00	\$562.50	Replace	Replace
	Body	LRFC-808022-RED	REFLECTOR-BUMPER	1.00	\$36.00	10.00	\$32.40	Replace	Replace
6010298			STOP LAMP LED	0.00	\$1,141.70	0.00	\$0.00	Replace	Check
6010299			SIGNAL LAMP LED REAR	0.00	\$1,274.10	0.00	\$0.00	Replace	Check
6012635	VE		REAR LAMP BULB (A95 MAN)	1.00	\$245.00	10.00	\$220.50	Replace	Replace
6012636	VE		REVERSE LAMP BULB (A95 MAN)	1.00	\$235.00	10.00	\$211.50	Replace	Replace
		36-15201-5208	TAIL PIPE	1.00	\$5,582.35	10.00	\$5,024.12	Replace	Replace
6013423	Body	155-2-2-009007	FRP REAR ENGINE DOOR COMPLETED	1.00	\$3,750.00	100.00	\$0.00	Repair	Repair
		124-2-2-001-034	RADIATOR GRILL	1.00	\$1,700.00	100.00	\$0.00	Repair	Repair
			SMRT STICKERS	1.00	\$75.00	0.00	\$75.00	Replace	Replace
			60 KM/H STICKER	1.00	\$5.00	0.00	\$5.00	Replace	Replace
		OSTK-0158-00	STICKER REFLECTOR RIGHT	0.00	\$137.50	0.00	\$0.00	Replace	Not Given
		81-96210-0602	RUBBER TO METAL PAD	1.00	\$87.85	10.00	\$79.07	Replace	Replace
Total					\$17,744.50		\$8,775.09		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		36-15201-5207	REAR EXHAUST PIPE	1.00	\$3,357.75	10.00	\$3,021.98	Replace	Replace / BT
6013766			COVER,RADIATOR:BOT TOM,MAN A95 E5 ONLY	1.00	\$1,125.00	10.00	\$1,012.50	Replace	Replace / BT
Total					4,482.75		4,034.48		

- Supplementary

✓ BR  
✓ BR  
✓ DD  
✓ BR  
XNN  
XNN  
✓ BR  
✓ DD  
XR  
XR  
✓ NEC  
✓ NEC  
XNN  
✓ TN

- Supplementary  
"