

~~1890~~

~~769~~ 769

1.

146,

76

285

100

~~1090~~

x 96 .

+
+
t.
+
-
+
+
+
+
+
✓
✓
✓

TO : INCOME MOTOR CLAIMS DEPTS
 VEHICLE NO : SLK7286X
 MODEL : VOLVO V40
 DATE OF ACCIDENT : 08.07.2024
 TIME OF ACCIDENT : 08:00 HOURS

22	TAILGATE WEATHER STRIP <i>new</i>	1	\$ 238.00	\$ 238.00	+
23	REAR END PANEL <i>Repair</i>	1	\$ 2,280.00	\$ 2,280.00	+
24	REAR END PANEL TOP COVER GARNISH <i>new</i>	1	\$ 570.00	\$ 570.00	+
25	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 568.10	\$ 568.10	+
26	RESR TOOLS TRAY <i>New</i>	1	\$ 665.00	\$ 665.00	+
27	REAR EXHAUST INSULATOR <i>Replaced</i>	1	\$ 380.00	\$ 380.00	+

5238 TOTAL PRICE \$ 24,263.30
 4714.20 LESS 10% \$ 2,426.33
 SUB TOTAL PRICE \$ 21,836.97

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
3	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
4	TAILGATE SEALANT	1	\$ 80.00	\$ 80.00	+
5	TAILGATE INNER TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
6	TAILGATE WINDSCREEN GLASS SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	TAILGATE WINDSCREEN GLASS INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	+
8	TAILGATE WINDSCREEN SOLAR FILM <i>new</i>	1	\$ 200.00	\$ 200.00	+
9	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
10	REAR END PANEL SEALANT	1	\$ 150.00	\$ 150.00	X NN
11	REAR END PANEL TOP GARNISH CLIP <i>new</i>	1	\$ 40.00	\$ 40.00	+

30 TOTAL \$ 920.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,000.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	600
3	TUFF COAT	\$ 250.00	40

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLK7286X**
 MODEL : **VOLVO V40**
 DATE OF ACCIDENT : 08.07.2024
 TIME OF ACCIDENT : 08:00 HOURS

4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	30
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	50
7	TRANSFER TAILGATE MECHANISM	\$ 100.00	X
8	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
9	REMOVE AND REFIX TAIL GATE WINDSCREEN	\$ 150.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	X 150

TOTAL \$ 5,750.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 22,756.97
 TOTAL LABOUR COST : \$ 5,750.00
 TOTAL REPAIR COST : \$ 28,506.97

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian King
 2/8 10/07/24.
 05 Days.

total. 6264.20

2/5! SK

SK

1500