

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24060005/KPA3Q2
Date: 15/07/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0003403_02
Claimant Vehicle No : SMP407Y Insured Vehicle No : SNN638X
Date of Loss: 01/06/2024 Nature of Claim: TP Claim No: MFL2024D0007223

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMP407Y
Make & Model: TOYOTA COROLLA ALTIS, 1.6 Elegance (A) Engine No: 1ZR0E13112V
Reg. Date: 06/09/2019 (Man. Year: 2016) Chassis No: MR053REH604599197
Colour: Metallic Black Odometer: 337245 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,478.22	0.00	5,478.22	100.00
Miscellaneous Items	237.00	12.00	225.00	94.94
Labour	1,480.00	1,000.00	480.00	32.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,195.22	1,012.00	6,183.22	85.94
+ GST 9.00/9.00% (S\$)	647.57	91.08	556.49	85.94
Nett Amount (S\$)	7,842.79	1,103.08	6,739.71	85.94
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
(S\$)		1,343.08		
Liabe Amount (80.00%) (S\$)		1,074.46		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		1,101.71		
Global Sum Settlement (S\$)		1,100.00		

INSPECTION

Date of Assignment: 10/06/2024 Present Location: City Auto Pte Ltd (HQ)
City Auto Pte Ltd (HQ)
Date Inspected: 11/06/2024 Inspected At: 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,
Singapore 575722
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jun 2025)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP407Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear RH door	Repair	1,864.60 FL	*- FL
2	1		*Rear RH fender	Repair	1,715.00 FL	*- FL
3	1		*Rear RH wheel rim	Serviceable	2,731.50 FL	*- FL
4	1		*Rear bumper	Repair	828.80 FL	*- FL
5	1		*Rear bumper retainer RH	Serviceable	164.40 FL	*- FL
Sub Total (\$\$)						7,304.30 0.00
- List Item Discount on L Items 25.00/25.00% (\$\$)						1,826.08 0.00
Total Parts (\$\$)						5,478.22 0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Rear RH wheel tire (Serviceable)	225.00	0.00
2	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			237.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts.	New	600.00	400.00
2	Spray painting on affected and replace parts.	New	800.00	600.00
3	Computerized wheel alignment.	New	80.00	0.00
Gross Labour Cost (\$\$)			1,480.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >