

Huey Yon (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Tuesday, 9 July 2024 5:18 PM
To: Venda Claims Dept
Cc: Huey Yon (LKKAUTO)
Subject: Re: Accident Involving GBF1841C with SHC4806E on 08/06/2024

Hi Pei Jin,

As per our message,

We will be advising our principal a cost of repair L/S of \$4,400.00 /- with 06 days of repair before GST, subject to their approval.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth. Print only when necessary.

From: Venda Claims Dept <claims@vendaengrg.com.sg>
Sent: Monday, 8 July 2024 6:43 pm
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: Re: Accident Involving GBF1841C with SHC4806E on 08/06/2024

Hi Rasul,

Please find attached supplementary estimates, damage parts & after repair photos for your finalize.
Thank you.

--

Pei Jin

Venda Engineering & Trading Pte Ltd
No 8 Tuas Avenue 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel : 8126 8587



Virus-free. www.avast.com

On Mon, Jun 10, 2024 at 7:47 PM Venda Claims Dept <claims@vendaengrg.com.sg> wrote:
Dear Officer In charge,

We are the repairer of vehicle GBF1841C. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) working days upon receipt of this email. Enclosed Accident Statement and LTA search fee for your attention please.

Kindly inform the vehicle already in our premises located at No. 8 Tuas Avenue 18, Singapore 638892.

Please call 8126 8587 for vehicle survey.

--

Pei Jin

Venda Engineering & Trading Pte Ltd

No 8 Tuas Avenue 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel : 8126 8587



Virus-free. www.avast.com