

(08/11/13) Wef
ASS. REC. BY:

REF: CS/SMR24070186/R4p3

2004

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To inspect Vehicle No: SLS 3875G
at Workshop m/s BORNO
of PANDAN CRESCENT
Insured: SMR
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bel. or Market Value: 67K
IDAC Accident Report: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLS 3875G Yr Regn: 2017 / 86P
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: TOYOTA PRIUS HYBRID 1.8 CVT c.c 1798
Colour: WHITE AC: Insured / Std / NI / NA
Sp. Reading: 56996 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: 3TDKB3FU 303571091
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R: 195/65R15

BS/DUN/EXNOVA/GY/FS/LZA/MIC/OHTSU/PIR/SUM/
TOYO/YOKO or

Front		Rear	
R/Bal.	<u>6</u> mm	R/Bal.	<u>6</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>6</u> mm
D.O.A.	<u>08/07/24</u>	D.O.I.	<u>10/07/24</u>
Survey held at <u>P.C</u>			

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 46K

Date/Time, File Pass to?

☐
☐

: Prel. Report

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) S+RS \$ _____

) Photos _____

) Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



Borneo Motors



TOYOTA

cape
Reg No. : 196700086Z
Reg No. : MR-8500000-9
2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 10/07/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q2	21/09/2017	SLS3875E	0	31473	67/TP/SLS3875E	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU303571091		2ZRS089449	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP-SHB5785E ACC DATE:08/07/2024 DRIVE IN:09/07/2024 DATE-IN:09/07/2024 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:						50 100.00
2	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR						198.00
3	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST						198.00
4	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT GARNIS H AND TAILGATE COMPONENTS TO ASSIST REPAIR						396.00
5	B	BP-ECU2 TO RESET ECU AND REPROGRAMME						198.00
6	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS						1584 2772.00
7	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS						1312 2624.00
8	1	SPC507-47006 16 BACK SENSOR 070 WHITE PEARL ?			1.00	251.40		251.40
9	2	U52159-47913 COVER, RR BUMPER em			1.00	680.60		680.60
10	3	U52576-47040 RETAINER, RR BUMPER ?			1.00	177.50		177.50
11	4	U52575-47040 RETAINER, RR BUMPER ?			1.00	180.50		180.50
12	5	U52453-47010 GUARD, RR BUMPER, de			1.00	884.60		884.60
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due	



Borneo Motors



TOYOTA

Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No. 0				
			Document Date 10/07/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	21/09/2017	SLS3875E	0	31473	67/TP/SLS3875E
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU303571091		2ZRS089449	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
13	6	U52169-47020 COVER, RR BUMPER, <i>ant</i>	1.00	21.40		21.40	
14	7	K52161-0K040 PIECE, RR BUMPER <i>gan</i>	10.00	5.80		58.00	
15	8	U52023-47030 REINFORCEMENT	1.00	512.40		512.40	
16	9	U58307-47090 PANEL SUB-ASSY, BODY <i>repair X?</i>	1.00	1000.10		1000.10	
17	0	U66259-47010 COVER, RR BODY <i>X</i>	1.00	318.60		318.60	
18	1	U76801-47110 A1 GARNISH SUB-ASSY. <i>repair</i>	1.00	1283.40		1283.40	
19	2	U75403-48010 EMBLEM SUB-ASSY, <i>an</i>	1.00	99.40		99.40	
20	3	U75441-47130 PLATE, LUGGAGE COMPT <i>an</i>	1.00	75.70		75.70	
21	4	U75442-47130 PLATE, LUGGAGE COMPT <i>an</i>	1.00	75.70		75.70	
22	5	U89997-30100 ANTENNA, ELECTRICAL <i>?</i>	1.00	100.00		100.00	
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <i>Ramal</i> <i>Hp 900w68</i> <i>4 days</i> <i>10/07/24</i> <i>Reg 68 paint</i>							
For & on behalf of		Acknowledged by Repairer		Customer's Signature		Charge Summary	
Borneo Motors (Singapore) Pte Ltd		Signature:				Total 12,205.30	
Date:		Please acknowledge receipt of vehicle				GST 9.00% 1,098.48	
				Parts 5,719.30			
				Labour 6,486.00			
				Sublet 0.00			
				Lubrication/Fluid 0.00		Less 0.00	
				Others 0.00		Amount Due 13,303.78	

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SLS3875E
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jul 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	2ZRS089449
Chassis No.:	JTDKB3FU303571091
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$31,008.00
Original Registration Date:	21 Sep 2017
First Registration Date:	21 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$5,412.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Sep 2027
PARF Rebate Amount:	\$3,517.00
Intended COE Rebate Details	
COE Expiry Date:	20 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$17,142.00
Total Rebate Amount:	\$20,659.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 11 Jul 2024

OK