

ONE GARAGE

8 KAKI BUKIT AVENUE 4 #03-33 PREMIER@KAKI BUKIT
SINGAPORE 415875
TEL: 96311088

VEHICLE NO	: SLA8171P (2016)	TP/NC Hui Rong
VEHICLE MODEL	: HONDA VEZEL	
CHASSIS NO	: RU11109542	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 38.50	\$ 77.00
2	REAR BUMPER <i>crack</i>	1	\$ 880.00	\$ 880.00
3	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 23.50	\$ 47.00
4	REAR BUMPER REFLECTOR <i>LH crack</i>	2	\$ 141.10	\$ 282.20
5	REAR SIDE BUMPER <i>LH torn</i>	2	\$ 195.00	\$ 390.00
6	REAR END PANEL <i>Dented</i>	1	\$ 585.00	\$ 585.00
7	REAR END PANEL TOP GARNISH <i>crack</i>	1	\$ 98.40	\$ 98.40
8	REAR END PANEL BUZZER <i>crack</i>	1	\$ 85.20	\$ 85.20
9	REAR END PANEL ANTENNA SENSOR <i>new</i>	1	\$ 60.10	\$ 60.10
10	TAILLAMP <i>LH cut</i>	2	\$ 474.60	\$ 949.20
11	TAILLAMP PANEL <i>new</i>	2	\$ 135.50	\$ 271.00
12	TAILGATE <i>Dented</i>	1	\$ 1,100.00	\$ 1,100.00
13	TAILGATE LOCK <i>crack</i>	1	\$ 182.50	\$ 182.50
14	TAILGATE LOCK STRIKER <i>new</i>	1	\$ 24.70	\$ 24.70
15	TAILGATE WEATHERSTRIPE <i>cut</i>	1	\$ 189.10	\$ 189.10
16	TAILGATE LAMP <i>new</i>	2	\$ 413.20	\$ 826.40
17	TAILGATE LAMP RUBBER GASKET <i>new</i>	2	\$ 38.50	\$ 77.00
18	TAILGATE OUTER GARNISH <i>new</i>	1	\$ 325.00	\$ 325.00
19	TAILGATE INNER TRIM BOARD <i>new</i>	1	\$ 285.60	\$ 285.60
20	TAILGATE INNER HANDLE POCKET <i>new</i>	1	\$ 27.50	\$ 27.50
21	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 120.00	\$ 120.00
22	HONDA LOGO <i>new</i>	1	\$ 30.40	\$ 30.40
23	VEZEL EMBLEM <i>new</i>	1	\$ 30.40	\$ 30.40
24	SPARE TYRE PANEL <i>Pair</i>	1	\$ 45.90	\$ 45.90
25	SPARE TYRE PANEL TOP COVER <i>new</i>	1	\$ 1,130.00	\$ 1,130.00
26	SPARE TYRE PANEL TOOLS TRAY SPONGE <i>crack</i>	1	\$ 306.60	\$ 306.60
27	SPARE TYRE PANEL UNDERCOVER <i>new</i>	1	\$ 285.40	\$ 285.40
28	SPARE TYRE UNDER JACK PANEL <i>new</i>	1	\$ 225.10	\$ 225.10
29	REAR FENDER ARC GARNISH	1	\$ 138.00	\$ 138.00
30	REAR FENDER INNER SHIELD	2	\$ 196.00	\$ 392.00
31	REAR FENDER INNER TRIM BOARD	2	\$ 147.50	\$ 295.00
		2	\$ 305.20	\$ 610.40

TOTAL PRICE: \$ 10,341.70
LESS 20% \$ 2,068.34
SUB TOTAL PRICE: \$ 8,273.36

438220

3505.76

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>3 new</i>	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER <i>new</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	REVERSE SENSOR (SET) <i>new</i>	1	\$ 280.00	\$ 280.00
5	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
6	TAILGATE OUTER GARNISH CLIPS (SET) <i>new</i>	1	\$ 25.00	\$ 25.00
7	TAILGATE INNER TRIM BOARD CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
8	TAILGATE GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
9	SPARE TYRE PANEL UNDERCOVER CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
10	SPARE TYRE PANEL INSULATION PAD <i>new</i>	1	\$ 250.00	\$ 250.00
12	REAR FENDER ARC GARNISH CLIPS (SET) <i>new</i>	2	\$ 30.00	\$ 60.00
13	REAR FENDER INNER SHIELD CLIPS (SET) <i>new</i>	2	\$ 30.00	\$ 60.00
14	REAR FENDER INNER TRIM BOARD CLIPS (SET) <i>new</i>	2	\$ 30.00	\$ 60.00
15	REAR CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00
			TOTAL :	\$ 1,445.00

310

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,800.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	700	
3	WIRING CHECK	\$ 50.00	30	
4	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
5	TO REMOVE REAR CAMERA	\$ 100.00	50	
6	TO REMOVE VIDEO RECORDER	\$ 100.00	50	
7	TO REMOVE UPHOLSTERY AND REAR SEAT	\$ 380.00	60	
8	TO SPRAY TUFF COAT	\$ 150.00	60	
9	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	
10	TO REPLACE TAILGATE GLASS	\$ 180.00	120	
		TOTAL \$	4,610.00	

ESTIMATE REPORT

TOTAL PARTS COST: \$ 9,718.36

TOTAL LABOUR COST: \$ 4,610.00

TOTAL REPAIR COST: \$ 14,328.36

1980

total: 5795.76

4/s: 4.61k

06 Days

4.61k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: