



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)
Email: motor@wahhong.sg
(199806235M)

Vehicle No. SMG1724Y-MITSUBISHI-ECLIPSE 1.5

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear lower windscreen moulding <i>ne</i>		50.00	
1	Boot lid <i>bt</i>		1100.00	
1	Boot lid center garnish <i>? xan</i>		590.00	X
1	Boot lid emblem "ECLIPSE CROSS" <i>? xan</i>		105.00	X
1	Boot lid emblem "MIVEC TECHNOLOGY" <i>? xan</i>		110.00	X
1	Boot lid inner weatherstrip <i>ne</i>		250.00	
1	Rear Tail lamp LH <i>? xan</i>		850.00	X
1	Rear bumper <i>de</i> <i>x ne</i>		750.00	
2	Rear bumper side retainer RH/LH @2\$38 <i>(1pc)</i>		76.00	38
1	Rear bumper lower garnish <i>cut</i>		210.00	
1	Rear bumper lower garnish silver cover LH <i>sc</i>		140.00	
1	Rear bumper reflector lamp LH <i>? xan</i>		160.00	
2	Rear bumper parking sensor @2\$350 <i>? xan</i>		700.00	X
1	Rear bumper inner panel LH (Repair refer to labour)		0.00	
1	Rear fender LH (Repair refer to labour)		0.00	
			2698	
			5091.00	
			10% 509.10	
			5600.10	
			2428.20	
SPECIAL NETT ITEMS				
1	Rear top windscreen sealant <i>ne</i>		50.00	
1	Rear lower windscreen sealant <i>ne</i>		50.00	
1	Rear bumper clip <i>ne</i>		35.00	30
Total Parts			5735.10	



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Vehicle No. SMG1724Y-MITSUBISHI-ECLIPSE 1.5

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	840.00	600 700
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	400 600
3	Sundries	40.00	20
4	To perform anti-rust treatment on affected areas	15.00	
5	To carried out remove and replace rear windscreen (Top)	100.00	
6	To carried out remove and replace rear windscreen (Lower)	100.00	
Labour Total :		1895.00	
TOTAL (PARTS & LABOUR):		5973.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rane

HP 90010068

6 days

P/P

11/07/24

Resy b & paint



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMG1724Y-MITSUBISHI-ECLIPSE 1.5

Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Rear bumper sponge LH <i>rw</i>		75.00	
1	Rear bumper lower garnish rivet@3*\$6 <i>rw</i>		18.00	
			93.00	
			-10%	
			-9.30	
			83.70	
	<u>SPECIAL NETT ITEMS</u>			
	<u>LABOUR</u>			
		Total Parts	83.70	

2428.20
130.00
1535.00
83.70
4176.90 6 days