

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY@KAKI BUKIT

SINGAPORE 417883

TEL: 92327457

TO	: NTUC INCOME		
VEHICLE NO	: SJV6577D (2010)	DATE	10/7/2024
VEHICLE MODEL	: TOYOTA VIOS	Xiao Chun.	
CHASSIS NO	: MR053HY9305148875		

PARTS		QTY	PER UNIT	PRICES	
1	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 69.40	\$ 138.80	+
2	REAR BUMPER <i>Distal</i>	1	\$ 550.60	\$ 550.60	✓
3	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 55.10	\$ 110.20	+
4	REAR BUMPER REFLECTOR <i>cracked</i>	2	\$ 105.40	\$ 210.80	✓
5	REAR END PANEL <i>Distal</i>	1	\$ 645.10	\$ 645.10	✓
6	REAR END PANEL TOP GARNISH <i>Distal</i>	1	\$ 230.40	\$ 230.40	✓
7	REAR END PANEL TRIANGULAR BRACKET <i>new</i>	2	\$ 89.40	\$ 178.80	+
8	TAILLAMP <i>cracked</i>	2	\$ 345.10	\$ 690.20	✓
9	TAILLAMP PANEL <i>Repair</i>	2	\$ 231.20	\$ 462.40	+
10	BOOTLID <i>Distal</i>	1	\$ 658.70	\$ 658.70	✓
11	BOOTLID LOCK <i>Jammed</i>	1	\$ 185.90	\$ 185.90	✓
12	BOOTLID WEATHERSTRIPE <i>at</i>	1	\$ 205.90	\$ 205.90	✓
13	BOOTLID HINGE <i>Bent</i>	2	\$ 70.60	\$ 141.20	✓
14	BOOTLID OUTER MOULDING <i>cracked</i>	1	\$ 198.70	\$ 198.70	✓
15	TOYOTA LOGO <i>new</i>	1	\$ 45.60	\$ 45.60	✓
16	VIOS EMBLEM <i>new</i>	1	\$ 50.90	\$ 50.90	✓
17	REAR FENDER <i>Buckled</i>	1	\$ 899.80	\$ 899.80	✓
18	REAR FENDER INNER SHIELD <i>new</i>	1	\$ 68.90	\$ 68.90	+
19	REAR FENDER INNER TRIM <i>new</i>	1	\$ 285.20	\$ 285.20	+
20	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 120.50	\$ 120.50	✓
21	SPARE TYRE PANEL <i>Repair</i>	1	\$ 871.40	\$ 871.40	+
22	SPARE TYRE PANEL TOP COVER <i>ton</i>	1	\$ 188.50	\$ 188.50	✓
23	SPARE TYRE PANEL CENTRE SPONGE <i>new</i>	1	\$ 182.60	\$ 182.60	+
24	SPARE TYRE PANEL SIDE SPONGE <i>Distal</i>	2	\$ 225.40	\$ 450.80	✓
25	REAR EXHAUST PIPE <i>new</i>	1	\$ 691.30	\$ 691.30	+
26	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 35.60	\$ 35.60	+
27	REAR EXHAUST PIPE GASKET <i>new</i>	1	\$ 31.20	\$ 31.20	+
			SUBTOTAL :	\$ 7,519.60	
			LESS 25% :	\$ 1,879.90	
			PARTS TOTAL :	\$ 5,639.70	

5473.60

4105.20

SPECIAL NETT	QTY	PER UNIT	PRICES
1 REAR NUMBER PLATE <i>But</i>	1	\$ 30.00	\$ 30.00 ✓
2 REAR NUMBER PLATE HOLDER <i>Delid</i>	1	\$ 30.00	\$ 30.00 ✓
3 REAR BUMPER CLIPS <i>Ner</i>	1 SET	\$ 50.00	\$ 50.00 ✓
4 REVERSE SENSOR <i>And</i>	1 SET	\$ 280.00	\$ 280.00 <i>200</i> ✓
5 REAR END PANEL TOP GARNISH CLIPS <i>re</i>	1 SET	\$ 20.00	\$ 20.00 ✓
6 REAR END PANEL PANEL SEALANT <i>re</i>	1 SET	\$ 60.00	\$ 60.00 ✓
7 TAILLAMP BACK GASKET <i>m</i>	2	\$ 20.00	\$ 40.00 ✓
8 BOOTLID OUTER MOULDING CLIPS <i>re</i>	1 SET	\$ 20.00	\$ 20.00 ✓
9 REAR FENDER SEALANT <i>Ner</i>	1 SET	\$ 60.00	\$ 60.00 ✓
10 REAR FENDER INNER SHIELD CLIPS <i>3 not</i>	1 SET	\$ 20.00	\$ 20.00 +
11 REAR FENDER INNER TRIM CLIPS	1 SET	\$ 30.00	\$ 30.00 +
12 REAR WINDSCREEN SEALANT <i>re</i>	1	\$ 60.00	\$ 60.00 ✓
13 SPARE TYRE PANEL SEALANT <i>re</i>	1	\$ 60.00	\$ 60.00 +
14 REAR EXHAUST CHROME PIPE <i>re</i>	1	\$ 120.00	\$ 120.00 +
		S/N TOTAL :	\$ 820.00

570

LABOUR CHARGES	PRICES	ADJUSTMENT
1 PANEL BEATING	\$ 1,600.00	<i>120</i>
2 SPRAY PAINTING	\$ 1,400.00	<i>100</i>
3 WIRING	\$ 50.00	<i>30</i>
4 TO SPRAY TUFF COAT	\$ 150.00	<i>100</i>
5 TO REMOVE REVERSE SENSOR <i>26w</i>	\$ 100.00	<i>50</i>
6 TO REMOVE UPHOLSTERY & REAR SEAT	\$ 280.00	<i>60</i>
7 TO TRANSFER BOOTLID FITTINGS	\$ 150.00	<i>60</i>
8 TO REMOVE REAR WINDSCREEN	\$ 180.00	<i>120</i>
9 TO REMOVE FUEL TANK	\$ 150.00	<i>+</i>
10 TO REMOVE REAR EXHAUST PIPE	\$ 150.00	<i>+</i>
LABOR TOTAL :		\$ 4,210.00

total: 7295.00

*1/s: S.I.K ✓
(nett value)
09 Days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: