



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNM 5184K

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER UPPER (SN)	DEFORMED	\$794.00	\$794.00
1	REAR BUMPER LOWER (SN)	SCRATCHED	\$1,469.00	\$1,469.00
			\$2,263.00	\$2,263.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & REPLACE REAR BUMPER		\$400.00	\$400.00
	TO RESPRAY REAR BUMPER		\$400.00	\$400.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS		\$150.00	\$150.00
			\$950.00	\$950.00
GRAND TOTAL			\$3,213.00	\$3,213.00
RECOMMENDED COST OF REPAIRS				\$3,213.00
Report Ref No: CS/SPS24070193/Rvp3m4				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.