

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 8-Jul-24

Estimate no.

1420

Plate No. JSP6663

Model. LC135

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	fork FOR SET <i>best</i>	\$ 350.00	✓	
2	FORK T-UNDER BRACKET <i>best</i>	\$ 280.00	✓	
3	STEERING CONE <i>best</i>	\$ 60 150.00	✓	
4	FRONT SPORT RIM <i>best</i>	\$ 280.00	✓	
5	FRONT TYRE SHAFT <i>best</i>	\$ 50 120.00	✓	
6	FRONT DISC BRAKE <i>best</i>	\$ 180.00	✓	
7	<i>front</i> FRONT CALIPER <i>best</i>	\$ 250.00	✓	
8	FRONT SPEEDO GEAR <i>best</i>	\$ 150.00	✓	
9	FRONT SPEEDO CABLE <i>best</i>	\$ 120.00	✓	
10	RADIATOR <i>best</i>	\$ 350.00	✓	
11	SPARE COOLANT TANK <i>best</i>	\$ 180.00	✓	
12	INNER PANEL 1 <i>best</i>	\$ 160 200.00	✓	
13	FRONT PANEL COVER <i>best</i>	\$ 140 180.00	✓	
14	FRONT SIGNAL LIGHT SET <i>best</i>	\$ 168 380.00	✓	
15	HANDLE BAR <i>best</i>	\$ 148 280.00	✓	
16	MIRROR SET <i>best</i>	\$ 80 120.00	✓	
17	STARTER SWITCH <i>best</i>	\$ 100.00	✓	
18	FRONT FAIRING TUNER COVER <i>best</i>	\$ 50 80.00	✓	
19	BODY UNDER COVER R <i>best</i>	\$ 120.00	✓	
20	BODY UNDER COVER L <i>best</i>	\$ 120.00	✓	
21	BASKET <i>best</i>	\$ 100.00	✓	
22	BRAKE LEVER <i>best</i>	\$ 120.00	✓	
23	FRONT TYRE <i>best</i>	\$ 150.00	✓	
24	FRONT FOOTREST RUBBER <i>best</i>	\$ 50.00	✓	
25	BRAKE PEDAL <i>best</i>	\$ 150.00	✓	
26	EXHAUST PIPE <i>best</i>	\$ 320 500.00	✓	
27	EXHAUST PROTECTOR (FRONT) <i>best</i>	\$ 50 180.00	✓	
28	EXHAUST PROTECTOR (REAR) <i>best</i>	\$ 40 150.00	✓	
29	FRONT HEAD LAMP <i>best</i>	\$ 250.00	✓	

102

not Authorized
has
now
Tel 6263561
not the TOTAL loss
2/s \$ 1400/
5-days
also the Attorney

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 8-Jul-24

Estimate no.

1420

Plate No. JSP6663

Model. LC135

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
30	REAR SIGNAL LIGHT SET <i>cm</i>	\$ 180.00	✓	
31	REAR BOX <i>cut</i>	\$ 350.00	250	
32	REAR BOX BRACKET <i>h</i>	\$ 250.00	X	
33	REAR NUMBER PLATE <i>hup</i>	\$ 30.00	105/10	
34	COVERSET <i>cm</i>	\$ 480.00	✓	
35	BODY ALIGNMENT <i>m</i>	\$ 700.00	✓	
36	LABOUR <i>4</i>	\$ 600.00	350	
37	FRONT FOOTREST BAR <i>set</i>	\$ 200.00	118 ✓	

102

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10% \$ 843.00
 \$ 8,430.00
 Sub Total : \$ 7,587.00
 GST 9% \$ 682.83
 Total: \$ 8,269.83

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.