



## QUOTATION

CODE: F0001  
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
ADDRESS: 16 RAFFLES QUAY  
#42-01  
HONG LEONG BUILDING  
SINGAPORE 048581  
ATTN: MOTOR CLAIM DEPT  
CONTACT NO.: 6507 3848  
MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B  
CHASSIS NO.: JM6GL1072K0312254  
ENGINE NO.: PE21258602  
REG NO.: SML4662X  
REGN DATE: 22/05/2019


PAGE NO.: 1  
DOCUMENT NO.: 2465  
DOCUMENT DATE: 09/07/2024  
POS ID: 12  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV: Lee Yao Sheng  
CSP/OP CODE: I  
DEPT: 14099  
WIP NO.:  
REF. NO.:  
DATE IN:  
EXT. WTY:  
MILEAGE: 0

### DESCRIPTION:

| Item  | Description                                                                                                                                                                                   | Qty.       | Unit Price<br>SGD | Stk/Status | Gross amount<br>SGD | GST<br>Code |
|-------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-------------------|------------|---------------------|-------------|
| NOTES | MS FIRST TP CLAM                                                                                                                                                                              |            |                   |            | 0.00                | O           |
| SUB   | TO REMOVE & REPLACE FRT BUMPER, GRILLE TOP, BONNET, FRT FENDER RH, FRT FENDER LH, FRT SUPPORT PANEL, FRT DOOR LH, REAR DOOR LH, REAR FENDER LH & REAR BUMPER. AND ALL ACCIDENT AFFECTED AREA. | @792X10-   |                   |            | 11,880.00           | S           |
| SUB   | TO RESPRAY FRT BUMPER, GRILLE TOP, BONNET, FRT FENDER RH, FRT FENDER LH, A PILLAR LH, FRT DOOR LH, REAR DOOR LH, REAR FENDER LH, REAR BUMPER & ROCKER PANEL LH.                               | @756X7.5 7 |                   |            | 11,340.00           | S           |
| SUB   | TO SUPPLY FRT NUMBER PLATE.                                                                                                                                                                   |            |                   |            | 70.00               | S           |
| SUB   | TO TRANSFER FRONT SENSORS.                                                                                                                                                                    |            |                   |            | 320.00              | S           |
| SUB   | TO TRANSFER THE DOOR MECHANISM.                                                                                                                                                               |            |                   |            | 792.00              | S           |
| SUB   | TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.                                                                                           |            |                   |            | 792.00              | S           |
| SUB   | TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.                                                                                                                           |            |                   |            | 560.00              | S           |

"This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs."

"Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle."



Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
Tel: 6363 3003, Fax: 6369 3003, BRN 199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres:

4 Lili Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 6846 1700 Service Fax: 6744 9403

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6116 Service Tel: 6603 6128

Eurokars Altersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606



## QUOTATION

CODE: F0001  
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
ADDRESS: 16 RAFFLES QUAY  
#42-01  
HONG LEONG BUILDING  
SINGAPORE 048581  
ATTN: MOTOR CLAIM DEPT  
CONTACT NO.: 6507 3848  
MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B  
CHASSIS NO.: JM6GL1072K0312254  
ENGINE NO.: PE21258602  
REG NO.: SML4662X  
REGN DATE: 22/05/2019


PAGE NO.: 2  
DOCUMENT NO.: 2465  
DOCUMENT DATE: 09/07/2024  
POS ID: 12  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV: Lee Yao Sheng  
CSP/OP CODE: I  
DEPT: 14099  
WIP NO.:  
REF. NO.:  
DATE IN:  
EXT. WTY:  
MILEAGE: 0

### DESCRIPTION:

| Item | Description                                                                         | Qty. | Unit Price | Sub/Status | Gross GST<br>amount Code |
|------|-------------------------------------------------------------------------------------|------|------------|------------|--------------------------|
|      |                                                                                     |      | SGD        |            | SGD                      |
| SUB  | TO SUPPLY SEALER ON THE WINDSCREEN GLASS.                                           |      |            |            | 120.00 S                 |
| SUB  | TO REMOVE & REPLACE THE WIRE HARNESS ASSY.                                          |      |            |            | 792.00 S                 |
| SUB  | TO REMOVE & REPLACE UNDERCARRIAGE.                                                  |      |            |            | 792.00 S                 |
| SUB  | TO REMOVE & REPLACE ABS HYDRAULIC UNIT ASSY AND BRAKE PIPING.                       |      |            |            | 792.00 S                 |
| SUB  | TO REMOVE & INSTALL ENGINE ASSY FOR ACCESS.                                         |      |            |            | 2,376.00 S               |
| SUB  | TO REALIGN BODY CHASSIS ALIGNMENT.                                                  |      |            |            | 2,376.00 S               |
| SUB  | TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.                                     |      |            |            | 120.00 S                 |
| SUB  | TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.                          |      |            |            | 560.00 S                 |
| SUB  | TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.                          |      |            |            | 250.00 S                 |
| SUB  | TO MOUNT CAR ON CAR O LINER AND REALIGN THE CAR BODY ACCORDING MAZDA SPECIFICATION. |      |            |            | 1,500.00 S               |

"This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs."

"Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle."



Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No. M90364005A

zoom-zoom

Showrooms & Service Centres:  
4 Loke Chuan Singapore 408605

Sales Tel: 6295 8888 Service Tel: 6395 8899  
Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128  
Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Pagar Singapore 609042  
Service Tel: 6331 0606  
Service Fax: 6331 0620



# QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN: MOTOR CLAIM DEPT  
 CONTACT NO.: 6507 3848  
 MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B  
 CHASSIS NO.: JM6GL1072K0312254  
 ENGINE NO.: PE21258602  
 REG NO.: SML4662X  
 REGN DATE: 22/05/2019


PAGE NO.: 3  
 DOCUMENT NO.: 2465  
 DOCUMENT DATE: 09/07/2024  
 POS ID: 12  
 PRINTED BY: Lee Yao Sheng  
 SERVICE ADV: Lee Yao Sheng  
 CSP/OP CODE: 1  
 DEPT: 14099  
 WIP NO.:  
 REF. NO.:  
 DATE IN:  
 EXT. WTY:  
 MILEAGE: 0

## DESCRIPTION:

| Item           | Description                                        | Qty.  | Unit Price | Stk/Status | Gross amount        | GST Code |
|----------------|----------------------------------------------------|-------|------------|------------|---------------------|----------|
|                |                                                    |       | SGD        |            | SGD                 |          |
| SUB            | TO CONDUCT BRAKE SYSTEM CHECKING                   |       |            | X117?      | 792.00              | S        |
| SUB            | USING SPECIFIC BRAKING TEST MACHINE.               |       |            |            |                     |          |
| SUB            | TO SUPPLY 2 PC TIRE <i>496</i>                     |       |            |            | <del>1,400.00</del> | S        |
| SUB            | TO CARRY OUT BODY CAVITY PRESERVATION.             |       |            |            | <del>250.00</del>   | S        |
| SUB            | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. |       |            | <i>150</i> | <del>250.00</del>   | S        |
| SUB            | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.    |       |            | <i>250</i> | <del>300.00</del>   | S        |
| SUB            | SUNDRIES.                                          |       |            | <i>20</i>  | <del>50.00</del>    | S        |
| GSJB-50-031 BB | FRT BUMPER GL3 W/PS <i>for</i>                     | 1.00  | 1,177.81   | STOCK      | <del>1,177.81</del> | S        |
| C274-50-133    | NUT, CLIP <i>for</i>                               | 12.00 | 2.36       | STOCK      | <del>28.32</del>    | S        |
| BBM4-50-355    | RIVET <i>for</i>                                   | 4.00  | 3.71       | STOCK      | <del>14.84</del>    | S        |
| S51S-51-833    | RIVET, SPLASH SHIELD <i>for</i>                    | 8.00  | 3.12       | STOCK      | <del>24.96</del>    | S        |
| GHP9-50-0Z5    | GROMMET, SCREW <i>for</i>                          | 2.00  | 2.36       | STOCK      | <del>4.72</del>     | S        |
| B45A-56-146A   | FASTENER <i>for</i>                                | 2.00  | 2.36       | STOCK      | <del>4.72</del>     | S        |
| F189-51-356A   | SPRING <i>for</i>                                  | 2.00  | 9.28       | STOCK      | <del>18.56</del>    | S        |
| GSH7-50-M42    | CAP(L) GL <i>MIS</i>                               | 1.00  | 73.00      | STOCK      | <del>73.00</del>    | S        |
| GBVG-50-131    | PROTECTOR(L), BUMPER GL3 <i>MIS</i>                | 1.00  | 79.23      | STOCK      | <del>79.23</del>    | S        |
| GSH7-50-102    | COVER LHF BUMPER GL3 <i>MIS</i>                    | 1.00  | 24.87      | STOCK      | <del>24.87</del>    | S        |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
 Tel: 6363 3003, Fax: 6369 3003, BRN 199103859N, GST Regn. No. M90364005A

**ZOOM-ZOOM**

Showrooms & Service Centres:

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6119

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042



MAZDA

## QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN: MOTOR CLAIM DEPT  
 CONTACT NO.: 6507 3848  
 MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B  
 CHASSIS NO.: JM6GL1072K0312254  
 ENGINE NO.: PE21258602  
 REG NO.: SML4662X  
 REGN DATE: 22/05/2019


PAGE NO.: 4  
 DOCUMENT NO.: 2465  
 DOCUMENT DATE: 09/07/2024  
 POS ID: 12  
 PRINTED BY: Lee Yao Sheng  
 SERVICE ADV:  
 CSP/OP CODE: Lee Yao Sheng  
 DEPT: I  
 WIP NO.: 14099  
 REF. NO.:  
 DATE IN:  
 EXT. WTY:  
 MILEAGE: 0

## DESCRIPTION:

| Item         | Description                                | Qty. | Unit Price | Stk/Status | Gross amount | GST Code |
|--------------|--------------------------------------------|------|------------|------------|--------------|----------|
|              |                                            |      | SGD        |            | SGD          |          |
| GRF2-50-050A | STIFF 'A', BUMPER GL3 <i>fom</i>           | 1.00 | 119.35     | STOCK      | 119.35       | S        |
| GHP9-50-0U1C | RETAINER LHF BUMPER GJ/GL <i>can</i>       | 1.00 | 14.84      | STOCK      | 14.84        | S        |
| GSH7-50-104  | COVER(L), BUMPER GL3 <i>mis</i>            | 1.00 | 36.50      | STOCK      | 36.50        | S        |
| GSH7-50-1V0  | PLATE(L), SEAL-F. BUMPER GL <i>mis</i>     | 1.00 | 95.25      | STOCK      | 95.25        | S        |
| G48F-50-111  | FOAM, BUMPER-FRONT GL <i>can</i>           | 1.00 | 73.00      | STOCK      | 73.00        | S        |
| FD01-68-AC3  | FASTENER <i>m</i>                          | 2.00 | 5.31       | STOCK      | 10.62        | S        |
| GSH7-50-070  | REINF., FRT BUMPER GL3 <i>ht</i>           | 1.00 | 563.37     | STOCK      | 563.37       | S        |
| GSK1-50-170  | HOLDER, LIC GL <i>Xan</i>                  | 1.00 | 111.77     | STOCK      | 111.77       | S        |
| KD47-67-UC5A | RETAINER S/ACTIV <i>mis</i>                | 1.00 | 15.77      | STOCK      | 15.77        | S        |
| KD47-67-UC1  | S.SENSOR, ULTRASONIC <i>mis</i>            | 1.00 | 184.59     | STOCK      | 184.59       | S        |
| GHP9-50-0U1C | RETAINER LHF BUMPER GJ/GL <i>mis</i>       | 1.00 | 14.84      | STOCK      | 14.84        | S        |
| GSH7-50-7K0D | MOULD LHF LWR BUMPER GL3 <i>can</i>        | 1.00 | 303.10     | NO STOCK   | 303.10       | S        |
| GSH7-50-719  | MESH, GRILL GL IPM3 <i>Ba Xan</i>          | 1.00 | 592.11     | STOCK      | 592.11       | S        |
| GSH7-50-EB1  | CLIP <i>m</i>                              | 1.00 | 9.28       | STOCK      | 9.28         | S        |
| GSH7-50-712B | REINF. RADIATOR GRILLE GL <i>can</i>       | 1.00 | 161.58     | STOCK      | 161.58       | S        |
| GSH7-50-161  | BRACKET LHF BUMPER GL <i>mis</i>           | 1.00 | 44.76      | STOCK      | 44.76        | S        |
| G46L-50-EB1  | CLIP <i>m</i>                              | 4.00 | 4.64       | STOCK      | 18.56        | S        |
| GSK1-50-191  | BRACKET GRILL GL <i>can</i> <i>7.49VLC</i> | 1.00 | 15.77      | STOCK      | 15.77        | S        |
| KD45-50-1K5A | PIN, LOCATOR <i>7.49VLC</i>                | 2.00 | 2.36       | STOCK      | 4.72         | S        |
| EA01-50-037  | RIVET <i>m</i>                             | 4.00 | 7.34       | STOCK      | 29.36        | S        |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
 Tel: 6363 3003, Fax: 6369 3003, BRN 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres:  
 5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6119

Eurokars Altersales Centre:  
 27A Tanjong Pagar Road Singapore 080012



## QUOTATION

CODE: F0001  
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
ADDRESS: 16 RAFFLES QUAY  
#42-01  
HONG LEONG BUILDING  
SINGAPORE 048581  
ATTN: MOTOR CLAIM DEPT  
CONTACT NO.: 6507 3848  
MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B  
CHASSIS NO.: JM6GL1072K0312254  
ENGINE NO.: PE21258602  
REG NO.: SML4662X  
REGN DATE: 22/05/2019


PAGE NO.: 5  
DOCUMENT NO.: 2465  
DOCUMENT DATE: 09/07/2024  
POS ID: 12  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV: Lee Yao Sheng  
CSP/OP CODE: I  
DEPT: 14099  
WIP NO.:  
REF. NO.:  
DATE IN:  
EXT. WTY:  
MILEAGE: 0

### DESCRIPTION:

| Item           | Description                               | Qty. | Unit Price | Stk/Status | Gross GST |      |
|----------------|-------------------------------------------|------|------------|------------|-----------|------|
|                |                                           |      |            |            | amount    | Code |
|                |                                           |      | SGD        |            | SGD       |      |
| GSH7-50-162    | BRACKET(L),F. BUMPER SIDE GL3 <i>MS</i>   | 1.00 | 44.76      | STOCK      | 44.76     | S    |
| KD45-50-ES1    | GROMMET <i>MS</i>                         | 2.00 | 2.36       | STOCK      | 4.72      | S    |
| GSH7-50-152    | BRACKET RHF BUMPER SIDE GL3 <i>MS XNN</i> | 1.00 | 44.76      | STOCK      | 44.76     | S    |
| GD7A-50-EA1    | FASTENER <i>MS</i>                        | 4.00 | 2.62       | STOCK      | 10.48     | S    |
| TK21-50-355    | RIVET <i>MS</i>                           | 6.00 | 7.42       | STOCK      | 44.52     | S    |
| GSH7-50-717A   | BRACKET,GRILLE-RADIA GL3 <i>MS</i>        | 1.00 | 114.63     | STOCK      | 114.63    | S    |
| GSH7-50-7E1 33 | GRILLE,UP.RADIATOR GL3 <i>MS</i>          | 1.00 | 482.37     | STOCK      | 482.37    | S    |
| GSH7-50-163    | BRACKET LHF BUMPER GL3 <i>MS</i>          | 1.00 | 14.84      | STOCK      | 14.84     | S    |
| GSH7-50-153    | BRACKET RHF BUMPER GL3 <i>MS</i>          | 1.00 | 14.84      | STOCK      | 14.84     | S    |
| S51S-51-833    | RIVET,SPLASH SHIELD <i>MS</i>             | 8.00 | 3.12       | STOCK      | 24.96     | S    |
| GSH7-50-7J0D   | MOULD RHF LWR BUMPER GL3 <i>MS</i>        | 1.00 | 303.10     | STOCK      | 303.10    | S    |
| GBFN-50-716    | BRACKET,RAD.GRILLE GL3 <i>MS</i>          | 1.00 | 128.37     | STOCK      | 128.37    | S    |
| G46L-51-730    | MASCOT,FRT GJ/GL <i>MS</i>                | 1.00 | 66.51      | STOCK      | 66.51     | S    |
| GRG1-50-164    | BRACKET LHF GRILL GL <i>MS</i>            | 1.00 | 15.77      | STOCK      | 15.77     | S    |
| S51S-51-833    | RIVET,SPLASH SHIELD <i>MS</i>             | 8.00 | 3.12       | STOCK      | 24.96     | S    |
| GRF5-51-075A   | PROTECTOR LHF HL GL3 <i>MS</i>            | 1.00 | 123.15     | STOCK      | 123.15    | S    |
| GSK4-51-041B   | HEADLAMP LH IPM3 GL <i>MS</i>             | 1.00 | 5,460.29   | STOCK      | 5,460.29  | S    |
| GSH7-50-ACYA   | BRACKET LHF HL GL3 <i>MS</i>              | 1.00 | 15.77      | STOCK      | 15.77     | S    |
| GSH7-50-ACXA   | BRACKET(L),HEAD LAMP GL3 <i>MS</i>        | 1.00 | 37.01      | STOCK      | 37.01     | S    |
| GRF5-51-0A1    | COVER,SOCKET GL <i>MS</i>                 | 1.00 | 13.91      | STOCK      | 13.91     | S    |

"This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

"Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No. M90364005A

zoom-zoom

Showrooms & Service Centres:

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6603 6128 Service Fax: 6603 6128

Eurokars Alterraus Centre:

27A Tanjong Penjuru Singapore 609042

Sales Tel: 6333 1100



## QUOTATION

CODE: T0001  
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
ADDRESS: 16 RAFFLES QUAY  
#42-01  
HONG LEONG BUILDING  
SINGAPORE 048581  
ATTN: MOTOR CLAIM DEPT  
CONTACT NO.: 6507 3848  
MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B  
CHASSIS NO.: JM6GL1072K0312254  
ENGINE NO.: PE21258602  
REG NO.: SML4662X  
REGN DATE: 22/05/2019


PAGE NO.: 6  
DOCUMENT NO.: 2465  
DOCUMENT DATE: 09/07/2024  
POS ID: 12  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV:  
CSP/OP CODE: Lee Yao Sheng  
DEPT: I  
WIP NO.: 14099  
REF. NO.:  
DATE IN:  
EXT. WTY:  
MILEAGE: 0

### DESCRIPTION:

| Item           | Description                                    | Qty.  | Unit Price |     | Stk/Status | Gross GST |      |
|----------------|------------------------------------------------|-------|------------|-----|------------|-----------|------|
|                |                                                |       |            | SGD |            | amount    | Code |
| B092-51-833    | RIVET <i>nu</i>                                | 2.00  | 2.95       |     | STOCK      | 5.90      | S    |
| B1Y4-67-SH3    | CORD,SHORT DJ/BM/BP/DM/KG/TC <i>cut</i>        | 1.00  | 60.52      |     | STOCK      | 60.52     | S    |
| GHP9-52-211A   | FENDER LHF GJ/GL <i>bu</i>                     | 1.00  | 372.97     |     | STOCK      | 372.97    | S    |
| GRF2-56-140    | GUARD LHF MUD GL3 <i>nu</i>                    | 1.00  | 123.15     |     | STOCK      | 123.15    | S    |
| GHP9-52-240D   | STAY(L),FENDER GJ/GL <i>mis</i>                | 1.00  | 58.33      |     | NO STOCK   | 58.33     | S    |
| B45A-56-146A   | FASTENER <i>nu</i>                             | 21.00 | 2.36       |     | STOCK      | 49.56     | S    |
| GJ21-68-885B02 | FASTENER <i>nu</i>                             | 3.00  | 2.36       |     | STOCK      | 7.08      | S    |
| GRF2-56-115    | SHIELD(L),SPLASH GL3 <i>mis</i>                | 1.00  | 16.69      |     | STOCK      | 16.69     | S    |
| GBY0-52-31XB   | BONNET GL3 <i>bt</i>                           | 1.00  | 1,228.97   |     | STOCK      | 1,228.97  | S    |
| TD11-56-694    | FASTENER,BONNET <i>nu</i>                      | 11.00 | 2.36       |     | STOCK      | 25.96     | S    |
| BC1D-58-762    | FASTENER <i>nu</i>                             | 20.00 | 2.70       |     | STOCK      | 54.00     | S    |
| GHP9-56-770    | WTHSTP,PARTING SEAL GJ/GL <i>cut</i>           | 1.00  | 106.63     |     | STOCK      | 106.63    | S    |
| J001-56-741    | RIVET <i>nu</i>                                | 22.00 | 1.86       |     | STOCK      | 40.92     | S    |
| P5E1-18-572    | CONVERTER,DC/DC SKYACTIV <i>? xsul</i>         | 1.00  | 459.78     |     | STOCK      | 459.78    | S    |
| PE05-18-58Z    | BRACKET GJ <i>bt</i>                           | 1.00  | 15.77      |     | STOCK      | 15.77     | S    |
| KD45-67-B1XA   | BRACKET,HARNESS KE <i>bt xsul</i>              | 1.00  | 13.91      |     | NO STOCK   | 13.91     | S    |
| GRT8-66-750    | BLOCK,RELAY GL/KF/KG <i>? xsul</i>             | 1.00  | 68.95      |     | STOCK      | 68.95     | S    |
| 9965-16-7570   | WHEEL,DISC 17"X7 GL <i>scr (1pc) rear xsul</i> | 2.00  | 1,222.15   |     | STOCK      | 2,444.30  | S    |
| GHY0-59-02XJ   | LHF DOOR GJ/GL <i>regr</i>                     | 1.00  | 1,126.65   |     | STOCK      | 1,126.65  | S    |
| TK48-59-762    | FASTENER(L) <i>nu</i>                          | 1.00  | 9.28       |     | STOCK      | 9.28      | S    |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
Tel: 6363 3003, Fax: 6369 3003, BRN 199103859N, GST Regn. No: M90364005A

zoom-zoom

Showrooms & Service Centres:  
1101 Close Singapore 408607

23 Leng Kee Road Singapore 149001

Eurokars AfterSales Centre:



## QUOTATION

CODE: F0001  
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
ADDRESS: 16 RAFFLES QUAY  
#42-01  
HONG LEONG BUILDING  
SINGAPORE 048581  
ATTN: MOTOR CLAIM DEPT  
CONTACT NO.: 6507 3848  
MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B  
CHASSIS NO.: JM6GL1072K0312254  
ENGINE NO.: PE21258602  
REG NO.: SML4662X  
REGN DATE: 22/05/2019


PAGE NO.: 7  
DOCUMENT NO.: 2465  
DOCUMENT DATE: 09/07/2024  
POS ID: 12  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV:  
CSP/OP CODE: Lee Yao Sheng  
DEPT: 1  
WIP NO.: 14099  
REF. NO.:  
DATE IN:  
EXT. WTY:  
MILEAGE: 0

### DESCRIPTION:

| Item         | Description                             | Qty. | Unit Price | Stk/Status | Gross GST |      |
|--------------|-----------------------------------------|------|------------|------------|-----------|------|
|              |                                         |      |            |            | amount    | Code |
|              |                                         |      | SGD        |            | SGD       |      |
| GJ6A-58-975  | GROMMET, SCREW <i>an</i>                | 9.00 | 2.36       | STOCK      | 21.24     | S    |
| GJR9-69-16YB | GARNISH(L), SAIL-OUT GJ/GL <i>X an</i>  | 1.00 | 125.08     | STOCK      | 125.08    | S    |
| GBFT-50-M20  | GARNISH LHF DR GL <i>X an</i>           | 1.00 | 119.35     | STOCK      | 119.35    | S    |
| GBFT-50-M40  | GARNISH(L) REAR DOOR GL <i>X an</i>     | 1.00 | 133.18     | STOCK      | 133.18    | S    |
| GJR9-50-M60A | GARNISH LHR DOOR GJ <i>X an</i>         | 1.00 | 69.71      | STOCK      | 69.71     | S    |
| CHP9-50-4R2A | GUARD STONE LHR GJ <i>cut</i>           | 1.00 | 15.77      | STOCK      | 15.77     | S    |
| GHY1-73-02XB | DOOR LHR GJ/GL <i>bt</i>                | 1.00 | 1,275.33   | STOCK      | 1,275.33  | S    |
| TK48-73-762  | FASTENER(L), WEATHERSTRIP <i>an</i>     | 1.00 | 9.28       | STOCK      | 9.28      | S    |
| GBFN-73-763  | FASTENER(L), WEATHERSTRIP <i>an</i>     | 1.00 | 9.28       | STOCK      | 9.28      | S    |
| GJ6A-58-975  | GROMMET, SCREW <i>an</i>                | 7.00 | 2.36       | STOCK      | 16.52     | S    |
| GSY7-71-41X  | FENDER LHR GL3 <i>bt</i>                | 1.00 | 1,506.02   | STOCK      | 1,506.02  | S    |
| GHK1-50-611B | MOULD, RR.WINDOW GL <i>an</i>           | 1.00 | 126.01     | STOCK      | 126.01    | S    |
| GJ6A-50-897  | SPACER <i>an</i>                        | 1.00 | 11.13      | STOCK      | 11.13     | S    |
| FB01-63-959  | TERMINAL, BACK WIND. <i>an</i>          | 3.00 | 31.78      | STOCK      | 95.34     | S    |
| TK21-50-355  | RIVET <i>an</i>                         | 2.00 | 7.42       | STOCK      | 14.84     | S    |
| GRF5-51-153  | GASKET(R), RR.COMB. GL3 <i>an</i>       | 1.00 | 52.77      | STOCK      | 52.77     | S    |
| GRF5-51-163  | GASKET(L), RR.COMB. GL3 <i>an</i>       | 1.00 | 52.77      | STOCK      | 52.77     | S    |
| FTH1-25-60X  | SHAFT LHF DRIVE KF/KG/GL5 <i>? X su</i> | 1.00 | 1,609.44   | STOCK      | 1,609.44  | S    |
| D651-33-042A | NUT, AXLE <i>? X su</i>                 | 1.00 | 12.98      | STOCK      | 12.98     | S    |
| KD35-33-04XF | HUB, WHEEL FRT BM/GJ/KF <i>? X su</i>   | 1.00 | 682.80     | STOCK      | 682.80    | S    |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
Tel: 6163 1003, Fax: 6169 1003, 88N.199103859N, CST Regn. No.: M90364005A

**ZOOM-ZOOM**

#### Showrooms & Service Centres :

5 Lili Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 6846 1700 Service Fax: 6744 9407

23 Leng Kee Road Singapore 159075

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7071 Service Fax: 6476 7417

#### Eurokars AfterSales Centre:

27A Tanjong Pagar Road Singapore 067094

Service Tel: 6331 0606

Service Fax: 6331 0620



## QUOTATION

CODE: F0001  
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
ADDRESS: 16 RAFFLES QUAY  
#42-01  
HONG LEONG BUILDING  
SINGAPORE 048581  
ATTN: MOTOR CLAIM DEPT  
CONTACT NO.: 6507 3848  
MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B  
CHASSIS NO.: JM6GL1072K0312254  
ENGINE NO.: PE21258602  
REG NO.: SML4662X  
REGN DATE: 22/05/2019


PAGE NO.: 8  
DOCUMENT NO.: 2465  
DOCUMENT DATE: 09/07/2024  
POS ID: 12  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV:  
CSP/OP CODE: Lee Yao Sheng  
DEPT: 1  
WIP NO.: 14099  
REF. NO.:  
DATE IN:  
EXT. WTY:  
MILEAGE: 0

### DESCRIPTION:

| Item         | Description                            | Qty. | Unit Price | Strk/Status | Gross amount | GST Code |
|--------------|----------------------------------------|------|------------|-------------|--------------|----------|
|              |                                        |      | SGD        |             | SGD          |          |
| KD45-33-271C | COVER(L),DUST GL/DK/KF ? xsvl          | 1.00 | 34.31      | *NO STOCK   | 34.31        | S        |
| GBFN-33-031  | KNUCKLE LHF GL ? xsvl                  | 1.00 | 455.57     | *NO STOCK   | 455.57       | S        |
| CHP9-43-990  | HOSE FLEXIBLE LHF GJ/GL ? xsvl         | 1.00 | 84.29      | STOCK       | 84.29        | S        |
| GBEF-32-290  | JOINT(L) STRG GL ? xsvl                | 1.00 | 143.96     | STOCK       | 143.96       | S        |
| T060-26-169A | PIN,SNAP ? xsvl                        | 1.00 | 5.74       | STOCK       | 5.74         | S        |
| GBFW-32-110  | GEAR,STEERING ASSY GL5 ? xsvl          | 1.00 | 962.13     | STOCK       | 962.13       | S        |
| G46C-34-350J | ARM LOWER LHF GL ? xsvl                | 1.00 | 577.70     | STOCK       | 577.70       | S        |
| GBJD-34-900A | DAMPER LHF GL ? xsvl                   | 1.00 | 449.92     | STOCK       | 449.92       | S        |
| KB7W-34-80XD | MEMBER,CROSS FRT GL/KF ✓               | 1.00 | 2,086.24   | STOCK       | 2,086.24     | S        |
| KD35-34-170  | LINK,CONTROL FRT GJ/GL/KE/KF/TC ? xsvl | 1.00 | 72.32      | STOCK       | 72.32        | S        |
| GBFN-34-15XA | STABILIZER,FRONT GL ? xsvl             | 1.00 | 667.72     | STOCK       | 667.72       | S        |
| GSH7-53-150  | MEMBER,SHROUD-UPPER GL3 ? xsvl         | 1.00 | 139.24     | STOCK       | 139.24       | S        |
| CHP9-52-15YA | STAY,LOCK GJ/GL ? xsvl                 | 1.00 | 44.51      | STOCK       | 44.51        | S        |
| CHP9-53-110B | PANEL SHROUD GL3 ? xsvl                | 1.00 | 479.34     | STOCK       | 479.34       | S        |
| GSH7-50-R10  | GRILLE,UNDER GL3 ? xsvl                | 1.00 | 877.08     | STOCK       | 877.08       | S        |
| GSH7-50-1COB | PLATE,SET GL ? xsvl                    | 1.00 | 188.97     | STOCK       | 188.97       | S        |
| GD7A-50-EA1  | FASTENER ? xsvl                        | 4.00 | 2.62       | STOCK       | 10.48        | S        |
| GBEF-51-PC1  | MLDG(L),FENDER-FRT GL3 X n             | 1.00 | 15.77      | STOCK       | 15.77        | S        |
| GSH7-56-11Y  | COVER,UNDER FRT GL de                  | 1.00 | 90.78      | STOCK       | 90.78        | S        |
| B61K-56-110A | COVER,UNDER BM/BN/GL ? xsvl            | 1.00 | 322.99     | STOCK       | 322.99       | S        |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
Tel: 6363 3003, fax: 6369 3003, BRN 199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres:


5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8888

23 Leng Kee Road Singapore 159095

Eurokars Altersales Centre:

27A Tanjong Pagar Road



## QUOTATION

CODE: F0001  
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
ADDRESS: 16 RAFFLES QUAY  
#42-01  
HONG LEONG BUILDING  
SINGAPORE 048581  
ATTN: MOTOR CLAIM DEPT  
CONTACT NO.: 6507 3848  
MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B  
CHASSIS NO.: JM6GL1072K0312254  
ENGINE NO.: PE21258602  
REG NO.: SML4662X  
REGN DATE: 22/05/2019

PAGE NO.: 9  
DOCUMENT NO.: 2465  
DOCUMENT DATE: 09/07/2024  
POS ID: 12  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV:  
CSP/OP CODE: Lee Yao Sheng  
DEPT: 1  
WIP NO.: 14099  
REF. NO.:  
DATE IN:  
EXT. WTY:  
MILEAGE: 0

### DESCRIPTION:

| Item                                | Description    | Qty. | Unit Price | Stk/Status | Gross amount | GST Code |
|-------------------------------------|----------------|------|------------|------------|--------------|----------|
|                                     |                |      | SGD        | STOCK      | SGD          |          |
| 11-BF25-W0-03: BRAKE FLUID D3 0.33L | <i>? X AM</i>  | 6.00 | 11.55      | NO STOCK   | 69.30        | S        |
| GCCD-67-010C HARNESS FRT GL         | <i>? X SVC</i> | 1.00 | 9,970.30   |            | 9,970.30     | S        |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Resur*  
*Hp 20010068*  
*16 days + 2 = 18 days*  
*p/p*  
*11/07/24*  
*Resy & paint*

|                  | GST Code | Rate  | Service/ Goods | GST      |
|------------------|----------|-------|----------------|----------|
| Parts 40,856.71  | O        | -     |                | -        |
| Surcharge 0.00   | S        | 9.00% | 80,132.71      | 7,211.94 |
| Labour 39,276.00 |          |       |                |          |
| Menus 0.00       |          |       |                |          |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

|                 | Before GST | GST      | Total     |
|-----------------|------------|----------|-----------|
| Gross           | 80,132.71  | 7,211.94 | 87,344.65 |
| Less: Deposit** | 0.00       | 0.00     | 0.00      |
| Amount Due      | 80,132.71  | 7,211.94 | 87,344.65 |


\*\*Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE  
No.

Date:

Customer signature

Authorised signature



Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres:  
511/1 Close Singapore 408605  
Sales Tel: 6395 8888 Service Tel: 6395 8899  
Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095  
Sales Tel: 6603 6118 Service Tel: 6603 6128  
Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Altersales Centre:  
17A Tanjong Penjuru Singapore 609042  
Service Tel: 6331 0606  
Service Fax: 6331 0620



## QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN: MOTOR CLAIM DEPT  
 CONTACT NO.: 6507 3848  
 MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B  
 CHASSIS NO.: JM6GL1072K0312254  
 ENGINE NO.: PE21258602  
 REG NO.: SML4662X  
 REGN DATE: 22/05/2019


PAGE NO.: 4  
 DOCUMENT NO.: 2838  
 DOCUMENT DATE: 22/10/2024  
 POS ID: 12  
 PRINTED BY: Wong Chun Wei  
 SERVICE ADV:  
 CSP/OP CODE: Wong Chun Wei  
 DEPT: I  
 WIP NO.: 14099  
 REF. NO.:  
 DATE IN: 03/08/2024  
 EXT. WTY:  
 MILEAGE: 0

### DESCRIPTION:

| Item        | Description                                                                                | Qty.  | Unit Price | Stk/Status | Gross amount | GST Code |
|-------------|--------------------------------------------------------------------------------------------|-------|------------|------------|--------------|----------|
|             |                                                                                            |       | SGD        |            | SGD          |          |
| SUB         | MZ 6 TP<br>TO CHECK ELECTRICAL SYSTEM<br>FOR PROPER FUNCTIONING.<br>- PO173050             |       |            |            | 150.00       | S        |
| SUB         | MZ 6 TP<br>TO REPROGRAMME AFTER THE<br>ACCIDENT REPAIR WORKS.<br>- PO173050                |       |            |            | 250.00       | S        |
| SUB         | MZ 6 TP<br>SUNDRIES.<br>- PO173050                                                         |       |            |            | 20.00        | S        |
| SUB         | MZ 6 TP<br>TO MOUNT SPORT RIM AND<br>CONDUCT WHEEL BALANCING. <i>2 suppl</i><br>- PO173050 |       |            |            | 80.00        | S        |
| GSJ8-50-031 | BB FRT BUMPER GL3 W/PS                                                                     | 1.00  | 1,177.81   | *ISSUED    | 1,177.81     | S        |
| C274-50-133 | NUT, CLIP                                                                                  | 12.00 | 2.36       | *ISSUED    | 28.32        | S        |
| BBM4-50-355 | RIVET                                                                                      | 4.00  | 3.71       | *ISSUED    | 14.84        | S        |
| S51S-51-833 | RIVET, SPLASH SHIELD                                                                       | 8.00  | 3.12       | *ISSUED    | 24.96        | S        |
| GHP9-50-025 | GROMMET, SCREW                                                                             | 2.00  | 2.36       |            | 4.72         | S        |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
 Tel: 6363 3003, Fax: 6369 3003, BRN 199103859N, GST Regn. No. M90364005A

### Showrooms & Service Centres:

**ZOOM! ZOOM!**

5 Ubi Close Singapore 408605

23 Leng Kee Road Singapore 159095

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Tel: 6603 6116 Service Tel: 6603 6128



MAZDA

## QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN: MOTOR CLAIM DEPT  
 CONTACT NO.: 6507 3848  
 MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B  
 CHASSIS NO.: JM6GL1072K0312254  
 ENGINE NO.: PE21258602  
 REG NO.: SML4662X  
 REGN DATE: 22/05/2019

PAGE NO.: 8  
 DOCUMENT NO.: 2838  
 DOCUMENT DATE: 22/10/2024  
 POS ID: 12  
 PRINTED BY: Wong Chun Wei  
 SERVICE ADV:  
 CSP/OP CODE: Wong Chun Wei  
 DEPT: I  
 WIP NO.: 14099  
 REF. NO.:  
 DATE IN: 03/08/2024  
 EXT. WTY:  
 MILEAGE: 0

## DESCRIPTION:

| Item          | Description                              | Qty. | Unit Price | Stk/Status | Gross amount | GST Code |
|---------------|------------------------------------------|------|------------|------------|--------------|----------|
|               |                                          |      | SGD        |            | SGD          |          |
| GJ6A-50-897   | SPACER                                   | 1.00 | 11.13      | *ISSUED    | 11.13        | S        |
| FB01-63-959   | TERMINAL, BACK WIND.                     | 3.00 | 31.78      | *ISSUED    | 95.34        | S        |
| TK21-50-355   | RIVET                                    | 2.00 | 7.42       | *ISSUED    | 14.84        | S        |
| GRF5-51-153   | GASKET(R), RR.COMB. GL3                  | 1.00 | 52.77      | *ISSUED    | 52.77        | S        |
| GRF5-51-163   | GASKET(L), RR.COMB. GL3                  | 1.00 | 52.77      | *ISSUED    | 52.77        | S        |
| KB7W-34-80XD  | MEMBER, CROSS FRT GL/KF                  | 1.00 | 2,086.24   | *ISSUED    | 2,086.24     | S        |
| GSH7-56-11Y   | COVER, UNDER FRT GL                      | 1.00 | 90.78      | *ISSUED    | 90.78        | S        |
| 9965-16-7570  | WHEEL, DISC 17"X7 GL <i>supl</i>         | 1.00 | 1,222.15   | *ISSUED    | 1,222.15     | S        |
| 11-GSH7-50-71 | MESH, GRILL GL IPM3 <i>ca</i>            | 1.00 | 592.11     | *ISSUED    | 592.11       | S        |
| GHP9-56-396A  | PLATE(L), SEAL F, FENDER GJ/GL <i>lt</i> | 1.00 | 88.76      | *ISSUED    | 88.76        | S        |
| P5E1-18-572   | CONVERTER, DC/DC SKYACTIV <i>shant</i>   | 1.00 | 459.78     | *ISSUED    | 459.78       | S        |
| GBFT-50-M40   | GARNISH(L) REAR DOOR GL <i>ca</i>        | 1.00 | 133.18     | *ISSUED    | 133.18       | S        |
| GJR9-50-M60A  | GARNISH LHR DOOR GL <i>ca</i>            | 1.00 | 69.71      | *ISSUED    | 69.71        | S        |
| D651-33-042A  | NUT, AXLE <i>an</i>                      | 1.00 | 12.98      | *ISSUED    | 12.98        | S        |
| GBFW-32-110   | GEAR, STEERING ASSY GLS <i>lt</i>        | 1.00 | 962.13     | *ISSUED    | 962.13       | S        |
| G46C-34-350J  | ARM LOWER LHF GL <i>lt</i>               | 1.00 | 577.70     | *ISSUED    | 577.70       | S        |
| GCCC-67-290   | CORD, SHORT FRT BUMPER GL <i>no</i>      | 1.00 | 133.60     | *ISSUED    | 133.60       | S        |
| 9965-16-7570  | WHEEL, DISC 17"X7 GL <i>supl</i>         | 1.00 | 1,222.15   | *ISSUED    | 1,222.15     | S        |
| KD35-33-04XF  | HUB, WHEEL FRT BM/GJ/KF <i>lt</i>        | 1.00 | 682.80     | *ISSUED    | 682.80       | S        |

|           | GST Code | Rate  | Service/Goods | GST      |
|-----------|----------|-------|---------------|----------|
| Parts     | 0        | -     |               | -        |
| Surcharge | S        | 9.00% | 42,501.28     | 3,825.12 |
| Labour    |          |       |               |          |
| Menus     |          |       |               |          |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.

|                 | Before GST | GST      | Total     |
|-----------------|------------|----------|-----------|
| Gross           | 42,501.28  | 3,825.12 | 46,326.40 |
| Less: Deposit** | 0.00       | 0.00     | 0.00      |
| Amount Due      | 42,501.28  | 3,825.12 | 46,326.40 |


CASH / NETS / AMEX / VISA / MASTER / CHEQUE  
 No.

\*\*Deposit tax invoice No.:

Date:

Customer signature

Authorised signature



Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
 Tel: 6363 3003, Fax: 6369 3003, BRN: 199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres:

5 Ubi Close Singapore 408605  
 Sales Tel: 6395 8888 Service Tel: 6395 8899  
 Sales Fax: 6846 7900 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095  
 Sales Tel: 6603 6118 Service Tel: 6603 6128  
 Sales Fax: 6476 7073 Service Fax: 6476 7417