

(08/11/13) waf
ASS. REC. BY:

REF: CS/SMR24070195/Rnp3

4200

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SMR 46622

at Workshop m/s

Eurokars

of

Tanjong Pagar

Insured:

SMR

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

93k

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMR 46622

Yr Regn:

2019 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAZDA 6 SEDAN 2.0 AT GLE c.c. 1998

Colour

BLACK

AC:

Insured / Std / NI / NA

Sp. Reading

35284

TRadio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6L1072K032254

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

06/07/24

D.O.I.

06/07/24

Survey held at

TANJONG P

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRT & N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair in Lim 11-53K

Date/Time, File Pass to?

☐
☐

: Prel. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐
☐
☐
☐

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

) \$ + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B
CHASSIS NO.: JM6GL1072K0312254
ENGINE NO.: PE21258602
REG NO.: SML4662X
REGN DATE: 22/05/2019

PAGE NO.: 1
DOCUMENT NO.: 2465
DOCUMENT DATE: 09/07/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: 1
WIP NO.: 14099
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	MS FIRST TP CLAM				0.00	O
SUB	TO REMOVE & REPLACE FRT BUMPER, GRILLE TOP, BONNET, FRT FENDER RH, FRT FENDER LH, FRT SUPPORT PANEL, FRT DOOR LH, REAR DOOR LH, REAR FENDER LH & REAR BUMPER. AND ALL ACCIDENT AFFECTED AREA.	@792X10-			11,880.00	S
					7920	
SUB	TO RESPRAY FRT BUMPER, GRILLE TOP, BONNET, FRT FENDER RH, FRT FENDER LH, A PILLAR LH, FRT DOOR LH, REAR DOOR LH, REAR FENDER LH, REAR BUMPER & ROCKER PANEL LH.	@756X7'S			11,340.00	S
					5670	
SUB	TO SUPPLY FRT NUMBER PLATE.				X 70.00	S
SUB	TO TRANSFER FRONT SENSORS.				180 330.00	S
SUB	TO TRANSFER THE DOOR MECHANISM.				396 792.00	S
SUB	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.				396 792.00	S
SUB	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.				560.00	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606

Service Fax: 6331 0620



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY

#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT

CONTACT NO.: 6507 3848
MODEL: MAZDA6 1PM 2L SDN EXECUTIVE B
CHASSIS NO.: JM6GL1072K0312254
ENGINE NO.: PE21258602
REG NO.: SML4662X
REGN DATE: 22/05/2019

PAGE NO.: 2
DOCUMENT NO.: 2465
DOCUMENT DATE: 09/07/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV: Lee Yao Sheng
CSP/OP CODE: I
DEPT: 14099
WIP NO.:
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price SGD	Stk/Status	Gross amount SGD	GST Code
SUB	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.				120.00	S
SUB	TO REMOVE & REPLACE THE WIRE HARNESS ASSY.				792.00	S
SUB	TO REMOVE & REPLACE UNDERCARRIAGE.				792.00	S
SUB	TO REMOVE & REPLACE ABS HYDRAULIC UNIT ASSY AND BRAKE PIPING.				792.00	S
SUB	TO REMOVE & INSTALL ENGINE ASSY FOR ACCESS.				2,376.00	S
SUB	TO REALIGN BODY CHASSIS ALIGNMENT.				2,376.00	S
SUB	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.				120.00	S
SUB	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.				560.00	S
SUB	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.				250.00	S
SUB	TO MOUNT CAR ON CAR O LINER AND REALIGN THE CAR BODY ACCORDING MAZDA SPECIFICATION.				1,500.00	S

"This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

"Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147

Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606

Service Fax: 6331 0620

**MAZDA**

QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN: MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B
 CHASSIS NO.: JM6GL1072K0312254
 ENGINE NO.: PE21258602
 REG NO.: SML4662X
 REGN DATE: 22/05/2019

PAGE NO.: 3
 DOCUMENT NO.: 2465
 DOCUMENT DATE: 09/07/2024
 POS ID: 12
 PRINTED BY: Lee Yao Sheng
 SERVICE ADV: Lee Yao Sheng
 CSP/OP CODE: 1
 DEPT: 14099
 WIP NO.:
 REF. NO.:
 DATE IN:
 EXT. WTY:
 MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
SUB	TO CONDUCT BRAKE SYSTEM CHECKING USING SPECIFIC BRAKING TEST MACHINE.				792.00	S
SUB	TO SUPPLY 2 PC TIRE <i>CLIP 7-26</i>			496	1,400.00	S
SUB	TO CARRY OUT BODY CAVITY PRESERVATION.				250.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150	250.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			250	300.00	S
SUB	SUNDRIES.			20	50.00	S
GSJ8-50-031 BB	FRT BUMPER GL3 W/PS <i>turn</i>	1.00	1,177.81	STOCK	1,177.81	S
C274-50-133	NUT, CLIP <i>new</i>	12.00	2.36	STOCK	28.32	S
BBM4-50-355	RIVET <i>new</i>	4.00	3.71	STOCK	14.84	S
S51S-51-833	RIVET, SPLASH SHIELD <i>new</i>	8.00	3.12	STOCK	24.96	S
GHP9-50-0Z5	GROMMET, SCREW <i>new</i>	2.00	2.36	STOCK	4.72	S
B45A-56-146A	FASTENER <i>new</i>	2.00	2.36	STOCK	4.72	S
F189-51-356A	SPRING <i>new</i>	2.00	9.28	STOCK	18.56	S
GSH7-50-M42	CAP(L) GL <i>M13</i>	1.00	73.00	STOCK	73.00	S
GBVG-50-131	PROTECTOR(L), BUMPER GL3 <i>M15</i>	1.00	79.23	STOCK	79.23	S
GSH7-50-102	COVER LHF BUMPER GL3 <i>M15</i>	1.00	24.87	STOCK	24.87	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147

Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6118

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Sales Tel: 6331 0606

ZOOM-ZOOM



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY

#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT

CONTACT NO.: 6507 3848
MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B
CHASSIS NO.: JM6GL1072K0312254
ENGINE NO.: PE21258602
REG NO.: SML4662X
REGN DATE: 22/05/2019

PAGE NO.: 4
DOCUMENT NO.: 2465
DOCUMENT DATE: 09/07/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 14099
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross GST	
					amount	Code
			SGD		SGD	
GRF2-50-0S0A	STIFF'A', BUMPER GL3 <i>turn</i>	1.00	119.35	STOCK	119.35	S
GHP9-50-0U1C	RETAINER LHF BUMPER GJ/GL <i>cm</i>	1.00	14.84	STOCK	14.84	S
GSH7-50-104	COVER(L), BUMPER GL3 <i>mis</i>	1.00	36.50	STOCK	36.50	S
GSH7-50-1V0	PLATE(L), SEAL-F. BUMPER GL <i>mis</i>	1.00	95.25	STOCK	95.25	S
G48F-50-111	FOAM, BUMPER-FRONT GL <i>cm</i>	1.00	73.00	STOCK	73.00	S
FD01-68-AC3	FASTENER <i>cm</i>	2.00	5.31	STOCK	10.62	S
GSH7-50-070	REINF., FRT BUMPER GL3 <i>cm</i>	1.00	563.37	STOCK	563.37	S
GSK1-50-170	HOLDER, LIC GL <i>X</i>	1.00	111.77	STOCK	111.77	S
KD47-67-UC5A	RETAINER S/ACTIV <i>mis</i>	1.00	15.77	STOCK	15.77	S
KD47-67-UC1	5.SENSOR, ULTRASONIC <i>mis</i>	1.00	184.59	STOCK	184.59	S
GHP9-50-0U1C	RETAINER LHF BUMPER GJ/GL <i>mis</i>	1.00	14.84	STOCK	14.84	S
GSH7-50-7K0D	MOULD LHF LWR BUMPER GL3 <i>cm</i>	1.00	303.10	*NO STOCK	303.10	S
GSH7-50-719	MESH, GRILL GL IPM3 <i>cm</i>	1.00	592.11	STOCK	592.11	S
GSH7-50-EB1	CLIP <i>cm</i>	1.00	9.28	STOCK	9.28	S
GSH7-50-712B	REINF. RADIATOR GRILLE GL <i>cm</i>	1.00	161.58	STOCK	161.58	S
GSH7-50-161	BRACKET LHF BUMPER GL <i>mis</i>	1.00	44.76	STOCK	44.76	S
G46L-50-EB1	CLIP <i>cm</i>	4.00	4.64	STOCK	18.56	S
GSK1-50-191	BRACKET GRILL GL <i>cm</i>	1.00	15.77	STOCK	15.77	S
KD45-50-1K5A	PIN, LOCATOR <i>?</i>	2.00	2.36	STOCK	4.72	S
EA01-50-037	RIVET <i>cm</i>	4.00	7.34		29.36	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147

Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461300 Service Fax: 6744 8402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7033 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606

Service Fax: 6331 0600

ZOOM-ZOOM



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B
CHASSIS NO.: JM6GL1072K0312254
ENGINE NO.: PE21258602
REG NO.: SML4662X
REGN DATE: 22/05/2019

PAGE NO.: 5
DOCUMENT NO.: 2465
DOCUMENT DATE: 09/07/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: 1
WIP NO.: 14099
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross GST	
					amount	Code
			SGD		SGD	
GSH7-50-162	BRACKET(L),F. BUMPER SIDE GL3 <i>MS</i>	1.00	44.76	STOCK	44.76	S
KD45-50-ES1	GROMMET <i>MS</i>	2.00	2.36	STOCK	4.72	S
GSH7-50-152	BRACKET RHF BUMPER SIDE GL3 <i>MS</i>	1.00	44.76	STOCK	44.76	S
GD7A-50-EA1	FASTENER <i>MS</i>	4.00	2.62	STOCK	10.48	S
TK21-50-355	RIVET <i>MS</i>	6.00	7.42	STOCK	44.52	S
GSH7-50-717A	BRACKET,GRILLE-RADIA GL3 <i>MS</i>	1.00	114.63	STOCK	114.63	S
GSH7-50-7E1 33	GRILLE,UP.RADIATOR GL3 <i>MS</i>	1.00	482.37	STOCK	482.37	S
GSH7-50-163	BRACKET LHF BUMPER GL3 <i>MS</i>	1.00	14.84	STOCK	14.84	S
GSH7-50-153	BRACKET RHF BUMPER GL3 <i>MS</i>	1.00	14.84	STOCK	14.84	S
S51S-51-833	RIVET,SPLASH SHIELD <i>MS</i>	8.00	3.12	STOCK	24.96	S
GSH7-50-7J0D	MOULD RHF LWR BUMPER GL3 <i>MS</i>	1.00	303.10	STOCK	303.10	S
GBFN-50-716	BRACKET,RAD.GRILLE GL <i>MS</i>	1.00	128.37	STOCK	128.37	S
G46L-51-730	MASCOT,FRT GJ/GL <i>MS</i>	1.00	66.51	STOCK	66.51	S
GRG1-50-164	BRACKET LHF GRILL GL <i>MS</i>	1.00	15.77	STOCK	15.77	S
S51S-51-833	RIVET,SPLASH SHIELD <i>MS</i>	8.00	3.12	STOCK	24.96	S
GRF5-51-075A	PROTECTOR LHF HL GL3 <i>MS</i>	1.00	123.15	STOCK	123.15	S
GSK4-51-041B	HEADLAMP LH IPM3 GL <i>MS</i>	1.00	5,460.29	STOCK	5,460.29	S
GSH7-50-ACYA	BRACKET LHF HL GL3 <i>MS</i>	1.00	15.77	STOCK	15.77	S
GSH7-50-ACXA	BRACKET(L),HEAD LAMP GL3 <i>MS</i>	1.00	37.01	STOCK	37.01	S
GRF5-51-0A1	COVER,SOCKET GL <i>MS</i>	1.00	13.91	STOCK	13.91	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN:MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B
 CHASSIS NO.: JM6GL1072K0312254
 ENGINE NO.: PE21258602
 REG NO.: SML4662X
 REGN DATE: 22/05/2019

PAGE NO.: 6
 DOCUMENT NO.: 2465
 DOCUMENT DATE: 09/07/2024
 POS ID: 12
 PRINTED BY: Lee Yao Sheng
 SERVICE ADV:
 CSP/OP CODE: Lee Yao Sheng
 DEPT: 1
 WIP NO.: 14099
 REF. NO.:
 DATE IN:
 EXT. WTY:
 MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
B092-51-833	RIVET <i>an</i>	2.00	2.95	STOCK	5.90	S
B1Y4-67-SH3	CORD,SHORT DJ/BM/BP/DM/KG/TC <i>cut</i>	1.00	60.52	STOCK	60.52	S
GHP9-52-211A	FENDER LHF GJ/GL <i>bm</i>	1.00	372.97	STOCK	372.97	S
GRF2-56-140	GUARD LHF MUD GL3 <i>ms</i>	1.00	123.15	STOCK	123.15	S
GHP9-52-240D	STAY(L),FENDER GJ/GL <i>ms</i>	1.00	58.33	STOCK	58.33	S
B45A-56-146A	FASTENER <i>an</i>	21.00	2.36	*NO STOCK	49.56	S
GJ21-68-885B02	FASTENER <i>an</i>	3.00	2.36	STOCK	7.08	S
GRF2-56-115	SHIELD(L),SPLASH GL3 <i>ms</i>	1.00	16.69	STOCK	16.69	S
GBY0-52-31XB	BONNET GL3 <i>bt</i>	1.00	1,228.97	STOCK	1,228.97	S
TD11-56-694	FASTENER,BONNET <i>an</i>	11.00	2.36	STOCK	25.96	S
BC1D-58-762	FASTENER <i>an</i>	20.00	2.70	STOCK	54.00	S
GHP9-56-770	WTHSTP,PARTING SEAL GJ/GL <i>cut</i>	1.00	106.63	STOCK	106.63	S
J001-56-741	RIVET <i>an</i>	22.00	1.86	STOCK	40.92	S
P5E1-18-572	CONVERTER.DC/DC SKYACTIV ?	1.00	459.78	STOCK	459.78	S
PE05-18-58Z	BRACKET GJ <i>bt</i>	1.00	15.77	STOCK	15.77	S
KD45-67-B1XA	BRACKET,HARNES KE <i>bt</i>	1.00	13.91	*NO STOCK	13.91	S
GRT8-66-750	BLOCK,RELAY GL/KF/KG	1.00	68.95	STOCK	68.95	S
9965-16-7570	WHEEL,DISC 17"X7 GL <i>scr (1pc) rear</i>	2.00	1,222.15	STOCK	2,444.30	S
GHY0-59-02XJ	LHF DOOR GJ/GL <i>repair</i>	1.00	1,126.65	STOCK	1,126.65	S
TK48-59-762	FASTENER(L) <i>an</i>	1.00	9.28		9.28	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147

Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606

zoom-zoom



QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN: MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA6 1PM 2L SDN EXECUTIVE B
 CHASSIS NO.: JM6GL1072K0312254
 ENGINE NO.: PE21258602
 REG NO.: SML4662X
 REGN DATE: 22/05/2019

PAGE NO.: 7
 DOCUMENT NO.: 2465
 DOCUMENT DATE: 09/07/2024
 POS ID: 12
 PRINTED BY: Lee Yao Sheng
 SERVICE ADV:
 CSP/OP CODE: Lee Yao Sheng
 DEPT: I
 WIP NO.: 14099
 REF. NO.:
 DATE IN:
 EXT. WTY:
 MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	SGD	Stk/Status	Gross amount	GST Code
						SGD	
GJ6A-58-975	GROMMET, SCREW <i>ne</i>	9.00	2.36	21.24	STOCK		S
GJR9-69-16YB	GARNISH(L), SAIL-OUT GJ/GL <i>X</i>	1.00	125.08	125.08	STOCK		S
GBFT-50-M20	GARNISH LHF DR GL <i>X</i>	1.00	119.35	119.35	STOCK		S
GBFT-50-M40	GARNISH(L) REAR DOOR GL <i>X</i>	1.00	133.18	133.18	STOCK		S
GJR9-50-M60A	GARNISH LHR DOOR GJ <i>X</i>	1.00	69.71	69.71	STOCK		S
GHP9-50-4R2A	GUARD STONE LHR GJ <i>cut</i>	1.00	15.77	15.77	STOCK		S
GHY1-73-02XB	DOOR LHR GJ/GL <i>st</i>	1.00	1,275.33	1,275.33	STOCK		S
TK48-73-762	FASTENER(L), WEATHERSTRIP <i>ne</i>	1.00	9.28	9.28	STOCK		S
GBFN-73-763	FASTENER(L), WEATHERSTRIP <i>ne</i>	1.00	9.28	9.28	STOCK		S
GJ6A-58-975	GROMMET, SCREW <i>ne</i>	7.00	2.36	16.52	STOCK		S
GSY7-71-41X	FENDER LHR GL3 <i>st</i>	1.00	1,506.02	1,506.02	STOCK		S
GHK1-50-611B	MOULD, RR WINDOW GL <i>ne</i>	1.00	126.01	126.01	STOCK		S
GJ6A-50-897	SPACER <i>ne</i>	1.00	11.13	11.13	STOCK		S
FB01-63-959	TERMINAL, BACK WIND. <i>ne</i>	3.00	31.78	95.34	STOCK		S
TK21-50-355	RIVET <i>ne</i>	2.00	7.42	14.84	STOCK		S
GRF5-51-153	GASKET(R), RR.COMB. GL3 <i>ne</i>	1.00	52.77	52.77	STOCK		S
GRF5-51-163	GASKET(L), RR.COMB. GL3 <i>ne</i>	1.00	52.77	52.77	STOCK		S
FTH1-25-60X	SHAFT LHF DRIVE KF/KG/GL5 <i>?</i>	1.00	1,609.44	1,609.44	STOCK		S
D651-33-042A	NUT, AXLE <i>?</i>	1.00	12.98	12.98	STOCK		S
KD35-33-04XF	HUB, WHEEL FRT BM/GJ/KF <i>?</i>	1.00	682.80	682.80	STOCK		S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147

Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

Showrooms & Service Centres :

23 Leng Kee Road Singapore 159095

Tel: 6395 8888 Service Tel: 6395 8899

27A Tanjong Penjuru Singapore 609042

Sales Tel: 6603 6118 Service Tel: 6603 6128

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B
CHASSIS NO.: JM6GL1072K0312254
ENGINE NO.: PE21258602
REG NO.: SML4662X
REGN DATE: 22/05/2019

PAGE NO.: 8
DOCUMENT NO.: 2465
DOCUMENT DATE: 09/07/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV: Lee Yao Sheng
CSP/OP CODE: 1
DEPT: 14099
WIP NO.:
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD	STOCK	SGD	
KD45-33-271C	COVER(L),DUST GL/DK/KF ?	1.00	34.31	*NO STOCK	34.31	S
GBFN-33-031	KNUCKLE LHF GL ?	1.00	455.57	*NO STOCK	455.57	S
GHP9-43-990	HOSE FLEXIBLE LHF GJ/GL ?	1.00	84.29	STOCK	84.29	S
GBEF-32-290	JOINT(L) STRG GL ?	1.00	143.96	STOCK	143.96	S
T060-26-169A	PIN,SNAP ?	1.00	5.74	STOCK	5.74	S
GBFW-32-110	GEAR,STEERING ASSY GL5 ?	1.00	962.13	STOCK	962.13	S
G46C-34-350J	ARM LOWER LHF GL ?	1.00	577.70	STOCK	577.70	S
GBJD-34-900A	DAMPER LHF GL ?	1.00	449.92	STOCK	449.92	S
KB7W-34-80XD	MEMBER,CROSS FRT GL/KF ✓	1.00	2,086.24	STOCK	2,086.24	S
KD35-34-170	LINK,CONTROL FRT GJ/GL/KE/KF/TC ?	1.00	72.32	STOCK	72.32	S
GBFN-34-15XA	STABILIZER,FRONT GL ?	1.00	667.72	STOCK	667.72	S
GSH7-53-150	MEMBER,SHROUD-UPPER GL3 ?	1.00	139.24	STOCK	139.24	S
GHP9-52-15YA	STAY,LOCK GJ/GL ?	1.00	44.51	STOCK	44.51	S
GHP9-53-110B	PANEL SHROUD GL3 ?	1.00	479.34	STOCK	479.34	S
GSH7-50-R10	GRILLE,UNDER GL3 ?	1.00	877.08	STOCK	877.08	S
GSH7-50-1C0B	PLATE,SET GL ?	1.00	188.97	STOCK	188.97	S
GD7A-50-EA1	FASTENER ?	4.00	2.62	STOCK	10.48	S
GBEF-51-PC1	MLDG(L),FENDER-FRT GL3 X	1.00	15.77	STOCK	15.77	S
GSH7-56-11Y	COVER,UNDER FRT GL de ✓	1.00	90.78	STOCK	90.78	S
B61K-56-110A	COVER,UNDER BM/BN/GL ?	1.00	322.99	STOCK	322.99	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147

Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

Showrooms & Service Centres :
23 Leng Kee Road Singapore 159095

23 Leng Kee Road Singapore 159095

Eurokars Aftersales Centre:
27A Tanjong Penjuru Singapore 609042



QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN: MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA6 IPM 2L SDN EXECUTIVE B
 CHASSIS NO.: JM6GL1072K0312254
 ENGINE NO.: PE21258602
 REG NO.: SML4662X
 REGN DATE: 22/05/2019

PAGE NO.: 9
 DOCUMENT NO.: 2465
 DOCUMENT DATE: 09/07/2024
 POS ID: 12
 PRINTED BY: Lee Yao Sheng
 SERVICE ADV: Lee Yao Sheng
 CSP/OP CODE: 1
 DEPT: 14099
 WIP NO.:
 REF. NO.:
 DATE IN:
 EXT. WTY:
 MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
11-BF25-W0-03:BRAKE FLUID D3 0.33L		6.00	11.55	*NO STOCK	69.30	S
GCCD-67-010C HARNESS FRT GL		1.00	9,970.30		9,970.30	S

Resur
Hp 90010068
16 days
P/P
11/07/24
Resy LF paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	* GST Code	Rate	Service/Goods	GST
Parts 40,856.71	O	-		-
Surcharge 0.00	S	9.00%	80,132.71	7,211.94
Labour 39,276.00				
Menus 0.00				

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

	Before GST	GST	Total
Gross	80,132.71	7,211.94	87,344.65
Less: Deposit**	0.00	0.00	0.00
Amount Due	80,132.71	7,211.94	87,344.65

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
 No.

Date:

Customer signature

Authorised signature



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147

Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	420D
Vehicle Details	
Vehicle No.:	SML4662X
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jul 2024
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 SEDAN 2.0 AT EXECUTIVE 2WD
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	PE21258602
Chassis No.:	JM6GL1072K0312254
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$21,917.00
Original Registration Date:	22 May 2019
First Registration Date:	22 May 2019
Transfer Count:	0
Actual ARF Paid:	\$22,684.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 May 2029
PARF Rebate Amount:	\$15,878.00
Intended COE Rebate Details	
COE Expiry Date:	21 May 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,010.00
COE Rebate Amount:	\$23,308.00
Total Rebate Amount:	\$39,186.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 13 Jul 2024

OK



Mazda 6 2.0A Executive


\$92,800 Instalment \$1,274/mth

PREMIUM AD

♡ Shortlist

✓ Get Warranty

📄 Loan Calculator



Overview Financial Photo Research

Depreciation	ⓘ \$16,520 / year
Reg. Date	12-Jun-2019 (4yrs 10mths 29days COE left)
Manufactured	ⓘ 2018
Mileage	<u>78,798 km</u> (15.5k / year)
Transmission	Auto
Engine Cap	1,998 cc
Road Tax	ⓘ \$1,210 / year
Power	121.0 kW (162 bhp) View specs of the Mazda 6 Sedan (2018)
Curb Weight	ⓘ <u>1,515 kg</u>
COE	ⓘ \$48,209
OMV	ⓘ \$22,282
ARF	ⓘ \$23,195
Dereg Value	ⓘ \$39,932 as of today