

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEEONG RIII DING
SINGAPORE 048081
Registration No : SLF4091L
Chassis No : JHMRU1830GX200239
Model : HRV 1 X-SIN CVT YM 2016
Owner's Name : TAN KIM HWEE
Ins Policy No. :
Date of Accident : 7/6/2024

Document No. : SQT24001619 Page 1
Date : 11. Jun 2024
Svc Advisor :
Engine No : L15B4530240
Date | Time : 11. Jun 2024 1:29:10 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST	Amount
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	TP INSURER:						
	TP VEH:						
Reverse Sensor	Reverse Sensor an X NN	1	320				
BO-WS-SEALANT	WINDSCREEN SEALANT (N) X NN	2	60.00		120.00	10.80	130.80
91505-TM8-003	CLIP,BUMPER X NN	14	2.30	25	24.15	2.17	26.32
75722-T7W-A01	EMBLEMRR. X NN	1	16.10	25	12.07	1.09	13.16
04715-T7A-900ZZ	FACE,RR.BUMPER X NN	1	494.40	25	370.80	33.37	404.17
33505-T7A-J01	REFLECTOR ASSYR.RR. X NN	1	189.20	25	141.90	12.77	154.67
33555-T7A-J01	REFLECTOR ASSYL.RR. X NN	1	189.20	25	141.90	12.77	154.67
71593-T9A-J00	SPACER R.RR.BUMPER SIDE X NN	1	11.50	25	8.62	0.78	9.40
71598-T9A-J00	SPACERL.RR.BUMPER SIDE X NN	1	11.50	25	8.62	0.78	9.40
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER X NN	1	105.90	25	79.42	7.15	86.57
04636-T7A-300ZZ	PANEL SETR.RR.OUTSIDE X NN	1	690.90	25	518.17	46.64	564.81
BOSUN	SUNDRIES	1	110.00		110.00	9.90	119.90
BOBC	BODY UNDERSIDE COATING (N)	1	520.00		520.00	46.80	566.80
BOJSE	SEALANT FOR REAR END PANEL X NN	1	120.00		120.00	10.80	130.80

Printed on 11/07/2024 1:38:57 PM

This is a computer generated quote, no signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Group)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No: M200050223

Company No: 2000120001

Customer: **WAT FIRST CAPITAL INSURANCE LIMITED**
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Document No. : SQT24001619 Page 2
Date : 11. Jun 2024
Customer No. : WZF002
Svc Advisor :
Engine no : L15D4530240
Date | Time : 11. Jun 2024 1:29:10 PM
Surveyor Name :
Survey Date :
Authorization Code :

Chassis No : JHMRU1830GX200239
Model : HRV LX-SIN CVT YM 2016
Owner's Name : TAN KIM HWEE
Date of Accident : 7/6/2024

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount Incl'd GST
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		250.00	22.50	272.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00		250.00	22.50	272.50
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	520.00		520.00	46.80	566.80
BP00R	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	1	650.00		650.00	58.50	708.50
BKBU01R	WINDSCREEN DAMKIT	1	120.00		120.00	10.80	130.80
BKBU01R	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	1	650.00		650.00	58.50	708.50
BKBU01R	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	650.00		650.00	58.50	708.50
	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		650.00	58.50	708.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	58.50	708.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00		4000.00	360.00	4360.00
	CUT OFF & RENEW RR PANEL STRAIGHTEN RR FENDERS AN	1	5000.00		5000.00	450.00	5450.00
Sum Labor					14260.00	1,283.40	15,543.40

Date & Time

Excess

Signature

Total Amount 16,152.29 1,453.71 17,606.00

Total (Inclusive of GST) 17,606.00

KK Auto Consultants hence notify the Reparer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Date:

This is a computer generated invoice. No signature is required.

Part prices are subject to change without notice.


The above estimated cost of repair do not include any collection charges.

GST is included in the above estimate.

This quotation is valid for the purpose of quotation above \$2000.00.

However, if the repair was subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

All quotations and prices are subject to GST adjustment from 0% to 9% with effect from 1st Jan 2024.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No: M200050223

Company Ref. No: S60FC1380G

Customer: CU0098198 / TAN KIM HWEE
Chassis No: JHMRU1830GX200239
License No: SLF4091L
Mileage: 40854
Engine No: L15B4530240

Document No: SVO24022965
Printed By: SHNG
Order Date: 19. June 2024
Order Time: 1:11:26 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	9% GST Amount incld Amount	Amount incld GST
	SUPPLEMENTARY						
42700-T7A-J92	DISK,ALUMINIUM WHEEL <i>cut</i>	1	852.90	25	639.67	57.57	697.24
90103-TA0-000	SCREW TAPPING 5 X 20 <i>ne</i>	2	4.30	25	6.45	0.58	7.03
91501-T2A-003	CLIPINNER FENDER <i>ne</i>	3	0.40	25	0.90	0.08	0.98
91501-TR0-003	CLIP,INNER FENDER <i>ne</i>	4	2.80	25	8.40	0.76	9.16
75450-SAA-013	OUTLETRR AIR <i>com</i>	1	27.50	25	20.62	1.86	22.48
	SUM PARTS:				676.04	60.85	736.89
BOJSE	1466	1	120.00		120.00	10.80	130.80
	SEALANT FOR RHR FENDER <i>ne</i> ne <i>NN</i>						
	SUM LABOUR:				120.00	10.80	130.80
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4 <i>ne</i>	1	220.00		220.00	19.80	239.80
	SUM EXT SERVICE:				220.00	19.80	239.80
	TOTAL SGD				1,016.04	91.45	1,107.49

Total Payable (SGD)

1,107.49

GST Amount is calculated from individual line(s)