



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 47029

Customer :

GREAT AMERICAN INSURANCE COMPANY, SINGAPORE BRANCH
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

DATE : 10/07/2024
CLAIM NO. : 12534
POLICY NO. : MC/01009082/02
FROM : RAYMOND

VEHICLE NO. : FBN5529L
MAKE/MODEL : YAM / NMAX155 ABS

*not authorized
in
may
11/7/24
2/5 \$320
2 days
telephone after up*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	LABOUR P/N: 06766	Supply/Install	2.00	\$85.00	170.00
2	LAMP TAIL ASSY P/N: 60928 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$254.00	254.00
3	MUDGUARD REAR P/N: 60932 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$57.00	57.00
4	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
5	TRANSPORT CHARGES P/N: 07169		1.00	\$62.00	62.00

SUB TOTAL \$574.00
GST @ 9 % \$51.66
GRAND TOTAL (SGD) \$625.66

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



RAYMOND

*47029 *

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Acknowledge & Accepted By

*P-342
102
307.80
100
407.80
202
326*



bizSAFE₃

