



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref:	CS/SMO24070198/Anp3m4 (N)
50 RAFFLES PLACE #03-03			Date:	21/04/2025
SINGAPORE LAND TOWERSINGAPORE 048623			Code:	SMO
ATTN: PAU LOONG				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 7217R	Veh. Inspected	YN 7973B	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2402256/GPL	Excess (\$)	0.00	
Assign From	IRENE HENRY	Assign Date	10/07/2024	
2. Vehicle Particulars & Condition				
Make & Model	HINO XZU710R-HKFMS3	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JHHUCS3H60K011804	Colour	WHITE	
Odometer	220987 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	7.00R16	BRIDGESTONE	6 mm	
L/H Front Tyre	7.00R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	7.00R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	7.00R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/07/2024	Inspection Date	12/07/2024	
Survey held at	AUTOMOBILE HUB ENTERPRISE			
	1 KAKI BUKIT AVENUE 6			
	#01-15 AUTOBAY			
	SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	