

AUTOMOBILE HUB ENTERPRISE

TO	: SOMPO	DATE	12/7/2024
VEHICLE NO	: YN7973B	<i>Hui Rong</i>	
VEHICLE MODEL	: HINO XZU710R		
CHASSIS NO	: JHHUCS3H60K011804		

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR DOOR <i>Dented.</i>	1	\$ 2,200.00	\$ 2,200.00 <i>1400</i>
2	REAR Door LOCK BAR	1	\$ 480.00	\$ 480.00 <i>+</i>
3	REAR DOOR LOCK BAR BRACKET <i>2 x AP</i>	3	\$ 100.00	\$ 300.00 <i>+</i>
5	REAR DOOR LOCK HANDLE <i>1 x H</i>	1	\$ 380.00	\$ 380.00 <i>+</i>
6	REAR DOOR HINGE <i>Bent</i>	2	\$ 350.00	\$ 700.00 <i>500</i>
7	REAR DOOR PILLAR <i>Repair</i>	1	\$ 1,200.00	\$ 1,200.00 <i>+</i>
8	SIDE BODY PANEL LOWER <i>Dented.</i>	1	\$ 3,000.00	\$ 3,000.00 <i>1600</i>
<i>3500</i>			TOTAL :	\$ 8,260.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00 <i>500</i>		
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>x</i>	
3	WIRING CHECK	\$ 50.00	<i>x</i>	
4	TO APPLY TUFF COAT	\$ 200.00	<i>x</i>	
TOTAL:		\$ 2,450.00	<i>500</i>	

ESTIMATE REPORT

TOTAL PARTS COST:	\$	8,260.00
TOTAL LABOUR COST:	\$	2,450.00
TOTAL REPAIR COST:	\$	10,710.00

Total: 4000
1/3: 32K
050 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: