

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

liusbro@ymail.com

Tel: 67411730

ESTIMATE

Name: **ALG Asia Pacific Insurance Pte Ltd**

Ref Date:

12/07/2024

Address Motor Claims Department

Ref No:

GBF1691T240705

78 Shenton Way #07-16

Vehicle No:

GBF1691T

ALG Building

Singapore 079120

Model / Make:

Mitsubishi Canter

Capacity: 2998 cc

FEA01BR1SDEB (CBU)

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Front Rh	Door Body ID	\$ 2,001.50	1	\$ 2,001.50		✓
2		Door Outer Garnish Toen	\$ 370.00	1	\$ 370.00		✓
3		Door Handle 11	\$ 136.00	1	\$ 136.00		X
4		Bumper Side N/S n o/s oe/toen	\$ 441.70	2	\$ 883.40		1 pc
5		Bumper Side Clips 2 set 11	\$ 45.00	2	\$ 90.00	SN	X
6		Signal Lamp o/s One	\$ 312.60	2	\$ 627.20		✓
7		Signal Lamp Clips 2 set 11	\$ 20.00	2	\$ 40.00	SN	X
8		Head Lamp Grille (Cover) side lamp o/s one	\$ 581.00	1	\$ 581.00		✓
9		Step Panel Lower o/s Daye	\$ 613.20	1	\$ 613.20		✓
10		To check all wiring & electrical component for proper function	(252)		\$ 20.00		✓
11		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 500.00		380
12		To putty & spray painting & including touch up paint on accident affected areas			\$ 400.00		300
						P-	3598.77
							25%
							2699.07
						L-	700
							3399.07
							202
							2719

Total Parts & Labour of estimate for damaged vehicle

\$ 6,262.30

Total amount in Lumpsum Basis for repaired vehicle**SDL**

Liu's Bro Auto Engrg Wks

Not Authorized
in
mccas
12/7/24
4/5 @ 2700 |
3 days.
take photo of my