FINAL COST OF REPAIR

(To be completed for only one type of item)

То:			From:		Ref BB73			
HD TPT CENTRE EAST, TPTHUBEAST SELARANG NODE RESOURCE SUP IC, TPTHUBEAST Unit			_	DC 34 3AMB Base/LEO Area Office				
Description of Item: TRK,CARGO		O:5 TONS,M.A.N. 16.284 LAERC	•	SAF 1	222:	: BB70(THE/SELG)/D/32/24		
Part/Reg No:	MID20800	Original Value:	-	Date:			10 July 2024	
Quantity:	01	CE/Non CE:	-	SAF 1204/SAF1351:		4/SAF1351:	8203091763	
		l		Date:			10 July 2024	
Description of Damages and Costs of Repairs:				Accide Date:	nt Job	No:	8203091763 10 July 2024	
S/N Incident Repair 1) RHR REFLECTOR RIPPED OFF 2) TAILBOARD RUBBER STOPPER BRKT BENT 3) TORQUE ALL WHEEL NUTS 4) QCI OUT INSPECTION						Man-hours 0.50 1.00 1.50 1.00		
<u>S/N</u> 1) REFLECTOR,I	<u>Unit Price</u>	<u>Qty</u> 1		<u>COST</u> \$5.21				
Base/LEO Area Office's Assessment of Damages								
Labour Charges @ \$79.48 per hour X 4.00 he Total Cost of Parts / Materials Used Sub-contractor Assessment Fee Towing Service Total				= = = = =		\$317.92 \$5.21 - - - \$323.13	_	
Estimated Time for Repair:				4.0hrs				

*Delete whichever is not applicable FINAL COST OF REPAIR

