

FINAL COST OF REPAIR

(To be completed for only one type of item)

To:		From:		Ref	BB73
HD TPT CENTRE EAST, TPTHUBEAST SELARANG NODE <u>RESOURCE SUP IC, TPTHUBEAST</u> Unit		DC 34 3AMB <u>Base/LEO Area Office</u>			
Description of Item:		TRK,CARGO:5 TONS,M.A.N. 16.284 LAERC		SAF 1222:	BB70(THE/SELG)/D/32/24
Part/Reg No: MID20800		Original Value: -		Date:	10 July 2024
Quantity: 01		CE/Non CE: -		SAF 1204/SAF1351:	8203091763
				Date:	10 July 2024
Description of Damages and Costs of Repairs:				Accident Job No: 8203091763	
				Date: 10 July 2024	
<u>S/N</u>	<u>Incident Repair</u>	<u>Man-hours</u>			
1)	RHR REFLECTOR RIPPED OFF	0.50			
2)	TAILBOARD RUBBER STOPPER BRKT BENT	1.00			
3)	TORQUE ALL WHEEL NUTS	1.50			
4)	QCI OUT INSPECTION	1.00			
<u>S/N</u>	<u>Materials Cost</u>	<u>Unit Price</u>	<u>Qty</u>	<u>COST</u>	
1)	REFLECTOR,INDICATING,CLEARANCE:W/PVC RIM		1	\$5.21	
Base/LEO Area Office's Assessment of Damages					
Labour Charges @ \$79.48 per hour X 4.00 hrs		=	\$317.92		
Total Cost of Parts / Materials Used		=	\$5.21		
Sub-contractor		=	-		
Assessment Fee		=	-		
Towing Service		=	-		
Total			<u>\$323.13</u>		
Estimated Time for Repair:				4.0hrs	

4.0hrs

*Delete whichever is not applicable

FINAL COST OF REPAIR

TAN

KEAN LYE

Digitally signed
by TAN KEAN
LYE
Date: 2024.07.25
16:08:24 +08'00'