

A.I. Generated Report



Case Information

Outcome	Total Loss
IVI Reference	2284139
IAAI Reference	SJP2435M



Vehicle Information

VIN	JMYSTCY4A9U000561
Registration Number	SJP2435M
Body Type	
Brand	Mitsubishi
Model	Lancer EX 2.0 (A)
Fuel Type	
Transmission	
Number of doors	
Paint Color	
Year	2009

[illegible]





Pictures



! Damages

Damage detail	Original photo
Location: Rear NS	
Location: Front	
Location: Rear	

 Estimate Summary

Description	Quantity	Time	Cost
Parts - Replace	41	5 days	\$7,676.87
Parts - Repairable (Opinion Time)	2	1 day	
Paint (inc. Blends and Repairs)			\$1,100.00
Specialist Operations	9		\$265.00
Misc.			
Labour (\$280.00/day)		6 days	\$1,680.00
Total			\$10,721.87

Estimate Parts

OE Part Code	Description	Price	Repair / Replace
-	Boot Floor	\$594.41	Replace
-	Boot Floor Side Trim LH	\$185.52	Replace
-	Boot Floor Side Trim RH	\$185.52	Replace
-	Boot Floor Trim	\$128.84	Replace
-	Bumper Rear Cover	\$555.63	Replace
-	Bumper Rear Reinforcement	\$217.40	Replace
-	Bumper Rear Retainer LH	\$29.65	Replace
-	Bumper Rear Retainer RH	\$29.65	Replace
-	Chassis Leg Rear Section LH	\$0.00	Repair
-	Exhaust Silencer Rear	\$700.36	Replace
-	Lamp Assembly Rear LH	\$191.21	Replace
-	NS Rear Quarter Light Glass	\$109.00	Replace
-	Rear Boot/Tailgate Weatherseal	\$125.72	Replace
-	Rear Bumper Sponge	\$91.19	Replace
-	Rear Fender LH	\$553.59	Replace
-	Rear Fender Liner LH	\$140.76	Replace
-	Rear Lamp Panel LH	\$109.45	Replace
-	Rear Panel	\$286.39	Replace
-	Rear Panel Top Garnish Trim	\$31.79	Replace
-	Shock Absorber Rear LH	\$130.73	Replace
-	Steering Geometry	\$0.00	Replace
-	Stub Axle Rear LH	\$232.88	Replace
-	Suspension Arm Rear Trailing Arm LH	\$115.90	Replace
-	Tailgate or Boot Lid	\$904.16	Replace
-	Tailgate or Boot Lid Aperture Trim	\$41.31	Replace
-	Tailgate or Boot Lid Centre Trim	\$48.01	Replace
-	Tailgate or Boot Lid Emblem	\$46.79	Replace
-	Tailgate or Boot Lid Hinge Cover Trim LH	\$17.91	Replace
-	Tailgate or Boot Lid Hinge Cover Trim RH	\$17.91	Replace
-	Tailgate or Boot Lid Hinge LH	\$109.62	Replace
-	Tailgate or Boot Lid Hinge RH	\$109.62	Replace
-	Tailgate or Boot Lid Lamp Cluster LH	\$169.82	Replace
-	Tailgate or Boot Lid Lamp Cluster RH	\$169.82	Replace
-	Tailgate or Boot Lid Lift Handle	\$154.63	Replace
-	Tailgate or Boot Lid Lock	\$139.64	Replace

-	Tailgate or Boot Lid Outer Release Handle	\$147.92	Replace
-	Tailgate or Boot Lid Pull Handle	\$39.43	Replace
-	Tailgate or Boot Lid Trim Board	\$145.13	Replace
-	Tow Eye Cover	\$21.15	Replace
-	Wheel Arch Inner Rear LH	\$375.08	Repair
-	Wheel Bearing Rear LH	\$216.90	Replace
-	Wheel Hub Rear LH	\$177.86	Replace
-	Wheel Road Rear LH	\$253.65	Replace

 Specialised Operations

Operation	Time	Price
Anti Corrosion for Door	-	\$20.00
Anti Corrosion for Quarter Panel	-	\$20.00
Anti Corrosion for Rear Bumper	-	\$20.00
Boot Floor Sealer for Rear Bumper	-	\$40.00
Door Card Clips for Door	-	\$15.00
Liner Clips for Quarter Panel	-	\$15.00
Rear Bumper Clips for Rear Bumper	-	\$20.00
Rear Panel Sealer for Rear Bumper	-	\$40.00
Steering Geometry Check for Quarter Panel	-	\$75.00





