



Century Motors

Inchcape

Co. Reg No. : 192800002R
GST Reg No. : MR85000009
6 MARSILING LANE
SINGAPORE 739145, Tel No.: 3157 2626



TAX INVOICE

Account Details			Account No.		Customer Details			
DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD 20 ANSON ROAD, 08 - 01 TWENTY ANSON SINGAPORE 079912			B2000503 / DIRECTAS		Mr Lim Tien Fang			
			Document No. 63001385		APT BLK 683A WOODLANDS DRIVE 62 #10-103			
			Document Date 12/07/2023		739683 Mobile: 96718189			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
0	OTHERS	ANY		SJP2435M	1	10626	SJP2435M/OD	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JMYSTCY4A9U000561		60	Lim Mei Hong	--/--/----	0.00		--/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	V	EXC Excess element of insurance repair to be paidby the insured party			8888	740.74		-740.74
2	M	BP-REC LUMP SUM REPAIR COST: TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR REPAIRS, PANEL BEATING WELDING, AND SPRAY PAINTING			*	5850.00		5850.00
For & on behalf of Century Motors (S) Pte Ltd			Customer's Signature		Charge Summary		Total 5,109.26	
					Parts 0.00		GST 8.00% 408.74	
					Labour 5,850.00			
					Sublet 0.00			
					Lubrication/Fluid 0.00		Less 0.00	
					Others 0.00		Amount Due 5,518.00	

Customer Copy



Century Motors

Inchcape

Co. Reg No. : 192800002R
GST Reg No. : MR85000009
6 MARSILING LANE
SINGAPORE 739145, Tel No.: 3157 2626



TAX INVOICE

Account Details			Account No.		Customer Details			
DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD 20 ANSON ROAD, 08 - 01 TWENTY ANSON SINGAPORE 079912			B2000503 / DIRECTAS		Mr Lim Tien Fang			
			Document No. 63001385		APT BLK 683A WOODLANDS DRIVE 62 #10-103			
			Document Date 12/07/2023		739683 Mobile: 96718189			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
0	OTHERS	ANY		SJP2435M	1	10626	SJP2435M/OD	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JMYSTCY4A9U000561		60	Lim Mei Hong	--/--/----	0.00		--/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	V	EXC Excess element of insurance repair to be paidby the insured party			8888	740.74		-740.74
2	M	BP-REC LUMP SUM REPAIR COST: TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR REPAIRS, PANEL BEATING WELDING, AND SPRAY PAINTING			*	5850.00		5850.00
For & on behalf of Century Motors (S) Pte Ltd			Customer's Signature		Charge Summary		Total 5,109.26	
					Parts 0.00		GST 8.00% 408.74	
					Labour 5,850.00			
					Sublet 0.00			
					Lubrication/Fluid 0.00		Less 0.00	
					Others 0.00		Amount Due 5,518.00	

Company Copy