

Our Ref: **SJP2435M**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	TAILGATE ✓ <i>DETACHED</i>		\$ 575.00 ✓
2	1	TAILGATE WEATHERSTRIP ✓ <i>cut</i>		\$ 185.00 ✓
3	1	TAILGATE HINGE LH ✓ <i>BRK</i>		\$ 95.00 ✓
4	1	TAILGATE HINGE RH ✓ <i>BRK</i>		\$ 95.00 ✓
5	1	TAILGATE ABSORBER LH ✓ <i>CRACK</i>		\$ 105.00 ✓
6	1	TAILGATE ABSORBER RH ✓ <i>BRK</i>		\$ 105.00 ✓
7	1	TAILGATE LOCK ✓ <i>BRK</i>		\$ 185.00 ✓
8	1	TAILGATE EMBLEM(LANCER EX) <i>X REPAIR</i>		\$ 90.00 <i>X</i>
9	1	TAILGATE THIRD BRAKE LAMP ?		\$ 155.00 <i>X nn</i>
10	1	TAILGATE LAMP LH ✓ <i>CRACK</i>		\$ 320.00 ✓
11	1	TAIL LAMP LH ✓ <i>CRACK</i>		\$ 385.00 ✓
12	1	REAR BUMPER ✓ <i>CRACK</i>		\$ 480.00 ✓
13	1	REAR BUMPER REINFORCEMENT ✓ <i>CRACK</i> — DM		\$ 195.00 ✓
14	1	REAR BUMPER SIDE RETAINER LH ✓ <i>SPLIT</i>		\$ 35.00 ✓
15	1	REAR BUMPER REFLECTOR LH ✓ <i>CRACK</i>		\$ 45.00 ✓
16	1	REAR WINDSCREEN ✓ <i>SHATTERED</i>		\$ 490.00 ✓
17	1	REAR WINDSCREEN MOULDING ✓ <i>WFL</i>		\$ 130.00 ✓
18	1	REAR FENDER LH ✓ <i>DETACHED</i>		\$ 385.00 ✓
19	1	REAR FENDER INNER SHIELD LH ✓ <i>DETACHED</i>		\$ 125.00 ✓
20	1	END PANEL <i>X REPAIR</i> ?		\$ 235.00 <i>X R</i>
21	1	CORNER PANEL LH ✓ <i>DETACHED</i>		\$ 185.00 ✓
22	1	END PANEL INNER TRIM ✓ <i>DETACHED</i>		\$ 165.00 ✓
23	1	REAR CHASSIS BAR LH		REPAIR
			SUB TOTAL	\$ 4,765.00
			MARGIN 10%	\$ 476.50
			TOTAL AMOUNT	\$ 5,241.50

Our Ref: SJP2435M

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR BUMPER CLIPS		\$ 20.00
2	1	REAR BUMPER PARKING SENSORS		\$ 250.00
3	1	WINDSCREEN SEALANT		\$ 50.00
			SUB TOTAL	\$ 320.00
			TOTAL PARTS COST	\$ 5,561.50

Our Ref: SJP2435M

S/NO	DESCRIPTION	EST. BY WORKSHOP
	LABOUR & PAINTWORK	
1	LABOUR CHARGE TO REMOVE, REFIT AND REPAIR AFFECTED ACCIDENT PARTS	\$ 1200 1,580.00
2	PAINT MATERIALS PER PANEL	\$ 1,000.00
3	LABOUR TO REMOVE & REFIT REAR WINDSCREEN	\$ 100.00
4	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ 50.00
5	ANTI-RUST COATING TO NEW METAL PANELS FITTED	\$ 50.00
	TOTAL BEFORE GST	\$ 8,441.50
	LESS EXCESS	\$ 800.00
	TOTAL BEFORE GST	\$ 7,641.50
	8% GST	\$ 611.32
	TOTAL REPAIR COST	\$ 8,252.82

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

****This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.**

*****On a separate note, please let us have your authorize repair confirmation and/or approval for the above OD case in your next reply.**

Yours Faithfully,
Ck Loh
 Claims Estimator

Authorise
 R/S AFTER REPAIR
 6 days
 Express #8001-
 Hsuan REPAIR
 AARON WANG 19/5/23
 1:55pm