

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

AIG
11/07/24
(Thursday)
LKF

Not withen
1/1pm & 1600h
Resurvey After Pain
2 days

20/06/2024

Owner: VAMOS CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA HR-V - SML3614S

2pcs	front headlamp @\$1784.50	N/S	CLB	\$ 3,569.00	X
2pcs	front headlamp top bracket @\$35.00			\$ 70.00	X
2pcs	front headlamp lower bracket @\$45.00		N/S CM	\$ 90.00	X
1pc	front centre grille base		CM	\$ 495.00	X
1pc	front centre grille bracket		N	\$ 75.00	X
1pc	front centre grille outer garnish		SN	\$ 380.00	X
1pc	front centre grille "HONDA" logo		MC	\$ 37.40	X
1pc	front bumper 566		My car	\$ 951.70	X
10pcs	front bumper clip @\$5.00		SM	\$ 50.00	X
2pcs	front bumper side retainer @\$25.60		DI	\$ 51.20	X
1pc	front bumper lower lid 352.60		BU	\$ 450.30	X
1pc	front bumper lower grille		SN	\$ 280.50	X
1pc	front bumper reinforcement 321.40		BY	\$ 368.80	X
				\$ 6,868.90	
less 20%				\$ 1,373.78	
				\$ 5,495.12	
1set	front number plate & casing		SN	s.nett \$ 50.00	X
	spray painting			\$ 800.00	220
	labour charges			\$ 800.00	250
	Total			\$ 7,145.12	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: