

辉 陽 汽 車 有 限 公 司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

ALG
11/07/24
(Thursday)
LKK

Not Withheld

1/1/24

Running After Pain

20/06/2024

Owner: VAMOS CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA HR-V - SML3614S

2pcs	front headlamp @\$1784.50	1/1/24 X	6/1/24	\$ 3,569.00
2pcs	front headlamp top bracket @\$35.00			\$ 70.00 X
2pcs	front headlamp lower bracket @\$45.00			\$ 90.00 7
1pc	front centre grille base			\$ 495.00 7
1pc	front centre grille bracket			\$ 75.00 7
1pc	front centre grille outer garnish			\$ 380.00 7
1pc	front centre grille "HONDA" logo			\$ 37.40 7
1pc	front bumper			\$ 951.70 7
10pcs	front bumper clip @\$5.00			\$ 50.00 ✓
2pcs	front bumper side retainer @\$25.60			\$ 51.20 ✓
1pc	front bumper lower lid			\$ 450.30 ✓
1pc	front bumper lower grille			\$ 280.50 7
1pc	front bumper reinforcement			\$ 368.80 7
				\$ 6,868.90
less 20%				\$ 1,373.78
				\$ 5,495.12
1set	front number plate & casing		in s.nett	\$ 50.00 X
spray painting				\$ 800.00 2201
labour charges				\$ 800.00 7
Total				
				\$ 7,145.12



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: