

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #09-16  
AIG BUILDING

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: TAM, IVAN-WK

Date: 19/07/2024

### **PRELIMINARY ADVICE**

Vehicle No	SML 3614S	Accident Date	14/06/2024
Make	HONDA HRV 1496cc	Policy No.	-
Assignment Date	11/07/2024	Excess	-
Inspection Date	11/07/2024	Est. Duration of Repair	2

Inspected At: HUI YANG MOTOR PTE LTD  
BLK 176 SIN MING DRIVE

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Workshop Estimate Amount:	7,145.12
Revised Estimate Amount:	2,004.88
"Check" Items Amount	\$0.00
Total	2,004.88
Lump Sum Repairs	<b>\$1,600.00</b>

#### **Total Loss Consideration**

Book Value	\$0.00
Market Value	\$0.00
COE / PARF Rebate	\$0.00
Salvage Value	\$0.00
Margin for Repair	\$0.00

### **Remarks**

- [ ] The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- [ ] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- [ ] Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.