

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24060052/UQH3E2**Date:** 11/07/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MCV24A00007700
Claimant Vehicle No :	SLA3806A	Insured Vehicle No :	YN6032Z
Date of Loss:	09/06/2024	Nature of Claim:	TP
		Claim No:	DMCV2400121H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA3806A		
Make & Model:	NISSAN NOTE, 1.2 CVT ABS D/AIRBAG 2WD 5DR DIG-S (A)	Engine No:	HR12167201B
Reg. Date:	27/02/2016 (Man. Year: 2016)	Chassis No:	JN1TAAE12Z0972180
Colour:	Green	Odometer:	100968 km
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,936.72	1,712.40	224.32	11.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,925.00	850.00	1,075.00	55.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,861.72	2,562.40	1,299.32	33.65
+ GST 9.00/9.00% (\$\$)	347.55	230.62	116.93	33.64
Nett Amount (\$\$)	4,209.27	2,793.02	1,416.25	33.65

INSPECTION

Date of Assignment:	12/06/2024		
Date Inspected:	12/06/2024	Inspected At:	Tan Chong Motor (HQ) 19 Ubi Road 4 Singapore 408623
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2024)
Parts:	144	NISSAN NOTE 1.2 CVT ABS D/AIRBAG 2WD 5DR DIG-S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA3806A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH SIDE MIRROR	Cracked	412.50 FN	*412.50 FN
2	1		*FRT RH OUTSIDE CHROME HANDLE	Cut	109.50 FN	*109.50 FN
3	1		*GLASS RUN RUBBER FRT RH DOOR	Damaged	177.90 FN	*177.90 FN
4	1		*FRT RH DOOR FRT SASH TAPE	Necessary	23.90 FN	*23.90 FN
5	1		*FRT RH DOOR WINDOW OUTER MLDG	Bent	100.40 FN	*100.40 FN
6	1		*FRT RH DOOR RR SASH TAPE	Necessary	23.90 FN	*23.90 FN
7	1		*FRONT RH DOOR	Badly Dented	1,125.30 FN	*1,125.30 FN
8	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
9	1		*RH SIDE MIRROR COVER	Cracked	308.00 F	*167.10 FL
F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.						
Sub Total (S\$)					2,331.40	2,140.50
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	33.42
- Nett Item Discount on N Items 20.00/20.00% (S\$)					394.68	394.68
Total Parts (S\$)					1,936.72	1,712.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR CHARGES TO RENEW RH FRT DOOR AND RIGH SIDE MIRROR	New	450.00	200.00
2	CHARGES TO SPRAY PAINTING FRT RH FENDER, FRT RH DOOR, RH SIDE MIRROR RH RR DOOR	New	1,225.00	400.00
3	APPLY SEALANT TO FRT RH DOOR	New	100.00	100.00
4	REMOVE AND TRANSFER FRT RH DOOR MECHANISM	New	150.00	150.00
Gross Labour Cost (\$)			1,925.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >