

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
29 UBI ROAD 4
SINGAPORE 408523
TEL: 6490 9556 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0210/24
DATE : 10-JUN-2024

ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
S(038987)
TEL : 63374779
FAX : 63389267
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MR CHIA KIAN BOON EDWIN (XIE JIANWEN EDWIN)
ADDRESS : 215 ONAN ROAD #04-06

TELEPHONE NO : 93650260
S(424597)

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : P10863311R01
VEHICLE NO : SLA3806A
MODEL CODE : TDWARDZE12EDAY407Z
MODEL/YEAR : NISSAN NOTE 1.2 BASE
ENGINE NO : HR12167201B
CHASSIS NO : JN1TAAE12Z0972180
MILEAGE : 100968 KM
DATE IN : 10/06/2024
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 09/06/2024

not of Autolion
in
in
80086608
11/6/24
Zhang, Mr. Bedu, 707
3 days
11/6 & 25/62-40

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts for resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

-9645 0084 elmer@fanchang.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLA3806A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO RENEW RH FRT DOOR AND RIGH SIDE MIRROR	450.00	200
2	ZZ/002	CHARGES TO SPRAY PAINTING FRT RH FENDER , FRT RH DOOR, RH SIDE MIRROR RH RR DOOR ,	1225.00	400
3	ZZ/003	APPLY SEALANT TO FRT RH DOOR	100.00	✓
4	ZZ/004	REMOVE AND TRANSFER FRT RH DOOR MECHANISM	150.00	✓
TOTAL LABOUR CHARGES			1925.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLA3806A

DAMAGED PARTS & PRICES				
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
1 SUNDRIES	NPN		11	50.00 ☒
2 RH SIDE MIRROR COVER	NPN1	167.10	CM	308.00 ☒
3 RH SIDE MIRROR	96301-5VA0B	412.50	CM	☒
4 FRT RH OUTSIDE CHROME HANDLE	80640-3AW0A	109.50	CM	☒
5 GLASS RUN RUBBER FRT RH DOOR	80330-5WH0A	177.90	Daye	☒
6 FRT RH DOOR FRT SASH TAPE	80816-3VA0B	23.90	ner	☒
7 FRT RH DOOR WINDOW OUTER MLDG	80820-3WC1A	100.40	3rd	☒
8 FRT RH DOOR RR SASH TAPE	80818-3VA0A	23.90	ner	☒
9 FRONT RH DOOR	H010M-3VAMA	1125.30	Butyng	☒
SUB TOTAL		1973.40	0.00	358.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		394.68	0.00	0.00
GRAND TOTAL		1578.72	0.00	358.00
OVERALL TOTAL		1936.72		

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLA3806A

TOTAL LABOUR CHARGES	1925.00
TOTAL SPARE PARTS CHARGES	1936.72

GRAND TOTAL	3861.72 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.